



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
HSBC LIFE (SINGAPORE) PTE LTD 10 MARINA BOULEVARD #48-01 MARINA BAY FINANCIAL CENTRE TOWER 2SINGAPORE 018983 ATTN:VALE OH		Ref: CC4/ASM22006472/Apa3q2 Date: 05/07/2023 Code: HSB	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHD 3275M	Veh. Inspected	GBL 1468R
Policy No.	P2465679	Coverage (\$)	0.00
Claim No.	S2M045X5	Excess (\$)	0.00
Assign From		Assign Date	06/07/2022
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA HIACE	c.c	2754
Engine No.	HIDDEN	Year of Reg.	2021
Chassis No.	GDH2012016873	Colour	SILVER
Odometer	35359 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195 R15C	ROYAL	6 mm
L/H Front Tyre	195 R15C	ROYAL	6 mm
R/H Rear Tyre	195 R15C	ROYAL	6 mm
L/H Rear Tyre	195 R15C	ROYAL	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	05/07/2022	Inspection Date	06/07/2022
Survey held at	N-51 AUTOMOTIVE PL 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	