

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT					
	LONPAC INSURAN	ICE BHD		Ref:	CS3/LPC22006473/Gce2
	300 BEACH ROAD SINGAPORE 1995	#17-04/07 THE CONCOURSE 55		Date:	25/07/2022
				Code:	LPC2
1.	Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	YN 8858U	Veh. Inspected	l	GBD 9974K
	Policy No.		Coverage (\$)		0.00
	Claim No.	21/22/22/VC05/025993	Excess (\$)		0.00
	Assign From	GERALD POH	Assign Date		06/07/2022
2.	. Vehicle Particulars & Condition				
	Make & Model	MITSUBISHI CANTER	c.c		2998
	Engine No.	HIDDEN	Year of Reg.		2015
	Chassis No.	FEA01BA10058	Colour		WHITE
	Odometer	163727 KM	Steering		IN ORDER
	Brakes	IN ORDER	Modification		NIL
	General	GOOD			
3.	Conditions of Tyres				
		Size	Make		Balance
	R/H Front Tyre	195 R15	FALKEN		6 mm
	L/H Front Tyre	195 R15	FALKEN		6 mm
	R/H Rear Tyre	195 R15 (D)	FALKEN		6/6 mm
	L/H Rear Tyre	195 R15 (D)	FALKEN		6/6 mm
4.	Description of Damages				
	THE VEHICLE SUS PORTION.	STAINED DAMAGES AT THE FRONT AND REAR			
5.	General Information				
	Accident Date	05/07/2022	Inspect Date /	Time	07/07/2022 (03:30 PM)
	Survey held at	H C AUTO PTE LTD			
		160 SIN MING DRIVE #05-09 SIN MING AUTOCITY SINGAPORE 575722			
5a.	Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				

Report Ref No. CS3/LPC22006473/Gce2

Inspected By

XING GUO QIANG

K.K.LAU CPT(RET)

M.MATAI, AMSAE-A

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser

Automotive Assessor