



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLC 5951P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR TAILGATE	DENTED	2,300.00	1,245.00
1	REAR TAILGATE WINDSCREEN MOULDING	NECESSARY	120.00	120.00
1	REAR TAILGATE TOYOTA EMBLEM	NECESSARY	80.00	60.00
1	REAR BUMPER CENTER PAD	TO REPAIR SEE LABOUR	150.00	-
1	REAR BUMPER	TO REPAIR SEE LABOUR	1,900.00	-
	LESS 25% DISCOUNT		-1,137.50	-356.25
			3,412.50	1,068.75
	<u>SPECIAL NETT ITEMS</u>			
1	REVERSE SENSOR (SN)	SHORTED	240.00	200.00
1	SEALANT (SN)	NECESSARY	60.00	40.00
			300.00	240.00
	<u>LABOUR</u>			
	TO LABOUR CHARGE FOR REMOVING REAR TAILGATE, REAR END PANEL AND REAR BUMPER OUT TO FACILITATE REPLACEMENT OF DAMAGED PART. INCLUSIVE OF THE REPAIR OF REAR BUMPER CENTER PAD & REAR BUMPER.		750.00	400.00
	TO RESPRAY REAR BUMPER AND REAR TAILGATE.		600.00	400.00
	TRANSFER TAILGATE MECHANISM.		150.00	50.00
	REMOVE AND INSTALL REAR TAILGATE WINDSCREEN GLASS.		150.00	120.00
			1,650.00	970.00
	GRAND TOTAL		5,362.50	2,278.75
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,800.00

Report Ref No. CS/SMR22006475/Eqcm4

CHEN TSUE YEE

Automotive Assessor

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.