

ASS. REC. BY:

REF:

EQ/ 22006477/KC

C

Kenneth

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \$123k

IDAC Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No

Est. Repairs: 11.13 days Res.: Yes or No

Lum Sum: 15 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SCR 230 Yr Regn: 12, 17

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or (A)

Make: Lexus 1S200T.C 1998

Colour: M. Black A/C: Insured / Std / NI / NA

Sp. Reading: 21506 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: JT1HBA102005060983

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: \_\_\_\_\_

R: 225/45R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front: \_\_\_\_\_ Rear: \_\_\_\_\_

R/Bal: 7 mm R/Bal: 7 mm

L/Bal: 7 mm L/Bal: 7 mm

D.O.A. 2/7/22 D.O.I. 6/7/2022

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Rm &amp; U/C

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

1/ 17A note @ 64,205.00

~~17/10 11.13pm @ 33,000 Cash~~

19/13.40pm Confirmed LS \$32K and 13 days with Ah Heng. (Red. 14,242.48, 31.2)

Date/Time, File Pass to?

☐

: Prel. Report

1)

☒

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 13

Resurvey No. of Trip: \_\_\_\_\_

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Survey Fee:

Transportation:

S + RS. SI

Fees

Others

TOTAL

Report Format:

TP

Lump Sum / I.B.I.: (\$ 33,000)

# SINGAPORE ACCIDENT STATEMENT

## IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

## ACCIDENT STATEMENT

|                                 |                                    |
|---------------------------------|------------------------------------|
| Date of Submission              | 04/07/2022 12:16 (SGT)             |
| Reported by                     | Driver                             |
| Date of Accident                | 02/07/2022 09:40 (SGT)             |
| Exact Location of Accident      | 165a Moulmein Rd, Singapore 308091 |
| Additional Location Information | -                                  |
| Country/State of Loss           | Singapore                          |

## DETAILS OF OWN VEHICLE

|                             |                         |
|-----------------------------|-------------------------|
| Vehicle Registration Number | SCR23D                  |
| INSURED/POLICYHOLDER        |                         |
| Is company?                 | No                      |
| Name of Registered Owner    | ONG CHENG KEE           |
| NRIC No                     | SXXXX340Z               |
| Email Address               | ong_jie_hui@hotmail.com |
| Mobile Phone No             | (Phone) +65-96342260    |
| Alternative Phone No        | -                       |

## VEHICLE PARTICULARS

|  |                           |
|--|---------------------------|
| Manufacturer   | Lexus                     |
| Model  | IS200T EXECUTIVE          |
| Variant  | -                         |
| Exact purpose for which vehicle was being used at time of accident           | -                         |
| Are you claiming under your own insurance policy for repair to your vehicle? | No - Claiming third party |
| Vehicle Category   | Private car               |
| Transmission   | Auto                      |
| CC   | 1998                      |

## INSURANCE COMPANY

|                                   |                          |
|-----------------------------------|--------------------------|
| Name of Insurance Company         | ERGO Insurance Pte. Ltd. |
| Policy Number / Cover Note Number | DMPG21013741             |

## DRIVER

|                |             |
|----------------|-------------|
| Name of Driver | ONG JIE HUI |
| NRIC No        | SXXXX517D   |
| Date Of Birth  | 29/07/1996  |
| Occupation     | Indoor      |

Date Of Driving Pass  
 Driving experience  
 Gender  
 Mobile Number  
 Alt. Phone Number  
 Email Address  
 Address  
 Address complement  
 Postcode  
 Is the driver the policyholder?  
 If No, Relationship of the Driver with the Insured  
 Does Driver Own Other Vehicles?  
 Vehicle Registration Number of Other Vehicle Owned by Driver  
 Insurance Company of Other Vehicle Owned by Driver

26/10/2016  
 5 YEARS AND 9 MONTHS  
 Female  
 (Phone) +65-98632453  
 -  
 ong\_jie\_hui@hotmail.com  
 23 JUBILEE ROAD  
 -  
 128562  
 No  
 Child  
 No  
 -  
 -

#### GENERAL INFORMATION OF THE ACCIDENT

Type of Accident  
 Weather Conditions  
 Road Surface

Collision - Major/Minor Rd  
 Clear  
 Dry

#### OTHER INFORMATION

Was any foreign vehicle involved in the accident? No  
 Number of vehicles involved in the accident 2  
 Was anybody injured in the Accident? No  
 Was any injured conveyed to hospital by ambulance? -  
 Was any other vehicle or property damaged? Yes  
 Number of Passengers (Including Driver) 1  
 Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No  
 Translator's name -  
 Translator's ID -  
 Translator's phone number -  
 Translator's email -  
 Original language used in the statement -

#### DETAILS OF POLICE ACTION

Was the accident reported to the police? No  
 Was notice of intended Prosecution given? No  
 If yes, against whom? -

#### CIRCUMSTANCES OF ACCIDENT

REFER TO SKETCH PLAN.

NOTE: VEHICLE REPAIR AT OWNER W/SHOP - GUAN MOTOR WORKS

#### ATTACHMENT(S)

Are accident photos available for attachment? Yes  
 Was there any video captured by Car Camera? No

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SME6918H  
 Vehicle Manufacturer Mazda  
 Vehicle Model 3  
 Vehicle Variant -  
 Vehicle Colour -  
 Vehicle Category Private car



Name of Driver

Contact Number

Address

Address complement

Postcode

Insurance Company Name

Nature Of Damage

Details of property damaged in accident

No. Of Passenger (Including Driver)

RUBY

GXXXX925T

(Phone) +65-86926609

## WITNESS DETAILS

### WITNESS 1

Name

Phone

Email

ALFIN

(Phone) +65-97595706




SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA):  
I understand, acknowledge, agree and consent that:  
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:  
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;  
(ii) investigating the accident and/or my claims;  
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;  
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or  
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.  
(collectively the "Purposes")  
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' law yers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and  
(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time: 20/04/2022  
 Driver's Signature (If driver is not the policyholder) / Date & Time: 04/04/2022  
 Witnessed by Reporting Centre Personnel: 10:17 AM  
FLORENCE

Sketch Plan



A = SCR 230  
 B = SM 16918 H

仰光拖車服務  
RANGOON RECOVERY SERVICES

Blk128 Ang Mo Kio Ave 3 #11-1847 Singapore 560128

H/P: 9116 0716

Registration No. 53413647L

CASH SALE No. 3438  
JOB ORDER

Messrs

CASH

Date: 2/7/22

车牌 Vehicle No.

50R230

车型 Model

Leifag

地点 Destination

169 Monlye in Rd 6 wfs

司机 Driver

723224

银 额

Amount \$

1200

☐ Change Tyre/Jumpstart

☐ Basement/Multi Carpark

☒ Accident

☒ King Dolly

经手人 Signature

Vehicle is transported at owner's risk. The company accepts no responsibility for damaged or other misdemeanour to your vehicle whilst being transported



SCR23D

Factory Japan 2022.0.1 : Lexus : IS : E30 Series : ASE30  
4-Wheel Total Alignment

Front : Left

| Actual | Before | Specified Range |
|--------|--------|-----------------|
| -1°00' | -1°00' | -1°00' 0°30'    |
| 4°38'  | 4°38'  | 7°30' 9°00'     |
| -0°14' | -0°14' | -0°05' 0°05'    |
| 14°05' | 14°05' | 9°40' 11°10'    |
| 13°05' | 13°05' | 8°40' 11°40'    |
|        |        |                 |

Camber  
Caster  
Toe  
SAI  
Included Angle  
Turning Angle Diff.

Front : Right

| Actual | Before | Specified Range |
|--------|--------|-----------------|
| -3°06' | -3°05' | -1°00' 0°30'    |
| 4°40'  | 4°40'  | 7°30' 9°00'     |
| -0°18' | -0°18' | -0°05' 0°05'    |
| 16°10' | 16°10' | 9°40' 11°10'    |
| 13°04' | 13°04' | 8°40' 11°40'    |
|        |        |                 |

Front

Cross Camber  
Cross Caster  
Cross SAI  
Total Toe  
Cross Turn Diff.

| Actual | Before | Specified Range |
|--------|--------|-----------------|
| 2°05'  | 2°05'  | -0°45' 0°45'    |
| -0°02' | -0°02' | -0°45' 0°45'    |
| -2°05' | -2°05' |                 |
| -0°32' | -0°32' | -0°11' 0°11'    |
|        |        |                 |

Rear : Left

| Actual | Before | Specified Range |
|--------|--------|-----------------|
| -0°53' | -0°53' | -2°20' -0°50'   |
| 0°02'  | 0°02'  | 0°00' 0°11'     |

Camber  
Toe

Rear : Right

| Actual | Before | Specified Range |
|--------|--------|-----------------|
| -0°44' | -0°44' | -2°20' -0°50'   |
| 0°01'  | 0°01'  | 0°00' 0°11'     |

Rear

Cross Camber  
Total Toe  
Thrust Angle  
Axle Offset

| Actual | Before | Specified Range |
|--------|--------|-----------------|
| -0°09' | -0°09' |                 |
| 0°03'  | 0°03'  | 0°00' 0°22'     |
| 0°00'  | 0°00'  |                 |
| 0mm    | 0mm    |                 |

源摩哆廠

# GUAN MOTOR WORKS

Business Regn. No: 081026001

176 Sin Ming Drive #02-03 Sin Ming Autocare Singapore 575721 Tel: 6453 6111 Fax: 6453 8292 H/P: 9742 6003

Not Notarized  
C/L Rp \$33,000/p  
11 days

## REPAIR ESTIMATE SCR23D

| No. | Qty   | List Items                                     |          |                 |   |
|-----|-------|--|----------|-----------------|---|
| 1   | 1     | Front bumper                                   | \$       | R1 1,032.90     | ✓ |
| 2   | 1     | Front bumper RH fog lamp cover                 | \$       | mir 170.70      | ✓ |
| 3   | 2     | Front bumper RH parking sensor                 | \$       | mir 981.60      | ✓ |
| 4   | 1     | Front bumper lower chrome spoiler              | \$       | 238.40          | ? |
| 5   | 1     | Front bumper RH side retainer                  | \$       | CM 133.20       | ✓ |
| 6   | 1     | Front bumper inner foam                        | \$       | Rp 105.20       | ✓ |
| 7   | 1     | Front bumper inner reinforcement               | \$       | R 690.20        | ✓ |
| 8   | 1     | Front bumper inner reinforcement outer garnish | \$       | R1 280.30       | ✓ |
| 9   | 1     | RH headlamp                                    | \$       | Rp 3,683.80     | ✓ |
| 10  | 1     | RH headlamp washer nozzle                      | \$       | mir 152.30      | ✓ |
| 11  | 1     | Front grille                                   | \$       | CM 846.10       | ✓ |
| 12  | 1     | Front grille outer surround chrome moulding    | \$       | CM 332.00       | ✓ |
| 13  | 1     | Front number plate garnish                     | \$       | Pu 170.70       | X |
| 14  | 1     | Front bonnet                                   | \$       | R1 2,784.80     | ✓ |
| 15  | 2     | Front bonnet lifter pop up hood                | \$       | Active 7,590.60 | ✓ |
| 16  | 2     | Front bonnet absorber                          | \$       | Pu 758.60       | X |
| 17  | 2     | Front bonnet hinge                             | \$       | 200.60          | ? |
| 18  | 1     | Front bonnet insulator                         | \$       | Pu 458.80       | X |
| 19  | 1 set | Front bonnet insulator clips                   | \$       | na 80.00        | X |
| 20  | 1     | Front bonnet lock                              | \$       | R 178.60        | X |
| 21  | 1     | Front support panel                            | \$       | 1,788.90        | ? |
| 22  | 1     | Front support panel top cover                  | \$       | 339.80          | ? |
| 23  | 1 set | Front support panel top cover clips            | \$       | na 50.00        | ✓ |
| 24  | 1     | Air con condenser                              | \$       | 2,346.10        | ? |
| 25  | 1     | Air con condenser inlet pipe                   | \$       | 657.80          | ? |
| 26  | 1     | Air con condenser outlet pipe                  | \$       | R 779.30        | X |
| 27  | 1     | Radiator                                       | \$       | R 3,242.80      | X |
| 28  | 1     | Air cleaner housing                            | \$       | 1,521.80        | ? |
| 29  | 1     | Front RH fender                                | \$       | R1 1,420.80     | ✓ |
| 30  | 1     | Front RH fender under shield                   | \$       | CM 351.50       | ✓ |
| 31  | 1 set | Front fender under shield clips                | \$       | na 50.00        | ✓ |
| 32  | 1     | Front RH sport rim                             | \$       | na 2,980.10     | ✓ |
| 33  | 1     | Front RH shock absorber                        | \$       | 960.10          | ? |
| 34  | 1     | Front RH lower arm                             | \$       | 1,095.60        | ? |
| 35  | 1     | Front RH knuckle arm                           | \$       | 935.30          | ? |
| 36  | 1     | Front RH wheel hub & bearing                   | \$       | 1,195.70        | ? |
|     |       |  | \$       | 40,585.00       |   |
|     |       |  | Less 10% | \$ 4,058.50     |   |
|     |       |  | Total :  | \$ 36,526.50    |   |

## Special Nett Items

|    |    |                    |         |           |          |
|----|----|--------------------|---------|-----------|----------|
| 37 | 1  | Front number plate | \$      | Pu 50.00  | X        |
| 38 | 1L | Radiator coolant   | \$      | 35.00     | ?        |
| 39 | 1  | Front RH tyre      | \$      | CM 260.00 | 70% sale |
|    |    |                    | Total : | \$ 345.00 |          |



源摩哆廠

GUAN MOTOR WORKS

Business Regn. No. 081026001

176 Sin Ming Drive #02-03 Sin Ming Autocare Singapore 575721 Tel: 6453 6111 Fax: 6453 8292 H/P: 9742 6003

NOT Authorised  
11 Rps 833,000  
13 days

REPAIR ESTIMATE SCR23D

| No. | Qty   | List Items                                     |          |                         |               |
|-----|-------|--|----------|-------------------------|---------------|
| 1   | 1     | Front bumper                                   | \$       | B <sub>1</sub> 1,032.90 | ✓             |
| 2   | 1     | Front bumper RH fog lamp cover                 | \$       | M <sub>1</sub> 170.70   | ✓             |
| 3   | 2     | Front bumper RH parking sensor                 | \$       | M <sub>1</sub> 981.60   | ✓ 490.80      |
| 4   | 1     | Front bumper lower chrome spoiler              | \$       | CM 238.40               | ✓             |
| 5   | 1     | Front bumper RH side retainer                  | \$       | CM 133.20               | ✓             |
| 6   | 1     | Front bumper inner foam                        | \$       | P <sub>1</sub> 105.20   | ✓             |
| 7   | 1     | Front bumper inner reinforcement               | \$       | P <sub>1</sub> 690.20   | ✓             |
| 8   | 1     | Front bumper inner reinforcement outer garnish | \$       | P <sub>1</sub> 280.30   | ✓             |
| 9   | 1     | RH headlamp 3683.80                            | \$       | P <sub>1</sub> 3,683.80 | ✓             |
| 10  | 1     | RH headlamp washer nozzle                      | \$       | M <sub>1</sub> 152.30   | ✓             |
| 11  | 1     | Front grille 781.20                            | \$       | CM 846.10               | ✓             |
| 12  | 1     | Front grille outer surround chrome moulding    | \$       | CM 332.00               | ✓             |
| 13  | 1     | Front number plate garnish                     | \$       | P <sub>1</sub> 170.70   | X             |
| 14  | 1     | Front bonnet 2452.30                           | \$       | P <sub>1</sub> 2,784.80 | ✓             |
| 15  | 2     | Front bonnet lifter pop up hood                | \$       | Activator 7,590.60      | ✓             |
| 16  | 2     | Front bonnet absorber                          | \$       | P <sub>1</sub> 758.60   | X             |
| 17  | 2     | Front bonnet hinge                             | \$       | O <sub>1</sub> 200.60   | ✓             |
| 18  | 1     | Front bonnet insulator                         | \$       | P <sub>1</sub> 458.80   | X             |
| 19  | 1 set | Front bonnet insulator clips                   | \$       | CM 80.00                | X             |
| 20  | 1     | Front bonnet lock                              | \$       | P <sub>1</sub> 178.60   | X             |
| 21  | 1     | Front support panel                            | \$       | P <sub>1</sub> 1,788.90 | ✓             |
| 22  | 1     | Front support panel top cover                  | \$       | CM 339.80               | ✓             |
| 23  | 1 set | Front support panel top cover clips            | \$       | P <sub>1</sub> 50.00    | ✓             |
| 24  | 1     | Air con condenser                              | \$       | P <sub>1</sub> 2,346.10 | ✓             |
| 25  | 1     | Air con condenser inlet pipe                   | \$       | P <sub>1</sub> 657.80   | X             |
| 26  | 1     | Air con condenser outlet pipe                  | \$       | P <sub>1</sub> 779.30   | X             |
| 27  | 1     | Radiator                                       | \$       | P <sub>1</sub> 3,242.80 | X             |
| 28  | 1     | Air cleaner housing                            | \$       | CM 1,521.80             | ✓             |
| 29  | 1     | Front RH fender                                | \$       | P <sub>1</sub> 1,420.80 | ✓             |
| 30  | 1     | Front RH fender under shield                   | \$       | CM 351.50               | ✓             |
| 31  | 1 set | Front fender under shield clips                | \$       | P <sub>1</sub> 50.00    | ✓             |
| 32  | 1     | Front RH sport rim                             | \$       | P <sub>1</sub> 2,980.10 | ✓             |
| 33  | 1     | Front RH shock absorber                        | \$       | P <sub>1</sub> 960.10   | ✓             |
| 34  | 1     | Front RH lower arm                             | \$       | P <sub>1</sub> 1,095.60 | ✓             |
| 35  | 1     | Front RH knuckle arm                           | \$       | P <sub>1</sub> 935.30   | ✓             |
| 36  | 1     | Front RH wheel hub & bearing                   | \$       | P <sub>1</sub> 1,195.70 | ✓             |
|     |       |  | \$       | 40,585.00               |               |
|     |       |  | Less 10% | \$ 4,058.50             |               |
|     |       |  | Total :  | \$ 36,526.50            |               |
|     |       | <u>Special Nett Items</u>                      |          |                         |               |
| 37  | 1     | Front number plate                             | \$       | P <sub>1</sub> 50.00    | X             |
| 38  | 1L    | Radiator coolant                               | \$       | P <sub>1</sub> 35.00    | 2.5L          |
| 39  | 1     | Front RH tyre                                  | \$       | CM 260.00               | 708.50 182.50 |
|     |       |  | Total :  | \$ 345.00               |               |

Labour

|         |  |    |          |       |
|---------|--|----|----------|-------|
| 1       | Towing charges.  | \$ | 80.00    | ✓     |
| 2       | Labour Charges for remove/refit, panel beating, cutting welding and replacement of damages.      | \$ | 1,100.00 | 9000  |
| 3       | To putty and spray Spray Paintings charges.  | \$ | 1,200.00 | 10000 |
| ④       | To remove, refit A/c condenser, A/c pipings/hoses and etc..., including vacuum & refill A/c gas. | \$ | 140.00   | 1000  |
| ⑤       | To remove, refix and reset front parking sensors.  | \$ | 80.00    | 600   |
| 6       | To check wirings & lightings.  | \$ | 40.00    | 200   |
| ⑤       | To remove, refit front RH under carriages.   | \$ | 250.00   | 2000  |
| 7       | To conduct computerise wheel alignment test.   | \$ | 80.00    | 600   |
| 8       | To supply and apply anti rust treatment  | \$ | 90.00    | 300   |
| Total : |  | \$ | 3,060.00 |       |

**Total Parts and Labour : \$ 39,931.50**

46,242.48

**LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

# 源摩哆廠 GUAN MOTOR WORKS

Business Regn. No: 08102600E

176 Sin Ming Drive #02-03 Sin Ming Autocare Singapore 575721 Tel: 6453 6111 Fax: 6453 8292 H/P: 9742 6003

7.07.2022

## SUPPLEMENTARY REPAIR ESTIMATE FOR Lexus IS200T EXECUTIVE – SCR 23 D

### List Items

|         |                                 |          |             |   |
|---------|---------------------------------|----------|-------------|---|
| 1 pc.   | RH Headlamp ECU wire            | CM       | \$ 152.30   | ✓ |
| → 1 pc. | RH Headlamp ECU                 | nu       | \$ 1,413.10 | ✓ |
| 1 pc.   | RH Side lamp 14P8-60            | CM       | \$ 1,596.90 | ✓ |
| → 1 pc. | RH Bumper reinforcement bracket | RH       | \$ 321.00   | ✓ |
| 1 pc.   | RH Bumper inner air duct        | CM       | \$ 106.60   | ✓ |
| → 1 pc. | RH Bumper low air duct          | CM       | \$ 480.70   | ✓ |
| 1 pc.   | RH Bumper inner part            | CM       | \$ 170.70   | ✓ |
|         |                                 |          | \$ 4,241.30 |   |
|         |                                 | Less 10% | 424.13      |   |
|         |                                 | Total    | \$ 3,817.17 |   |

# GUAN MOTOR WORKS

Business Regn. No: 08102600E

176 Sin Ming Drive #02-03 Sin Ming Autocare Singapore 575721 Tel: 6453 6111 Fax: 6453 8292 H/P: 9742 6003

19.07.2022

## SUPPLEMENTARY REPAIR ESTIMATE FOR Lexus IS200T EXECUTIVE - SCR 23 D

1 pc. Front bonnet lifter pop up hood ECU  
1 pc. Front Lexus Emblem

|          |                    |   |
|----------|--------------------|---|
| Short    | \$ 2,217.40        | ✓ |
| Mr       | \$ 553.50          | ✓ |
|          | <u>\$ 2,770.90</u> |   |
| Less 10% | 277.09             |   |
| Total    | <u>\$ 2,493.81</u> |   |