



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | | |
|--|--|-----------------|---------------------------|--|
| SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623 | | | Ref: CS/SMO22006478/Aqce2 | |
| | | | Date: 20/03/2023 | |
| | | | Code: SMO | |
| 1. Policy Particulars :- THIRD PARTY CLAIM | | | | |
| Insured Veh. | XD 7409D | Veh. Inspected | PC 8371X | |
| Policy No. | | Coverage (\$) | 0.00 | |
| Claim No. | CMTD2202335/THE | Excess (\$) | 0.00 | |
| Assign From | GRACE TEO | Assign Date | 06/07/2022 | |
| 2. Vehicle Particulars & Condition | | | | |
| Make & Model | TOYOTA HIACE | c.c | 2754 | |
| Engine No. | HIDDEN | Year of Reg. | 2019 | |
| Chassis No. | GDH2232001483 | Colour | WHITE | |
| Odometer | 270395 KM | Steering | IN ORDER | |
| Brakes | IN ORDER | Modification | NIL | |
| General | GOOD | | | |
| 3. Conditions of Tyres | | | | |
| | Size | Make | Balance | |
| R/H Front Tyre | 195 R15C | MICHELIN | 6 mm | |
| L/H Front Tyre | 195 R15C | MICHELIN | 6 mm | |
| R/H Rear Tyre | 195 R15C | MICHELIN | 6 mm | |
| L/H Rear Tyre | 195 R15C | MICHELIN | 6 mm | |
| 4. Description of Damages | | | | |
| THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS. | | | | |
| 5. General Information | | | | |
| Accident Date | 06/07/2022 | Inspection Date | 06/07/2022 | |
| Survey held at | AUTOMOBILE HUB ENTERPRISE 1 KAKI BUKIT AVENUE 6 #02-11 AUTOBAY SINGAPORE 417883 | | | |
| 5a. Remarks | | | | |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | | |
| 5b. Estimate Days of Repair | | | | |
| ESTIMATED NORMAL PERIOD FOR REPAIR: | | | 11 Working Days | |