

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22006483/EVY3Q2**Date:** 14/10/2022REFERENCE

| | | | | | |
|------------------------------|---|-----------------------------|--------------------|-----------|-------------------------|
| Handling Insurer: | China Taiping Insurance (Singapore) Pte. Ltd. | Policy No: | DMCVSNW00097932100 | | |
| Claimant Vehicle No : | SKB9788K | Insured Vehicle No : | YN5020P | | |
| Date of Loss: | 30/06/2022 | Nature of Claim: | TP | Claim No: | SNM22D204677/C02/CHNGPW |

DESCRIPTION & IDENTIFICATION OF VEHICLE

| | | | |
|-----------------------------|-----------------------------------|-------------|-------------------|
| Reg No: | SKB9788K | Engine No: | F242K884B48B20A |
| Make & Model: | BMW X3, 2.0 (A) | Chassis No: | WBA22DP0309K93529 |
| Reg. Date: | 15/06/2022 (Man. Year: 2022) | Odometer: | 1715 km |
| Colour: | Grey | | |
| Engine Capacity: | 1998 cc | | |
| Market Value/New Car Price: | N/A | | |
| Sum Insured (S\$): | Market Value/New Car Price | | |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition: | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification: | No | Pre-accident Condition: |

CONDITION OF TYRES

| | | | |
|-------------------|---------------|------------------|---------------|
| Front Tyre Size: | 225/55 R17 | Rear Tyre Size: | 225/55 R17 |
| Front Left Side: | Michelin 5 mm | Rear Left Side: | Michelin 5 mm |
| Front Right Side: | Michelin 5 mm | Rear Right Side: | Michelin 5 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|-------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts | 2,714.30 | 2,275.70 | 438.60 | 16.16 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 4,331.00 | 2,428.00 | 1,903.00 | 43.94 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Gross Total (S\$) | 7,045.30 | 4,703.70 | 2,341.60 | 33.24 |
| + GST 7.00/7.00% (S\$) | 493.17 | 329.26 | 163.91 | 33.24 |
| Nett Amount (S\$) | 7,538.47 | 5,032.96 | 2,505.51 | 33.24 |

INSPECTION

| | | |
|-----------------------------|--------------------------|---|
| Date of Assignment: | 06/07/2022 | |
| Date Inspected: | 07/09/2022 Inspected At: | Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre Singapore 159941 |
| Estimated Period of Repair: | 3.0 days | |

Adjuster: CHEN TSUE YEE**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

| | |
|----------------------------|--|
| Part Source: MRM-SG | Version: 1.0 (Last Synchronised: 13 Oct 2022) |
| Parts: M1-SUV | BMW X3 2.0 (A) (Catalogue:Merimen Singapore 1.0) |
| Labour: Repairer's | (Price-denominated Standard List) |
| Print Code: | (Unsubmitted, no print-code for SKB9788K) |
| Validity: | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk *. |

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|--------------------------|---------------|-------------|--------------|
| 1 | 1 | | *SUNDRIES | Necessary | 80.00 FS | *80.00 FS |
| 2 | 1 | | *BONNET | Dented | 1,929.95 FS | *1,929.95 FS |
| 3 | 10 | | *EXPANDING RIVET | Not Necessary | 5.00 FS | *- FS |
| 4 | 1 | | *GRILL FRONT | Cut | 265.75 FS | *265.75 FS |
| 5 | 1 | | *AIR FLAPS TOP | Not Necessary | 291.55 FS | *- FS |
| 6 | 1 | | *FRT ENGINE HOOD SEALING | Not Necessary | 34.55 FS | *- FS |
| 7 | 1 | | *AIR DUCT RADIATOR TOP | Not Necessary | 107.50 FS | *- FS |

F=Franchise part. S=SpcNett.

| | | |
|-------------------------|-----------------|-----------------|
| Total Parts (\$) | 2,714.30 | 2,275.70 |
|-------------------------|-----------------|-----------------|

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|---------------------|---|----------|---------------------------------|-----------------|
| Labour Items | | | | |
| 1 | TO REPLACE ENGINE HOOD AND MAKE GOOD FRONT BUMPER | New | 1,700.00 | 850.00 |
| 2 | TO RESPRAY ENGINE HOOD AND FRONT BUMPER | New | 2,336.00 | 1,298.00 |
| 3 | TO CARRY OUT BODY CAVITY PRESERVATION (PER PANEL) | New | 118.00 | 112.00 |
| 4 | TO CHECK ELECTRICAL SYSTEM | New | 177.00 | 168.00 |
| | | | Gross Labour Cost (\$\$) | 2,428.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >