

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22006485/KQY3Q2**Date:** 02/11/2022REFERENCEHandling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSNW00046172201

**Claimant Vehicle
No :** GBH2655G**Insured Vehicle
No :** XE494Y

Date of Loss: 05/07/2022

Nature of Claim: TP

Claim
No: SNM22D204681/C02/CSCDESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **GBH2655G**

Make & Model: TOYOTA HIACE, 3.0 D TURBO 5DR (M)

Engine No: 1KD2797663

Reg. Date: 11/04/2018 (Man. Year: 2018)

Chassis No: JTFHT02P000242279

Colour: White

Odometer: 136975 km

Engine Capacity: 2982 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15X8

Rear Tyre Size:

195 R15X8

Front Left Side: OHTSU 3 mm

Rear Left Side:

Bridgestone 6 mm

Front Right Side: OHTSU 3 mm

Rear Right Side:

Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	19,391.20	10,654.65	8,736.55	45.05
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,280.00	4,380.00	1,900.00	30.25
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	25,671.20	15,034.65	10,636.55	41.43
Approved Total (Overridden) (\$\$)		11,800.00		
Nett Amount (\$\$)	25,671.20	11,800.00	13,871.20	54.03

INSPECTION

Date of Assignment: 28/10/2022

Date Inspected: 07/07/2022 Inspected At:

Poon Siang Seow (HQ)

160 Sin Ming Drive, #05-13 Sin Ming AutoCity
Singapore 575722

Estimated Period of Repair: 16.0 days

Adjuster: KENNETH KONG**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 01 Nov 2022)
Parts:	213	TOYOTA HIACE 3.0 D TURBO 5DR (M) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBH2655G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR FENDER LEFT	Bent / Buckled	1,623.30 F	*1,623.30 FL
2	1		*REAR FENDER RIGHT	Bent / Buckled	1,623.30 F	*1,623.30 FL
3	1		*TAIL LAMP INNER PANEL LEFT	Bent	596.90 F	*542.10 FL
4	1		*TAIL LAMP INNER PANEL RIGHT	Bent	596.90 F	*542.10 FL
5	2		*REAR FENDER INNER TRIM SIDE PANEL	Bent	593.90 F	*593.90 FL
6	2		*REAR PANEL CONNER TRIM PANEL	Cracked	240.00 F	*240.00 FL
7	2		*REAR FENDER INNER PANEL	Repair	792.00 F	*- FL
8	1		*REAR FENDER INNER AIR INLET	Serviceable	163.20 F	*- FL
9	1		*TAIL GATE	Bent	2,492.30 F	*1,855.20 FL
10	2		*TAIL GATE DAMPER	Bent (1 PCS ONLY)	627.80 F	*313.90 FL
11	1		*TAIL GATE RUBBER (50%)	Cut	396.90 FS	*198.45 FS
12	1		*TAIL GATE WIPER MOTOR	Serviceable	598.90 F	*- FL
13	1		*TAIL GATE WIPER MOTOR GARISH COVER	Distorted	230.00 F	*230.00 FL
14	1		*WIPER ARM AND BLADE	Dented	98.00 F	*98.00 FL
15	1		*THIRD BRAKE LAMP	Mtg Cracked	185.90 F	*185.90 FL
16	1		*TAIL GATE LOGO	Necessary	65.90 F	*65.90 FL
17	1		*TAIL GATE STICKER TOYOTA HIACE	Necessary	89.80 F	*89.80 FL
18	1		*TAIL GATE STICKER 70K/M	Necessary	20.00 FS	*15.00 FS
19	1		*TAIL GATE INNER LOCK	Jammed	297.90 F	*297.90 FL
20	1		*TAIL GATE OUTER HANDLE	Warped	159.80 F	*159.80 FL
21	2		*NUMBER PLATE LAMP	Serviceable	80.00 F	*- FL
22	1		*TAIL GATE BOARD	Buckled	119.80 F	*119.80 FL
23	1		*FLOOR WOODEN BOARD	Serviceable	450.00 F	*- FL
24	1		*SPARE TYRE HOLDER	Repair	360.00 F	*- FL
25	1		*REAR PANEL	Bent	396.90 F	*396.90 FL
26	1		*REAR PANEL INNER PANEL	Repair	360.00 F	*- FL
27	1		*REAR PANEL TOP MOULDING	Distorted	120.00 F	*120.00 FL
28	2		*TAIL LAMP	Broken	731.80 F	*613.80 FL
29	2		*TAIL LAMP CONNER PANEL	Buckled	303.90 F	*303.90 FL
30	2		*TAIL LAMP CONNER PANEL RETAINER	Distorted	202.40 F	*202.40 FL
31	1		*REAR BUMPER	Bent	454.90 F	*454.90 FL
32	1		*REAR BUMPER SENSOR	Dented	350.00 FS	*200.00 FS
33	2		*REAR BUMPER RETAINER	Cracked	131.80 F	*131.80 FL
34	6		*REAR BUMPER CHIP	Necessary	9.00 F	*9.00 FL
35	1		*FRONT DASHBOARD GARISH	Serviceable	650.00 F	*- FL
36	1		*CAMERA	Missing	588.00 FS	*250.00 FS
37	1		*W/S GLASS	Shattered	1,340.00 F	*1,340.00 FL
38	1		*NUMBER PLATE	Dented	50.00 FS	*20.00 FS
39	1		*STICKER LOGO	Necessary	1,200.00 FS	*856.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	19,391.20	13,693.05
- List Item Discount on L Items 0.00/25.00% (\$)	0.00	3,038.40
Total Parts (\$)	19,391.20	10,654.65

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RUST PROOFING	New	150.00	120.00
2	TO REMOVE AND REFIT ROOF CUSHION	New	180.00	100.00
3	TO REMOVE AND REFIT REAR W/S GLASS AND SEALANT	New	350.00	160.00
4	PANEL BEATING	New	3,800.00	2,600.00
5	SPRAY PAINTING	New	1,800.00	1,400.00
Gross Labour Cost (\$)			6,280.00	4,380.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >