

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22006488/ECY3Q2**Date:** 28/11/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00051962200

Claimant Vehicle No : SLZ7564P **Insured Vehicle No :** YQ6801E

Date of Loss: 05/07/2022 Nature of Claim: TP Claim No: SNM22D204741/C02/LEEPG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLZ7564P**

Make & Model: INFINITI Q30, 1.5 D PREM DCT EU6 (A) Engine No: K9KG481D004093

Reg. Date: 17/05/2018 (Man. Year: 2017) Chassis No: SJKDAAH15U1060729

Colour: Blue Odometer: 41768 km

Engine Capacity: 1461 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/50 R18 Rear Tyre Size: 235/50 R18

Front Left Side: Bridgestone 5 mm Rear Left Side: Bridgestone 5 mm

Front Right Side: Bridgestone 5 mm Rear Right Side: Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	24,655.40	22,049.55	2,605.85	10.57
Miscellaneous Items	0.00	0.00	0.00	
Labour	11,478.00	9,878.00	1,600.00	13.94
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	36,133.40	31,927.55	4,205.85	11.64
+ GST 7.00/7.00% (S\$)	2,529.34	2,234.93	294.41	11.64
Nett Amount (S\$)	38,662.74	34,162.48	4,500.26	11.64

INSPECTION

Date of Assignment: 07/07/2022

Date Inspected: 07/07/2022 Inspected At: 45 LENG KEE ROAD
SINGAPORE 159103.
Repairer:Wearnes Automotive Pte Ltd (Leng Kee)

Estimated Period of Repair: 8.0 days

Adjuster: CHEN TSUE YEE**Manager:** CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 28 Nov 2022)

Parts: N/A INFINITI Q30 1.5 D PREM DCT EU6 (A) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLZ7564P)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FENDER -FRONT LH Q30	Dented	2,250.00 FS	*2,025.00 FS
2	1		*BAFFLE PLATE -FRT FEN	Crushed	336.10 FS	*302.49 FS
3	6		*CLIP CANOE	Necessary	30.00 FS	*27.00 FS
4	1		*FENDER -OVER ,FR	Cut	1,450.10 FS	*1,305.09 FS
5	2		*SCR -P HD PP,W	Necessary	7.40 FS	*6.66 FS
6	2		*CLIP	Necessary	5.20 FS	*4.68 FS
7	1		*DOOR -FRONT LH Q30	Dented	3,329.30 FS	*2,996.37 FS
8	1		*DOOR SEAL FRT LH Q30	Necessary	525.80 FS	*473.22 FS
9	1		*MIRROR ASSY -OUT	Cut	1,197.30 FS	*1,077.57 FS
10	1		*COVER -MIRR BODY FRT	Cut	199.20 FS	*179.28 FS
11	1		*DOOR -REAR LH	Dented	3,163.50 FS	*2,847.15 FS
12	1		*WSTRIP ASSY -RR	Necessary	499.50 FS	*449.55 FS
13	1		*FENDER OVER REAR LH	Cut	1,450.10 FS	*1,305.09 FS
14	10		*GROM-SCR	Necessary	26.00 FS	*23.40 FS
15	2		*RIVET	Necessary	25.20 FS	*22.68 FS
16	2		*WHEEL-ROAD ALLOY 18	Cut	8,948.20 FS	*8,053.38 FS
17	1		*GRIP -OUTSIDE LH	Cut	776.50 FS	*698.85 FS
18	1		*ESCU-OUTSIDE LH	Necessary	107.60 FS	*96.84 FS
19	1		*GASKET -OUTSIDE	Necessary	6.10 FS	*5.49 FS
20	1		*GASKET -OUTSIDE	Necessary	6.40 FS	*5.76 FS
21	1		*BRKT -DOOR OUTSI	Not Necessary	171.90 FS	*- FS
22	1		*RIVET DOOR TRIM -Q30 (25 PCS)	Necessary	144.00 FS	*144.00 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) **24,655.40** **22,049.55**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE FRT LH DOOR REAR LH DOOR ,FRT LH FENDER ,FRT LH FENDER MLDING ,REAR LH FENDER MLDING,WING MIRROR LH	New	4,800.00	3,200.00
2	TO SPRAYPAINT ON FRT LH FENDER ,FRT LH DOOR ,REAR LH DOOR ,REAR LH FENDER ,REAR BUMPER ,WING MIRROR LH ETC	New	4,800.00	4,800.00
3	TO REMOVE ,REFIT & TRANSFER ,FRT LH DOOR COMPONENTS	New	500.00	500.00
4	TO REMOVE ,REFIT & TRANSFER REAR LH DOOR COMPONENTS	New	500.00	500.00
5	TO REPLACE FRT LH RIM	New	50.00	50.00
6	TO REPLACE REAR LH RIM	New	50.00	50.00
7	WHEEL ALIGNMENT	New	280.00	280.00
8	TO CHECK WIRING INCLUDING RESETTING OF ALL ELECTRICAL MODULES	New	498.00	498.00
Gross Labour Cost (\$\$)			11,478.00	9,878.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >