

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI22006489/VCY3Q2**Date:** 17/10/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00022812200	
<b>Claimant Vehicle No :</b>	SBS6792J	<b>Insured Vehicle No :</b>	XE7073H	
Date of Loss:	01/07/2022	Nature of Claim:	TP	Claim No: SNM22D204737/C02/TANCHC

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SBS6792J</b>			
Make & Model:	MERCEDES-BENZ CITARO O530, 6.4 L AT TURBO ABS (A)	Engine No:	902926C1064423	
Reg. Date:	08/08/2014 (Man. Year: 2014)	Chassis No:	WEB62808323125436	
Colour:	Multi-colour	Odometer:	4242640 km	
Engine Capacity:	6374 cc			
Market Value/New Car Price:	N/A			
Sum Insured (S\$):	<b>Market Value/New Car Price</b>			

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	275/70 R22.5	Rear Tyre Size:	275/70 R22.5
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	2,632.00	2,632.00	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	688.00	688.00	0.00	0.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>3,320.00</b>	<b>3,320.00</b>	<b>0.00</b>	<b>0.00</b>
<b>+ GST 7.00/7.00% (S\$)</b>	232.40	232.40	0.00	0.00
<b>Nett Amount (S\$)</b>	<b>3,552.40</b>	<b>3,552.40</b>	<b>0.00</b>	<b>0.00</b>

**INSPECTION**

Date of Assignment:	07/07/2022		
Date Inspected:	07/07/2022	Inspected At:	Sbs Transit Ltd ( Bedok) (HQ) 1470 BEDOK NORTH AVE 4 Singapore 489946
Estimated Period of Repair:	2.0 days		

**Adjuster:** Thevan Thomas Karthikesavan**Manager:** CELINE FONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

(REPAIR COST NOT CONCLUDE)

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 14 Oct 2022)	
<b>Parts:</b>	N/A	MERCEDES-BENZ CITARO O530 6.4 L AT TURBO ABS (A) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SBS6792J)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SEALING SECTION RIGHT ,ENT,EXIT DR	Cut	601.00 F	*601.00 F
2	1		*SEALING SECTION LEFT ,ENT,EXIT DR	Cut	601.00 F	*601.00 F
3	4		*DOOR STOPPER ,EXIT DOOR	Necessary	106.00 F	*106.00 F
4	1		*GLASS NO 4 EXIT DR	Broken	662.00 F	*662.00 F
5	1		*GLASS NO 3 EXIT DR	Broken	662.00 F	*662.00 F
<b>Total Parts (S\$)</b>						<b>2,632.00</b>
						<b>2,632.00</b>

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	CONTRACTOR LABOUR COST	New	500.00	500.00
2	WORKSHOP LABOUR COST	New	188.00	188.00
3	ADVERTISEMENT COST (NPA)	New	0.00	0.00
4	TOW COST (NPA)	New	0.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>688.00</b>	<b>688.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >