

SLN2557G [SDM669E] - Submitted by: A-PAC Adjusters & Surveyors Pte Ltd (HQ)



1/44: Dismantling Photo



2/44: Dismantling Photo



3/44: Rear Boot Sponge Storage - Cut



4/44: Rear Boot Sponge Storage - Cut

SLN2557G [SDM669E] - Submitted by: A-PAC Adjusters & Surveyors Pte Ltd (HQ)



5/44: Tailgate Inner Trim - Studs Cracked



6/44: Tailgate Inner Trim - Studs Cracked



7/44: Tailgate Inner Trim - Studs Cracked



8/44: Rear Exhaust Assembly - Bent

SLN2557G [SDM669E] - Submitted by: A-PAC Adjusters & Surveyors Pte Ltd (HQ)



9/44: Rear Exhaust Assembly - Bent



10/44: Rear Exhaust Assembly - Bent



11/44: Tailgate Weather Moulding - Deformed



12/44: Tailgate Weather Moulding - Deformed

SLN2557G [SDM669E] - Submitted by: A-PAC Adjusters & Surveyors Pte Ltd (HQ)



13/44: Reverse Sensoer - Cracked



14/44: Reverse Sensoer - Cracked



15/44: Tailgate Handle Grib - Cracked



16/44: Tailgate Handle Grib - Cracked

SLN2557G [SDM669E] - Submitted by: A-PAC Adjusters & Surveyors Pte Ltd (HQ)



17/44: Rear End Panel Garnish - Dented/Deformed



18/44: Rear End Panel Garnish - Dented/Deformed



19/44: Tailgate Sensor - Cracked



20/44: Tailgate Sensor - Cracked

SLN2557G [SDM669E] - Submitted by: A-PAC Adjusters & Surveyors Pte Ltd (HQ)



21/44: Tailgate Sensor - Cracked



22/44: Tailgate Sensor Bracket - Cracked



23/44: Tailgate Sensor - Electrical Plug Cracked



24/44: Tailgate Sensor - Electrical Plug Cracked

SLN2557G [SDM669E] - Submitted by: A-PAC Adjusters & Surveyors Pte Ltd (HQ)



25/44: Rear Bumper Reflector LH - Stud Cracked



26/44: Rear Bumper Reflector LH - Stud Cracked



27/44: Rear Bumper Reflector RH - Stud Cracked



28/44: Rear Bumper Reflector RH - Stud Cracked

SLN2557G [SDM669E] - Submitted by: A-PAC Adjusters & Surveyors Pte Ltd (HQ)




29/44: Taillamp LH - Studs Cracked



30/44: Taillamp LH - Studs Cracked



31/44: Taillamp LH - Studs Cracked



32/44: Taillamp RH - Studs Cracked

SLN2557G [SDM669E] - Submitted by: A-PAC Adjusters & Surveyors Pte Ltd (HQ)



33/44: Taillamp RH - Studs Cracked



34/44: Taillamp RH - Studs Cracked



35/44: Tailgate Lock Assembly - Jammed



36/44: Tailgate Lock Assembly - Jammed

SLN2557G [SDM669E] - Submitted by: A-PAC Adjusters & Surveyors Pte Ltd (HQ)



37/44: Rear End Panel - Dented/Deformed



38/44: Rear End Panel - Dented/Deformed



39/44: Rear End Panel - Dented/Deformed



40/44: Rear End Panel - Dented/Deformed

SLN2557G [SDM669E] - Submitted by: A-PAC Adjusters & Surveyors Pte Ltd (HQ)



41/44: Rear End Panel - Dented/Deformed



42/44: Spare Tyre Wheel - Dented



43/44: Spare Tyre Wheel - Dented



44/44: Spare Tyre Wheel - Dented