

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: MSIG/TPS/21-02007  
Date: 05/03/2021

### REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: 29126858AT2  
Claimant Vehicle No: SLN2557G Insured Vehicle No: SDM669E  
Date of Loss: 02/02/2021 Nature of Claim: TP Claim No: 633543

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLN2557G  
Make & Model: HONDA VEZEL HYBRID, 1.5 RS (A) Engine No: L15B4406627  
Reg. Date: 27/04/2017 (Man. Year: 2017) Chassis No: RU11206627  
Colour: Grey/Silver Odometer: 295280 km  
Engine Capacity: 1496 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): Market Value/New Car Price

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 215/60R16 Rear Tyre Size: 215/60R16  
Front Left Side: Goldway 6 mm Rear Left Side: Goldway 6 mm  
Front Right Side: Goldway 6 mm Rear Right Side: Goldway 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	6,004.00	-6,004.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	1,020.00	-1,020.00	
Paintwork Labour	0.00	800.00	-800.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>0.00</b>	<b>7,824.00</b>	<b>-7,824.00</b>	
<b>Approved Total (Overridden) (S\$)</b>		<b>6,250.00</b>		
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>6,250.00</b>	<b>-6,250.00</b>	
<b>Liabe Amount (0.00%) (S\$)</b>		<b>0.00</b>		

### INSPECTION

Date of Assignment: 04/02/2021  
Date Inspected: 04/02/2021, 05/02/2021, 23/02/2021 Inspected At: Messrs Lay Auto Garage Pte Ltd (HQ)  
38 Toh Guan Road East #01-56  
Singapore 608581  
Estimated Period of Repair: 7.0 days

Adjuster: William Ng Manager: Patrick Soo

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

### **CONSISTENCY OF DAMAGES**

1. The inspected vehicle sustained damage at the REAR portion.
2. During visual inspection, our surveyor noted that the tailgate, rear bumper, taillamp left & right, rear end panel and among other parts were affected.
3. All stated damage is subject to consistency of the accident reports.

### **MARKET VALUE**

The market value of this vehicle was at about S\$66,000.00 at the time of the accident with PARF/COE Rebate at S\$48,594.00. The Economical Repair Limit is about S\$17,406.00. In our opinion, it is NOT economical to repair if the cost of repair exceeded S\$17,406.00.

### **SPECIAL REMARKS**

1. The repairer did NOT provide Repair Estimate during our pre-repair inspection.
2. Our surveyor recommended cost of repair is on Lump Sum Basis estimated at S\$6,250.00.
3. The repair would require 7.0 days for completion.
4. We have perused the contents of the GIA Reports from both parties and collision impact portion noted on subject vehicle has been found to be consistent towards the accident.
5. This inspection was conducted on a "Without Prejudice" Basis.

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 10 Feb 2021)
<b>Parts:</b>	M1-SUV	HONDA VEZEL HYBRID 1.5 RS (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	<b>A-PAC Adjusters &amp; Surveyors Pte Ltd/SLN2557G/05/03/2021 14:11</b>	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Dented	0.00 F	*- FL
2	1		*REAR BUMPER	Dented	0.00 F	*- FL
3	1		*TAILGATE INNER TRIM	Studs Cracked	0.00 F	*- FL
4	1		*REAR BOOT STORAGE SPONGE	Torn	0.00 F	*- FL
5	1		*REAR EXHAUST ASSEMBLY	Bent	0.00 F	*- FL
6	1		*TAILGATE WEATHERSTRIP	Deformed	0.00 F	*- FL
7	1		*TAILGATE HANDLE GRIP	Cracked	0.00 F	*- FL
8	1		*REAR BUMPER REFLECTOR LH/RH	Cracked	0.00 F	*- FL
9	1		*TAIL LAMP LH	Studs Cracked	0.00 F	*- FL
10	1		*TAIL LAMP RH	Cracked	0.00 F	*- FL
11	1		*REAR END GARNISH	Deformed	0.00 F	*- FL
12	1		*REAR END PANEL	Dented	0.00 F	*- FL
13	1		*SPARE WHEEL WELL	Deformed	0.00 F	*- FL
14	1		*REAR WINDSCREEN WEATHERSTRIP	Necessary	0.00 F	*- FL
15	1		*TAILGATE LOCK ASSEMBLY	Necessary	0.00 F	*- FL
16	1		*SEALANT	Necessary	0.00 FS	*- FS
17	1		*REAR BUMPER CLIPS	Necessary	0.00 FS	*- FS
18	1		*REVERSE SENSOR	Cracked	0.00 FS	*- FS
19	1		*TAILGATE SENSOR ASSEMBLY	Malfunctioned	0.00 FS	*- FS
20	1		*ESTIMATE PARTS PRICE		-	*6,830.00 FL
21	1		*ESTIMATE SPECIAL NETT PARTS PRICE		-	*540.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>0.00</b>	<b>7,370.00</b>
<b>- List Item Discount on L Items 0.00/20.00% (\$\$)</b>	<b>0.00</b>	<b>1,366.00</b>
<b>Total Parts (\$\$)</b>	<b>0.00</b>	<b>6,004.00</b>

A-PAC Adjusters & Surveyors Pte Ltd/SLN2557G/05/03/2021 14:11. Not valid without Reference section.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Paintwork Labour</u>				
1	SPARY PAINTING.	New	-	800.00
<u>Labour Items</u>				
2	LABOUR TO REFIX/REPLCACE/ REPAIR ACCIDENT AFFECTED AREAS.	New	0.00	900.00
3	LABOUR TO REMOVE AND REFIX TAILGATE WINDSCREEN.	New	-	120.00
<b>Gross Labour Cost (\$\$)</b>			<b>0.00</b>	<b>1,820.00</b>

A-PAC Adjusters & Surveyors Pte Ltd/SLN2557G/05/03/2021 14:11. Not valid without Reference section.

< END OF ESTIMATES >