9/13/22, 9:14 AM Adjuster Report

#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG22006494/UPA3Q2

13/09/2022 Date:

**REFERENCE** 

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2070099429 **Claimant Vehicle** 

YN2725J Insured Vehicle No: **SBA8000T** No:

Date of Loss: 02/07/2022 Nature of Claim: TP Claim No: 6198535203SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: YN2725J

Make & Model: HINO XZU700R, 4.0 D (M) N04CUV10873 Engine No:

Reg. Date: 02/04/2012 (Man. Year: 2011) Chassis No: JHHTCP3H70K001212

Colour: White Odometer: 223815 km

**Engine Capacity:** 4009 cc Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price** 

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Engine Modification: Pre-accident Condition: Yes Nο

CONDITION OF TYRES

Front Tyre Size: 7.00 R16 Rear Tyre Size: 7.00 R16 (D) Front Left Side: Rear Left Side: Austone 8/8 mm Austone 8 mm Front Right Side: Austone 8 mm Rear Right Side: Austone 8/8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		4,013.00	1,755.50	2,257.50	56.25
Miscellaneous Items		0.00	0.00	0.00	
Labour		1,840.00	1,000.00	840.00	45.65
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	5,853.00	2,755.50	3,097.50	52.92
	Approved Total (Overridden) (S\$)		2,200.00		
	Nett Amount (S\$)	5,853.00	2,200.00	3,653.00	62.41
	+ Loss of Use (5.0 x S\$*	120.00/day) (S\$)	600.00		
	+ Doc/s	Search Fee (S\$)	2.00		
	N	ett Liability (S\$)	2,802.00		
	Global Sum Settlement (S\$)		2,800.00		

**INSPECTION** 

Date of Assignment: 07/07/2022

Liu's Brother Auto Engineering Workshop (HQ)

BLK 1 KAKI BUKIT AVE 6, #01-01 AUTO BAY @ Date Inspected: 07/07/2022 Inspected At:

KAKI BUKIT Singapore 417883

Estimated Period of Repair: 4.0 days

MARCUS CHUA Manager: **CHEW HSIAO TONG** Adjuster:

### **REPAIR DETAILS**

## **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER (SAFETY BAR)	Bent	600.00 FS	*600.00 FS
2	2		*REAR BUMPER BRACKET	Bent	500.00 FS	*500.00 FS
3	1		*SET REAR FREEZER BOX SUPPORT RUBBER CENTRE BIG	Torn	250.00 FS	*250.00 FS
4	1		*REAR NUMBER PLATE PANEL	Repair	860.00 F	*- FL
5	1		*REAR NUMBER PLATE LAMP	Cracked	165.00 F	*165.00 FL
6	1		*REAR NUMBER PLATE METAL	Bent	28.00 FS	*14.00 FS
7	2		*REAR LH FREEZER BOX DOOR RUBBER (Torn)	Not Consistent With The Impact	760.00 FS	*-FS
8	1		*REAR LH FREEZER BOX SUPPORT RUBBER SMALL	Not Necessary	200.00 FS	*- FS
9	1		*REAR LH TAIL LAMP	Cracked	270.00 F	*270.00 FL
10	1		*REAR RH FREEZER BOX DOOR RUBBER LOWER	Not Necessary	380.00 FS	*- FS
F=Fra	nchise	part. S=S	SpcNett. L=ListItemDisc.		-	
				Sub Total (S\$)	4,013.00	1,799.00
- List Item Discount on L Items 0.00/10.00% (S\$)					0.00	43.50
				Total Parts (S\$)	4,013.00	1,755.50
			Report was unsubmitted during t	this print-out.	E	

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Lab</u>	our Items			
1	TO REMOVE ,REPLACE AND REALIGN FREEZER DOOR PANEL ,FITTING AND MECHANISMS	New	600.00	0.00
2	TO CHECK ALL WIRING & ELECTRICAL COMPONENT FOR PROPER FUNCTION	New	40.00	20.00
3	LABOR FOR PANEL BEATING ,CUT ,WELD ,STRAIGHTEN & REPLACING PARTS ETCS	New	600.00	580.00
4	TO PUTTY & SPRAY PAINTING & INCLUDING TOUCH UP PAINT ON ACCIDENT AFFECTED AREAS	New	600.00	400.00
	Gross Labou	r Cost (S\$)	1,840.00	1,000.00
	Report was unsubmitted during this	print-out.		

< END OF ESTIMATES >