



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. YP 8454R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	REAR CHASSIS CROSS MEMBER	DISTORTED	1,855.70	1,200.00
	LESS 10% DISCOUNT		-185.57	-120.00
			1,670.13	1,080.00
<b><u>SPECIAL NETT ITEMS</u></b>				
2	REAR REVERSE LAMP (SN)	DAMAGED	100.00	100.00
1	REAR NUMBER PLATE (SN)	DAMAGED	65.00	30.00
1	REAR NUMBER PLATE HOLDER (SN)	NECESSARY	35.00	15.00
1	REAR NUMBER PLATE LAMP (SN)	SHOCKED	45.00	45.00
1	REAR BUMPER BEAM (SN)	BROKEN	650.00	500.00
2	REAR BUMPER BRACKET (SN)	CRACKED	180.00	180.00
1	REAR PALGATE (SN)	MALFUNCTION	8,000.00	2,500.00
1	TAILGATE "60KM/H" STICKER (SN)	NECESSARY	35.00	35.00
1	TAILGATE "12 PAX" STICKER (SN)	NECESSARY	25.00	25.00
			9,135.00	3,430.00
<b><u>LABOUR</u></b>				
	TO TUFF-KOTE EFFECT AREA.		180.00	50.00
	TO TRANSFER PALGATE MECHANISM, MOTOR, LOCK HANDLE AND WIRING.		600.00	200.00
	TO REMOVE & REPLACE PALGATE ASSY.		1,400.00	800.00
	TO CHECK WIRING SYSTEM.		180.00	50.00
			2,360.00	1,100.00
<b>GRAND TOTAL</b>			<b>13,165.13</b>	<b>5,610.00</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>4,500.00</b>

Report Ref No. CS3/AGI20003837/Tvy3e2-1

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ANG BRYAN TANI

Automotive Assessor / Investigator

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.