



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CS3/AGI20003837/Tvy3-1

AUTO & GENERAL INSURANCE (S) PL
(BUDGET DIRECT INSURANCE) 190
CLEMENCEAU AVENUE #03-01 S S C S 239924

Ref: ~~CS3/AGI20003837/Tvy3-1~~
Date: ~~30/11/2020~~ 30/05/2022
Code: AGI

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SJR 8630R	Veh. Inspected	YP 8454R
Policy No.		Coverage (\$)	0.00
Claim No.	C10005810	Excess (\$)	0.00
Assign From	WY RATILLA NG CHEN HOW	Assign Date	10/03/2020 30/05/2022

2. Vehicle Particulars & Condition

Make & Model	NISSAN MKB37BNHRA	c.c	7684
Engine No.	HIDDEN	Year of Reg.	2007
Chassis No.	MKB37BN00034	Colour	WHITE
Odometer	454398 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/90 R17.5	BRIDGESTONE	8 mm
L/H Front Tyre	225/90 R17.5	BRIDGESTONE	8 mm
R/H Rear Tyre	225/90 R17.5 (D)	BRIDGESTONE	8/8 mm
L/H Rear Tyre	225/90 R17.5 (D)	BRIDGESTONE	8/8 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
--

5. General Information

Accident Date	04/03/2020	Inspection Date	11/03/2020
Survey held at	MK VEHICLE ENTERPRISE 48 TOH GUAN ROAD EAST #04-124 SINGAPORE 608586		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$6,000-\$7,000

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	7 Working Days
-------------------------------------	----------------