Serveyor:	REF: CS1/SPF220	006499/Gcy3	Special Instruction:
From (Person): HAFIZUL FARHAL Estimated Cost: OD/TP Re-inspection / Eyalua To Inspect Vehicle No: SMZ at Workshop m/s APEX MOTO of 25 KAKI BUKIT ROAD 4 Policy No: Sum Insured: Make of Veh: (Client's Record)	Bill to: Bill to: 1984M PRING #01-55 SYNERGY @	Insured: QX 556K Tel: KB SINGPORE 417800. Claim No: ACS/105/009 Excess:	L/S: \$ 2,900 / DAYS: 4 Third Parties: Claimant: Surveyor: TY5 CONSULTANCY Workshop: APEX MOTORING
Date/Time: Confir Date/Time: Submit Date/Time Action/Instruction	Person Contacted: med with Fin t Final Fig \$1700 -	Vehicle IN / O	
Para(1): Parts found no			
Para(2): Comments on o	onsistency of dam	ages (Parts Not Consi	stent : NC)
Market Value Salvage Value Nett Value 1) Date/Time F 3) Date/Time F 5) Date/Time F	:le Pass tole Pass to	4) Date/Time	***************************************



(Registration No.: 53429875C)

Address: 50 Chin Swee Road #09-04, Thong Chai Building, Singapore 169874
Contact: +65 8788 5345 | Email Address: admin@ty5group.com.sg

Our Services: Automotive Surveying | Vehicle Valuation Motor Claims Investigation | Evaluation & Consultation

Reference : TY5/TA/10107/1984/TP/05.22

SGD 478.00

Date : 25 May 2022 Vehicle no : SMZ 1984M

To: Skyway Motor Pte Ltd c/o 25 Kaki Bukit Road 4 #01-55, Synergy @ Kaki Bukit Singapore 417800

INVOICE

PARTICULARS AMOUNT

Registration No. : SMZ 1984M Date of accident : 30 April 2022

Make / Model : Toyota C-HR Hybrid 1.8S CVT

Invoice No. : 10107

Being work done and services rendered as follows:

✓ Inspection of Vehicle

✓ Re-Inspection

✓ Appraisal Report

38 Colored Photographs

✓ Transport Charges

TOTAL SGD 478.00

Dollars: Four Hundred and Seventy-Eight Only

(Cheque should be crossed and make payable to " TY5 CONSULTANCY ")

TY5 CONSULTANCY



(Registration No.: 53429875C)

Address: 50 Chin Swee Road #09-04, Thong Chai Building, Singapore 169874 Contact: +65 8788 5345 | Email Address: admin@ty5group.com.sg

Our Services: Automotive Surveying | Vehicle Valuation Motor Claims Investigation | Evaluation & Consultation

Reference : TY5/TA/10107/1984/TP/05.22

Date : 25 May 2022 Vehicle no : SMZ 1984M

To: Skyway Motor Pte Ltd c/o 25 Kaki Bukit Road 4 #01-55, Synergy @ Kaki Bukit Singapore 417800

VEHICLE INSPECTION REPORT

Name of Workshop : Apex Motoring

Place of inspection : 25 Kaki Bukit Road 4 #01-55, Synergy @ Kaki Bukit, Singapore 417800

Date of Accident : 30 April 2022 Date of Inspection : 12 May 2022

VHICLE PARTICULAR

Registration No.	:	SMZ 198	34M	Chassis Frame No.	:	ZYX10-2177713
Make / Model	:	Toyota	C-HR Hybrid 1.8S CVT	Engine No.	:	2ZR2D67969
Year of Registration	:	2021		Odometer Reading	:	102,815 KM
Class / Type	:	SUV		Colour	:	Green

VEHICLE CONDITION

General Condition	:	Excellent	Steering	:	Serviceable
Paintwork	:	Excellent	Foot/ Parking Brake	:	Serviceable

TYRE CONDITION

	Size	Thread Balance
Front L/H :	DAVANTI 215 / 60 R17	$7\mathrm{mm}$
Front R/H :	DAVANTI 215 / 60 R17	7mm
Rear L/H :	DAVANTI 215 / 60 R17	$7 \mathrm{mm}$
Rear R/H :	DAVANTI 215 / 60 R17	7mm

^{*} The above is an estimate of the remaining life of the tyre thread in percentages

COST OF REPAIR

TY5 Recommendation

	F	Repairer S\$	A	djuster S\$	Lump S	um Repair :	
Parts	\$ 3,231.55		S	2,016.34	¢.	0.000.00	
Labour	8	2,120.00	\$	1,630.00	Ф	2,900.00	
	\$ 5,351.55		8	3,646.34	Estimate	Repair Duration:	

4

working days (excluding Sat, Sun & Public Holidays)

NOTE: The information contained in these documents may be privileged and confidential, and is intended for the exclusive use of the addressee designation. If you are not the addressee, any enclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited.



(Registration No.: 53429875C)

Address: 50 Chin Swee Road #09-04, Thong Chai Building, Singapore 169874 Contact: +65 8788 5345 | Email Address: admin@ty5group.com.sg

Our Services: Automotive Surveying | Vehicle Valuation Motor Claims Investigation | Evaluation & Consultation

Reference

: TY5/TA/10107/1984/TP/05.22

Date

: 25 May 2022

Vehicle no

: SMZ 1984M

ASSESSMENT SCHEDULE

<u>SN</u>	Qty	Descriptions	Conditions		Repairer's Estimate		Surveyor's Revised
		LIST ITEMS:-					
1	1 pc	rear upper bumper	deformed	8	808.45	s	808.45 < .
2	$1 \mathrm{pc}$	rear lower bumper	broken	8	406.10	S	406.10
3	$1 \mathrm{pc}$	rear bumper reinforcement	buckled	\$	509.10	8	509.10 X NN
4	1 pc	rear bumper tow hook cover	missing	\$	69.00	S	69.00
5	1 pc	rear bumper l/h side retainer	necessary	\$	65.30	\$	65.30
6	1 pc	rear bumper r/h side retainer	necessary	\$	65.30	S	65.30~
7	1 set	rear bumper clips	necessary	\$	35.00	S	35.00
8	2 pcs	reverse sensor @\$\$365.10	not working	\$	730.20	S	730.20 200 (SN)
9	$1\mathrm{pc}$	rear end (outer) panel	dented	\$	543.10		repair
				\$	3,231.55	\$	2,688.45
		Less 25%				s	672.11
				\$	3,231.55	\$	2,016.34



(Registration No.: 53429875C)

Address: 50 Chin Swee Road #09-04, Thong Chai Building, Singapore 169874 Contact: +65 8788 5345 | Email Address: admin@ty5group.com.sg

Our Services: Automotive Surveying | Vehicle Valuation Motor Claims Investigation | Evaluation & Consultation

Reference

: TY5/TA/10107/1984/TP/05.22

Date

: 25 May 2022

Vehicle no

: SMZ 1984M

ASSESSMENT SCHEDULE

<u>SN</u>	Qty	<u>Descriptions</u>	Conditions		Repairer's Estimate	5	Surveyor's Revised
		B/F		\$	3,231.55	\$	2,016.34
10		To panel beat and renewal of all necessary damaged body parts		\$	1,000.00	s	800.00 400
11		To remove and reinstall rear boot upholstery		\$	120.00	8	100.00
12		To remove and reinstall reverse sensor		\$	140.00	S	100.00 60
13		To apply anti-rust		\$	60.00	8	30.00 🗙
14		To putty and spray-paint of affected areas		8	800.00	\$	Oup 00.000
				\$	2,120.00	\$	1,630.00

(qdays



(Registration No.: 53429875C)

Address: 50 Chin Swee Road #09-04, Thong Chai Building, Singapore 169874 Contact: +65 8788 5345 | Email Address: admin@ty5group.com.sg

Our Services: Automotive Surveying | Vehicle Valuation


Motor Claims Investigation | Evaluation & Consultation

Reference : TY5/TA/10107/1984/TP/05.22

Date : 25 May 2022 Vehicle no : SMZ 1984M

ASSESSMENT SUMMARY

Damages sustained were consistent with the subject vehicle being involved in a collision with another vehicle and the impact of the collision was delivered Squarely to the Rear portion of the vehicle.



(Please refer to the list and survey photographs as attached for more information)

ASSESSMENT RECOMMENDATIONS

COST OF REPAIR

Repairer S\$ Adjuster S\$ Parts \$ 3,231.55 \$ 2,016.34 Labour \$ 2,120.00 \$ 1,630.00 \$ 5,351.55 \$ 3,646.34

TY5 Recommendation

Contract Lump Sum of

\$ 2,900.00

Estimated Repair Duration:

working days

(excluding Sat, Sun & Public Holidays)

Enclosed No. Of Photograph:

38

(at the time of static inspection)

Our attached assessment schedule has been checked throughly by us against the actual damages sustained on the vehicle, and we recommend the replacement of parts and repair accordingly. We have adjusted the cost and the repairer has agreed to undertake the repair at the recommended sum to a acceptable quality and standards. We have not given authorization and instruction to the repairer to proceed with the repairs.

The survey was done on a Without Prejudice Basis and we are reverting the matter to you for a decision.

We thank you for engaging our services and we enclosed herewith our invoice no.

10107

TY5 CONSULTANCY

TERRENCE HONG
AUTOMOTIVE SURVEYOR

NOTE: This revised estimate was from a visual inspection. Should there be any discrepancy or unseen items not listed in this survey, kindly notify the company via email only and follow up with a phone call, within Fourteen (14) days from the date hereof. Otherwise this revised amount shall be treated as valid.