

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/EG122006501/AVY3M4**Date:** 21/07/2022REFERENCE

Handling Insurer:	ERGO Insurance Pte. Ltd.	Policy No:	DMFG22001158
Claimant Vehicle No :	SDM78K	Insured Vehicle No :	YP1854R
Date of Loss:	06/07/2022	Nature of Claim:	TP
		Claim No:	CDMFG22001323

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SDM78K		
Make & Model:	MERCEDES-BENZ GLA200, 1.6 (A)	Engine No:	27091031526234
Reg. Date:	18/01/2019 (Man. Year: 2017)	Chassis No:	WDC1569432J470800
Colour:	White	Odometer:	26293 km
Engine Capacity:	1595 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/45 R19	Rear Tyre Size:	235/45 R19
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,822.90	3,304.20	1,518.70	31.49
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,800.00	1,110.00	690.00	38.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,622.90	4,414.20	2,208.70	33.35
Approved Total (Overridden) (S\$)		3,500.00		
Nett Amount (S\$)	6,622.90	3,500.00	3,122.90	47.15

INSPECTION

Date of Assignment:	07/07/2022	
Date Inspected:	06/07/2022	Inspected At: Ysk Auto Workshop (HQ) No.1 Kaki Bukit Avenue 6, #01-49 Autobay Singapore 417883
Estimated Period of Repair:	4.0 days	

Adjuster: ADRIAN LING**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 21 Jul 2022)
Parts:	M1-SUV	MERCEDES-BENZ GLA200 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SDM78K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT LH FENDER	Dented	997.40 F	*997.40 FL
2	1		*FRONT LH FENDER ARC MOULDING	Cut	235.90 F	*235.90 FL
3	1		*FRONT LH DOOR	Dented	2,022.40 F	*2,022.40 FL
4	1		*FRONT LH DOOR WEATHERSTRIP	Necessary	382.30 F	*382.30 FL
5	1		*FRONT LH DOOR WING MIRROR	Not Necessary	1,154.90 F	*- FL
6	1		*FRONT LH FENDER ARC MOULDING CLIPS	Necessary	30.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,822.90	3,668.00
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	363.80
Total Parts (\$\$)	4,822.90	3,304.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	800.00	500.00
2	SPRAY PAINTING	New	800.00	500.00
3	WIRING	New	50.00	30.00
4	TO TRANSFER DOOR FITTINGS	New	150.00	80.00
Gross Labour Cost (\$\$)			1,800.00	1,110.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >