

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22006502/KVY3Q2**Date:** 18/10/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNA00119112101

Claimant Vehicle No : GBF2339E **Insured Vehicle No :** YP4579R

Date of Loss: 03/07/2022 Nature of Claim: TP Claim No: SNM22D204647/C02/LEEPG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBF2339E**

Make & Model: MITSUBISHI CANTER, 3.0 D FEA01BR1SDEB (M) Engine No: 4P10C24850

Reg. Date: 22/08/2016 (Man. Year: 2016) Chassis No: FEA01BA20293

Colour: White Odometer: 125042 km

Engine Capacity: 2998 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15X8 Rear Tyre Size: 195 R15X8 (D)

Front Left Side: Bridgestone 9 mm Rear Left Side: Bridgestone 1/1 mm

Front Right Side: Bridgestone 9 mm Rear Right Side: Bridgestone 1/1 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,716.00	2,972.80	743.20	20.00
Miscellaneous Items	20.00	20.00	0.00	0.00
Labour	1,990.00	1,620.00	370.00	18.59
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	5,726.00	4,612.80	1,113.20	19.44
Approved Total (Overridden) (\$\$)		4,600.00		
(\$\$)	5,726.00	4,600.00	1,126.00	19.66
+ GST 7.00/7.00% (\$\$)	400.82	322.00	78.82	19.66
Nett Amount (\$\$)	6,126.82	4,922.00	1,204.82	19.66

INSPECTION

Date of Assignment: 17/10/2022 Present Location: Cheng Hoe Motor Pte Ltd (Yishun)

Date Inspected: 13/07/2022 Inspected At: Cheng Hoe Motor Pte Ltd (Yishun)
Blk 1019 #01-374/382, Yishun Industrial Park A
Singapore 768761

Estimated Period of Repair: 6.0 days

Adjuster: KENNETH KONG**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 17 Oct 2022)	
Parts:	N/A	mitsubishi canter 3.0 d fea01br1sdeb (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBF2339E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*1 PC FRT BUMPER RH SIDE PAD	Buckled / Cut	190.00 F	*190.00 FL
2	1		*1 PC RH SIGNAL LAMP	Broken	160.00 F	*160.00 FL
3	1		*1 PC RH HEADLAMP	Mtg Cracked	280.00 F	*280.00 FL
4	1		*1 PC RH HEADLAMP SIDE REFLECTOR	Broken	110.00 F	*110.00 FL
5	1		*1 PC FRT RH CORNAL PANEL	Cracked	240.00 F	*240.00 FL
6	1		*1 PC FRT RH DOOR	Bent	950.00 F	*950.00 FL
7	1		*1 PC FRT RH DOOR TOP HINGE	Distorted	75.00 F	*75.00 FL
8	1		*1 PC FRT RH DOOR BOTTOM HINGE	Bent	75.00 F	*75.00 FL
9	1		*1 PC FRT RH DOOR CHECKER	Bent	38.00 F	*38.00 FL
10	1		*1 PC FRT RH DOOR INNER RUBBER	Cut	160.00 F	*160.00 FL
11	1		*1 PC FRT RH DOOR INNER LOWER RUBBER	Cut	18.00 F	*18.00 FL
12	1		*1 PC FRT RH DOOR LOWER PROTECTOR	Bent	45.00 F	*45.00 FL
13	1		*1 PC FRT RH DOOR GLASS REGULATOR	Distorted / Bent	420.00 F	*420.00 FL
14	1		*1 PC FRT RH DOOR STICKER (DUONIC)	Necessary	40.00 F	*40.00 FL
15	1		*1 PC FRT RH STEP TRAY	Cracked	235.00 F	*235.00 FL
16	1		*1 PC FRT RH WHEEL ARP PANEL	Bent	260.00 F	*260.00 FL
17	1		*1 PC FRT RH WHEEL ARP TOP GARNISH	Dented	80.00 F	*80.00 FL
18	1		*1 PC FRT RH STEP PANEL	Bent	200.00 F	*200.00 FL
19	1		*1 PC FRT RH DOOR INNER LOCK	Dented	105.00 F	*105.00 FL
20	1		*1 PC FRT RH DOOR INNER AIR-SCOOP GRILLE	Cracked	35.00 F	*35.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$)	3,716.00	3,716.00
- List Item Discount on L Items 0.00/20.00% (\$)	0.00	743.20
Total Parts (\$)	3,716.00	2,972.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	1 PC FRT RH DOOR COY STICKER (NECESSARY)	20.00	20.00
Sub Total (\$\$)			20.00	20.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE & REFIX FRT RH DOOR,TRANSFER DOOR ATTACHMENT,TO STRAIGHTEN,KNOCK & REPAIR FRT RH W/SCREEN PILLAR,TO CUT,WELD & RENEW FRT RH STEP PANEL,WHEEL ARP PANEL,KNOCK & REPAIR FRT RH FLOOR BOARD AND REALIGN THE SAME	New	1,100.00	850.00
2	PUTTY & RESPRAY ON FRT RH W/SCREEN PILLAR,FRT RH STEP PANEL,FRT RH WHEEL ARP PANEL,FRT BUMPER,FRT RH DOOR	New	700.00	600.00
3	REMOVE & REFIX FRT RH DOOR GLASS,CHECK CENTRE LOCKING AND POWER MIRROR	New	60.00	60.00
4	TO REWRITE ADVERTISEMENT	New	100.00	80.00
5	RUSTPROOFING	New	30.00	30.00
Gross Labour Cost (\$\$)			1,990.00	1,620.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >