

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

MS FIRST CAPITAL INSURANCE LTD	Affiliated to Federation Internationale Des Experts En Automobile					
#16-01 CITY HOUSESINGAPORE 068877 Code: FCI2		MS FIRST CAPITA	L INSURANCE LTD	Ref	CS/FCI22006504/Kcy3m4	
Policy Particulars: THIRD PARTY CLAIM Insured Veh. GX 298Z				Date	e: 23/08/2022	
Insured Veh. GX 298Z				Cod	le: FCI2	
Policy No. D-22098657MCVP Coverage (\$) 0.00	1.	Policy Particulars :- THIRD PARTY CLAIM				
Claim No. D22002056MCVP Excess (\$) 0.00 Assign From JOANNE TAN JOANN Assign Date 07/07/2022		Insured Veh.	GX 298Z	Veh. Inspected	SJA 2384E	
Assign From JOANNE TAN JOANN Assign Date 07/07/2022		Policy No.	D-22098657MCVP	Coverage (\$)	0.00	
Nake & Model TOYOTA VIOS (A) C.c. 1497		Claim No.	D22002056MCVP	Excess (\$)	0.00	
Make & Model		Assign From	JOANNE TAN JO ANN	Assign Date	07/07/2022	
Engine No.	2. Vehicle Particulars & Condition					
Chassis No. MR053HY9305015505 Colour METALLIC GREY Odometer 281879 KM Steering IN ORDER Brakes IN ORDER Modification STANDARD ALLOY RIM General GOOD 3. Conditions of Tyres Size Make Balance		Make & Model	TOYOTA VIOS (A)	c.c	1497	
Odometer 281879 KM Steering IN ORDER		Engine No.	HIDDEN	Year of Reg.	2007	
Brakes IN ORDER Modification STANDARD ALLOY RIM General GOOD 3. Conditions of Tyres Size Make Balance		Chassis No.	MR053HY9305015505	Colour	METALLIC GREY	
General GOOD 3. Conditions of Tyres R/H Front Tyre		Odometer	281879 KM	Steering	IN ORDER	
3. Conditions of Tyres Size		Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
R/H Front Tyre 195/55 R15 ARIVO 4 mm L/H Front Tyre 195/55 R15 ARIVO 4 mm R/H Rear Tyre 195/55 R15 FALKEN 6 mm L/H Rear Tyre 195/55 R15 FALKEN 6 mm L/H Rear Tyre 195/55 R15 FALKEN 6 mm 4. Description of Damages THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS. 5. General Information Accident Date 04/07/2022 Inspection Date 08/07/2022 Survey held at AUBURN AUTO PTE LTD 176 SIN MING DRIVE #04-18 SIN MING AUTOCARE SINGAPORE 575721 5a. Remarks A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.		General	GOOD			
R/H Front Tyre 195/55 R15 ARIVO 4 mm L/H Front Tyre 195/55 R15 ARIVO 4 mm R/H Rear Tyre 195/55 R15 FALKEN 6 mm L/H Rear Tyre 195/55 R15 FALKEN 6 mm L/H Rear Tyre 195/55 R15 FALKEN 6 mm 4. Description of Damages THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS. 5. General Information Accident Date 04/07/2022 Inspection Date 08/07/2022 Survey held at AUBURN AUTO PTE LTD 176 SIN MING DRIVE #04-18 SIN MING AUTOCARE SINGAPORE 575721 5a. Remarks A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.	3.		Condition	ons of Tyres	_	
L/H Front Tyre 195/55 R15 ARIVO 4 mm R/H Rear Tyre 195/55 R15 FALKEN 6 mm L/H Rear Tyre 195/55 R15 FALKEN 6 mm 4. Description of Damages THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS. 5. General Information Accident Date 04/07/2022 Inspection Date 08/07/2022 Survey held at AUBURN AUTO PTE LTD 176 SIN MING DRIVE #04-18 SIN MING AUTOCARE SINGAPORE 575721 5a. Remarks A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			Size	Make	Balance	
R/H Rear Tyre 195/55 R15 FALKEN 6 mm L/H Rear Tyre 195/55 R15 FALKEN 6 mm 4. Description of Damages THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS. 5. General Information Accident Date 04/07/2022 Inspection Date 08/07/2022 Survey held at AUBURN AUTO PTE LTD 176 SIN MING DRIVE #04-18 SIN MING AUTOCARE SINGAPORE 575721 5a. Remarks A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.		R/H Front Tyre	195/55 R15	ARIVO	4 mm	
L/H Rear Tyre 195/55 R15 FALKEN 6 mm 4. Description of Damages THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS. 5. General Information Accident Date 04/07/2022 Inspection Date 08/07/2022 Survey held at AUBURN AUTO PTE LTD 176 SIN MING DRIVE #04-18 SIN MING AUTOCARE SINGAPORE 575721 5a. Remarks A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.		L/H Front Tyre	195/55 R15	ARIVO	4 mm	
4. Description of Damages THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS. 5. General Information Accident Date 04/07/2022 Inspection Date 08/07/2022 Survey held at AUBURN AUTO PTE LTD 176 SIN MING DRIVE #04-18 SIN MING AUTOCARE SINGAPORE 575721 5a. Remarks A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.		R/H Rear Tyre	195/55 R15	FALKEN	6 mm	
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS. 5. General Information Accident Date 04/07/2022 Inspection Date 08/07/2022 Survey held at AUBURN AUTO PTE LTD 176 SIN MING DRIVE #04-18 SIN MING AUTOCARE SINGAPORE 575721 5a. Remarks A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.		L/H Rear Tyre	195/55 R15	FALKEN	6 mm	
DAMAGES SEE DETAILS. 5. General Information Accident Date 04/07/2022 Inspection Date 08/07/2022 Survey held at AUBURN AUTO PTE LTD 176 SIN MING DRIVE #04-18 SIN MING AUTOCARE SINGAPORE 575721 5a. Remarks A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.	4.	Description of Damages				
5. General Information Accident Date 04/07/2022 Inspection Date 08/07/2022 Survey held at AUBURN AUTO PTE LTD 176 SIN MING DRIVE #04-18 SIN MING AUTOCARE SINGAPORE 575721 5a. Remarks A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.		THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
Accident Date 04/07/2022 Inspection Date 08/07/2022 Survey held at AUBURN AUTO PTE LTD 176 SIN MING DRIVE #04-18 SIN MING AUTOCARE SINGAPORE 575721 5a. Remarks A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.		DAMAGES SEE DETAILS.				
Survey held at AUBURN AUTO PTE LTD 176 SIN MING DRIVE #04-18 SIN MING AUTOCARE SINGAPORE 575721 5a. Remarks A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.	5.	General Information				
176 SIN MING DRIVE #04-18 SIN MING AUTOCARE SINGAPORE 575721 5a. Remarks A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.		Accident Date	04/07/2022	Inspection Date	08/07/2022	
#04-18 SIN MING AUTOCARE SINGAPORE 575721 5a. Remarks A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.		Survey held at	AUBURN AUTO PTE LTD			
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			#04-18 SIN MING AUTOCARE			
B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.	5a. Remarks					
		B)THE INSPECTIO	B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair	5b.					
ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days						