



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
HSBC LIFE (SINGAPORE) PTE LTD 10 MARINA BOULEVARD #48-01 MARINA BAY FINANCIAL CENTRE TOWER 2SINGAPORE 018983 ATTN:VALE			Ref: CC4/ASM22006510/Apa3q2 Date: 18/05/2023 Code: HSB	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SHD 3207K	Veh. Inspected	YQ 6773C	
Policy No.	P2465679	Coverage (\$)	0.00	
Claim No.	S2M0466J	Excess (\$)	0.00	
Assign From		Assign Date	07/07/2022	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	TOYOTA DYNA	c.c	2755	
Engine No.	HIDDEN	Year of Reg.	2022	
Chassis No.	JHHAGV4680K002219	Colour	SILVER	
Odometer	3766 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	175/75 R15	BRIDGESTONE	6 mm	
L/H Front Tyre	175/75 R15	BRIDGESTONE	6 mm	
R/H Rear Tyre	145/80 R13	BRIDGESTONE	6 mm	
L/H Rear Tyre	145/80 R13	BRIDGESTONE	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT & REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	07/07/2022	Inspection Date	08/07/2022	
Survey held at	HD PERFECT AUTOWORK PTE LTD 8 KAKI BUKIT AVENUE 4, #08-09, PREMIER @ KAKI BUKIT, SINGAPORE 415875			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		12 Working Days		