

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/GRB22006516/AGA3Q2**Date:** 17/03/2023REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0000447_01

Claimant Vehicle No : SKC292C **Insured Vehicle No :** SMH738J

Date of Loss: 06/07/2022 Nature of Claim: TP Claim No: MFL2022D0003565

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKC292C**
 Make & Model: LEXUS ES300H, 2.5 Executive (A) Engine No: A25AN237042
 Reg. Date: 27/11/2020 (Man. Year: 2020) Chassis No: JTHB21B1402119655
 Colour: White Odometer: 44886 km
 Engine Capacity: 2487 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/45 R18 Rear Tyre Size: 235/45 R18
 Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm
 Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,630.73	6,196.49	4,434.24	41.71
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,095.00	1,940.00	2,155.00	52.63
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	14,725.73	8,136.49	6,589.24	44.75
+ GST 7.00/7.00% (S\$)	1,030.80	569.55	461.25	44.75
Nett Amount (S\$)	15,756.53	8,706.04	7,050.49	44.75
+ Car Rental (8.0 x S\$120.00/day + 7.00% GST) (S\$)		1,027.20		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		9,740.69		

INSPECTION

Date of Assignment: 07/07/2022

Date Inspected: 07/07/2022 Inspected At: Autobacs Car Care (Singapore) Pte Ltd (HQ)
 8 Kaki Bukit Ave 4 #08-45/46 Premier@Kaki Bukit
 Singapore 415875

Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 08 Sep 2022)
Parts:	143	LEXUS ES300H 2.5 Executive (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKC292C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR DOOR RH	Dented	1,271.42 FL	*1,271.42 FL
2	1		*REAR DOOR BLACK TAPE TOP RH	Necessary	65.65 FL	*65.65 FL
3	1		*REAR DOOR BLACK TAPE FRONT RH	Necessary	61.39 FL	*61.39 FL
4	1		*REAR DOOR BLACK TAPE BLACK RH	Necessary	48.25 FL	*48.25 FL
5	1		*REAR DOOR STICKER RH	Necessary	42.59 FL	*42.59 FL
6	1		*REAR DOOR HYBRID EMBLEM RH	Necessary	91.55 FL	*91.55 FL
7	1		*REAR FENDER RH	Repair	1,683.00 FL	*- FL
8	1		*REAR FENDER STICKER RH	Necessary	58.31 FL	*58.31 FL
9	1		*REAR FENDER INNER SHIELD RH	Deformed	223.67 FL	*223.67 FL
10	1		*REAR FENDER INNER PANEL RH	Repair	454.00 FL	*- FL
11	1		*REAR BUMPER	Deformed	1,249.45 FL	*1,249.45 FL
12	1		*REAR BUMPER SIDE RETAINER RH	Not Necessary	188.00 FL	*- FL
13	1		*REAR BUMPER LOWER DIFFUSER WITH CHROME	Not Necessary	677.00 FL	*- FL
14	1		*ROCKER SIDE SKIRTING RH	Cracked	730.75 FL	*730.75 FL
15	1		*REAR 18 SPORT RIM RH (ORIGINAL)	Cut	2,941.96 FL	*2,941.96 FL
16	1		*REAR KNUCKLE ARM RH	Not Necessary	639.51 FL	*- FL
17	1		*REAR KNUCKLE ARM BEARING RH	Not Necessary	629.87 FL	*- FL
18	1		*REAR FENDER INNER SHIELD CLIPS SET RH	Necessary	60.00 FS	*30.00 FS
19	1		*SET REAR BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
20	1		*ROCKER SIDE SKIRTING CLIPS SET RH	Necessary	60.00 FS	*30.00 FS
21	1		*REAR 18 TYRE RH	Not Necessary	480.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	11,736.37	6,874.99
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,105.64	678.50
Total Parts (\$\$)	10,630.73	6,196.49

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE & REPLACED WITH PANEL BEATING ALL THE ACCIDENT PORTION	New	1,320.00	650.00
2	TO SPRAY PAINTING ALL THE ACCIDENT PORTION & POLISHING AFFECTED AREA	New	1,320.00	800.00
3	TO APPLY ANTI-RUST & TUFF KOTE	New	95.00	60.00
4	TO PERFORM LIGHTING & WIRING CHECK	New	80.00	30.00
5	TO DISMANTLE & REINSTALL REAR WINDSCREEN PERFORM	New	150.00	0.00
6	TO DISMANTLE & REPLACED REAR BUMPER REVERSE SENSOR WITH DISTANCE SETTING	New	120.00	60.00
7	TO DISMANTLE & REPLACED REAR UNDER CARRIAGE COMPONENT RH TO PERFORM FACILITATE REPAIRS	New	280.00	0.00
8	TO SEND VEHICLE FOR 3D COMPUTERISED TO PERFORM CHECK & ADJUSTED ALL WHEEL ALIGNMENT	New	100.00	80.00
9	TO PERFORM DIAGNOSTIC CHECK & RESET MEMORY FAULT CODE TO IDENTIFICATION STANDARD	New	380.00	180.00
10	TO DISMANTLE & REINSTALL INTERIOR CARPET WITH OTHER ATTACHMENT PARTS COMPONENT TO FACILITATE REPAIR	New	250.00	80.00
Gross Labour Cost (S\$)			4,095.00	1,940.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >