



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMG 3544L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	FRT BUMPER	TORN	635.70	635.70
1	FRT BUMPER REINFORCEMENT	NOT NECESSARY	228.10	-
1	FRT BUMPER SIDE RETAINER RH	DAMAGED	31.40	31.40
1	FRT BUMPER FOG LAMP COVER RH	NOT NECESSARY	69.90	-
1	HEADLAMP RH	CUT	689.70	689.70
1	HEADLAMP BRACKET RH	NOT NECESSARY	49.10	-
1	FRT FENDER COWLING RH	DEFORMED	134.90	134.90
	LESS 20% DISCOUNT		-367.76	-298.34
			1,471.04	1,193.36
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	SET FRT BUMPER CLIPS (SN)	NECESSARY	60.00	30.00
1	SET FRT FENDER COWLING CLIPS RH (SN)	NECESSARY	40.00	30.00
			100.00	60.00
	<b><u>LABOUR</u></b>			
	TO CHECK WIRING.		50.00	30.00
	TO SPRAY UNDERSEAL.	NOT NECESSARY	80.00	-
	(FRONT) TO SPRAY PAINTING.		700.00	400.00
	TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.		700.00	300.00
			1,530.00	730.00
	<b>GRAND TOTAL</b>		<b>3,101.04</b>	<b>1,983.36</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>1,550.00</b>

Report Ref No. CS/AGI22006518/Acy3m4

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.