

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/III22006532/APA3Q2**Date:** 08/12/2022REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D22MPC0002635
Claimant Vehicle No :	SLW9366Y	Insured Vehicle No :	SMQ5394L
Date of Loss:	07/07/2022	Nature of Claim:	TP
		Claim No:	MPC2022D0003640

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLW9366Y		
Make & Model:	HYUNDAI ELANTRA, 1.6 AD GLS (AMS) (A)	Engine No:	G4FGJU150297
Reg. Date:	10/03/2018 (Man. Year: 2018)	Chassis No:	KMHD841CMJU645461
Colour:	Silver	Odometer:	87505 km
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,040.88	4,799.84	5,241.04	52.20
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,830.00	2,070.00	2,760.00	57.14
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,870.88	6,869.84	8,001.04	53.80
Approved Total (Overridden) (S\$)		5,500.00		
Nett Amount (S\$)	14,870.88	5,500.00	9,370.88	63.01
+ Loss of Use (5.0 x S\$60.00/day) (S\$)		300.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		5,807.45		

INSPECTION

Date of Assignment:	08/07/2022	
Date Inspected:	08/07/2022 Inspected At:	HD Perfect Autowork Pte Ltd (HQ) 8 Kaki Bukit Ave 4, #08-09 Premier @ Kaki Bukit Singapore 415875
Estimated Period of Repair:	6.0 days	

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 07 Oct 2022)
Parts:	143	HYUNDAI ELANTRA 1.6 AD GLS (AMS) (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLW9366Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	757.40 FL	*495.00 FL
2	1		*REAR BUMPER DIFFUSER	Deformed	996.30 FL	*305.00 FL
3	1		*REAR BUMPER REFLECTOR	N/S Cracked	145.00 FL	*72.50 FL
4	2		*REAR BUMPER RETAINER	Not Necessary	114.60 FL	*- FL
5	1		*REAR BUMPER REINFORCEMENT	Dented	494.80 FL	*329.00 FL
6	5		*REAR BUMPER BRACKET	Bent	177.00 FL	*90.00 FL
7	1		*REAR BUMPER SIDE INNER GARNISH	N/S Torn	197.20 FL	*98.60 FL
8	2		*REAR FENDER INNER TRIM	Not Necessary	875.00 FL	*- FL
9	1		*REAR FENDER INNER COWLING	Not Necessary	146.80 FL	*- FL
10	1		*BOOTLID	Buckled	1,782.10 FL	*1,782.10 FL
11	2		*BOOTLID LAMP	Not Necessary	1,328.40 FL	*- FL
12	1		*BOOTLID LOGO	Necessary	59.60 FL	*59.60 FL
13	1		*BOOTLID EMBLEM ELANTRA	Necessary	62.80 FL	*62.80 FL
14	1		*BOOTLID EMBLEM GLS	Necessary	53.20 FL	*53.20 FL
15	1		*BOOTLID REVERSE CAMERA	Not Necessary	875.40 FL	*- FL
16	2		*BOOTLID HINGE	Not Necessary	188.60 FL	*- FL
17	2		*BOOTLID STOPPER	Not Necessary	38.40 FL	*- FL
18	1		*BOOTLID INSULATOR	Not Necessary	179.80 FL	*- FL
19	1		*BOOTLID TOP LOCK	Damaged	166.70 FL	*166.70 FL
20	1		*BOOTLID LOWER LOCK	Not Necessary	19.10 FL	*- FL
21	1		*BOOTLID WEATHERSTRIP	Cut	152.60 FL	*152.60 FL
22	2		*TAILLAMP	Cracked	1,753.60 FL	*1,196.00 FL
23	1		*REAR END PANEL	Dented	569.40 FL	*569.40 FL
24	1		*REAR END PANEL TOP GARNISH	Deformed	142.30 FL	*142.30 FL
25	1		*REAR NUMBER PLATE	Not Necessary	80.00 FS	*- FS
26	1		*SET REAR BUMPER CLIP	Necessary	80.00 FS	*30.00 FS
27	1		*SET REAR BUMPER EXHAUST COVER GARNISH CLIP	Not Necessary	30.00 FS	*- FS
28	1		*SET REAR BUMPER SIDE INNER GARNISH CLIP	Necessary	80.00 FS	*20.00 FS
29	1		*SET REAR FENDER INNER COWLING CLIP	Not Necessary	80.00 FS	*- FS
30	1		*SET REAR FENDER INNER TRIM CLIPS	Not Necessary	80.00 FS	*- FS
31	1		*SET BOOT LID INSULATOR CLIP	Not Necessary	80.00 FS	*- FS
32	1		*SET TAIL LAMP CLIP	Necessary	60.00 FS	*20.00 FS
33	1		*SET REAR END PANEL TOP GARNISH CLIPS	Necessary	80.00 FS	*10.00 FS
34	1		*REAR END PANEL SEALANT	Necessary	150.00 FS	*60.00 FS
35	1		*REVERSE SENSOR	Damaged	220.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	12,296.10	5,914.80
- List Item Discount on L Items 20.00/20.00% (\$\$)	2,255.22	1,114.96
Total Parts (\$\$)	10,040.88	4,799.84

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ,REMOVAL AND REPLACING PARTS	New	1,800.00	850.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,600.00	850.00
3	TUFF COAT	New	250.00	80.00
4	WIRING CHECK	New	180.00	30.00
5	REMOVE AND REFIX UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR	New	250.00	80.00
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	New	80.00	50.00
7	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE	New	80.00	50.00
8	REAR CHASSIS ALIGNMENT	New	250.00	0.00
9	TRANFER BOOTLID MECHANISM	New	80.00	80.00
10	CONDUCT WATER LEAKAGE TEST	New	80.00	0.00
11	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT /CONTROL UNITS RESET MEMORIES TO SPECIFICATION ETC	New	180.00	0.00
Gross Labour Cost (S\$)			4,830.00	2,070.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >