

Vehicle Damage Assessment Report for [SLW9366Y]

Estimate Created: 08/07/2022 07:33 by LKK_admin-a
(LKK_Auto_Consultants_Pte_Ltd)

Owned: 18/09/2022 10:57 by LKK_cs-a (LKK_Auto_Consultants_Pte_Ltd)

General Information

Insurance Company		Claim Number
Claim Type	TP	
Workshop	LKK_Auto_Consultants_Pte_Ltd	Reference Number

Vehicle Information

Brand	Hyundai	Model	Elantra
Engine Type			
License Plate Number	SLW9366Y	VIN (or Chassis #)	

Vehicle Condition

Damaged Diagram	Odometer	0.00 Km
	Tyres Condition	
	Front Left	mm
	Front Right	mm
	Rear Left	mm
	Rear Right	mm

Comments

- Final review base on information provided by LKK: Concluded the cost of repair at lump sum \$5,500.00 with 6 days for repair

Insurlogic 3 (18/09/2022 10:57)

Parts

Description	Number/Type	Qty	Cost	Markup/Disc.%	Sum
Rear Bumper		1	495.00	-20.00 %	396.00
Rear Bumper Diffuser		1	305.00	-20.00 %	244.00
Rear Bumper Reflector LH		1	72.50	-20.00 %	58.00
Rear Bumper Reinforcement		1	329.00	-20.00 %	263.20
Rear Bumper Bracket		5	18.00	-20.00 %	72.00
Rear Bumper Side Inner Garnish LH		1	98.60	-20.00 %	78.88
Bootlid		1	1782.10	-20.00 %	1,425.68
Bootlid Logo		1	59.60	-20.00 %	47.68
Bootlid Emblem 'Elantra'		1	62.80	-20.00 %	50.24
Bootlid Emblem 'GLS'		1	53.20	-20.00 %	42.56
Bootlid Top Lock		1	166.70	-20.00 %	133.36
Bootlid Weatherstrip		1	152.60	-20.00 %	122.08
Tail Lamp		1	1196.00	-20.00 %	956.80
Rear End Panel		1	569.40	-20.00 %	455.52
Rear End Panel Top Garnish		1	142.30	-20.00 %	113.84
Rear Bumper Clips Set		1	30.00	0.00 %	30.00
Rear Bumper Side Inner Garnish Clips Set		1	20.00	0.00 %	20.00
Tail Lamp Clips Set		1	20.00	0.00 %	20.00
Rear End Panel Top Garnish Clips Set		1	10.00	0.00 %	10.00
Rear End Panel Sealant		1	60.00	0.00 %	60.00
Reverse Sensor		1	200.00	0.00 %	200.00

Parts Subtotal 4,799.84

Labor**Replace/RnR**

Description	Type	Cost	Markup/Disc %	Price
To remove & refix rear damaged parts	RnR	850.00	0.00 %	850.00
Tuff-kote	RnR	80.00	0.00 %	80.00
Check wiring	RnR	30.00	0.00 %	30.00
RnR upholstery & roof lining	RnR	80.00	0.00 %	80.00
RnR reverse sensor	RnR	50.00	0.00 %	50.00
RnR reverse camera	RnR	50.00	0.00 %	50.00
Transfer bootlid mechanism	RnR	80.00	0.00 %	80.00

Paint

Description	Paint Type	Cost	Markup/Disc %	Price
To spray paint on the accident affected area	Full spray	850.00	0.00 %	850.00
Labor Rate	S\$ 50 / Hour			
			General Labor Subtotal	1,220.00
			Paint Labor Subtotal	850.00
			Labor Subtotal	2,070.00

Summary

Repair Cost	6,869.84
Discount(20 %)	(1,369.84)
	5,500.00
Excess	(0.00)
GST(0.00 %)	0.00
Grand Subtotal	5,500.00