

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22006534/AVY3Q2**Date:** 28/11/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00148372101	
Claimant Vehicle No :	SJK1128H	Insured Vehicle No :	SMN2711R	
Date of Loss:	25/06/2022	Nature of Claim:	TP	Claim No: SNM22D204503/C02/KHONGLH

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJK1128H		Engine No:	CZDC47062
Make & Model:	AUDI Q3, 1.4 TFSI (A)		Chassis No:	WAUZZZF38M1147604
Reg. Date:	28/10/2021 (Man. Year: 2021)		Odometer:	13037 km
Colour:	Black			
Engine Capacity:	1395 cc			
Market Value/New Car Price:	N/A			
Sum Insured (\$\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/55 R18	Rear Tyre Size:	235/55 R18
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,282.00	1,075.00	5,207.00	82.89
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,152.00	2,152.00	2,000.00	48.17
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	10,434.00	3,227.00	7,207.00	69.07
+ GST 7.00/7.00% (\$\$)	730.38	225.89	504.49	69.07
Nett Amount (\$\$)	11,164.38	3,452.89	7,711.49	69.07

INSPECTION

Date of Assignment:	21/11/2022	55 UBI ROAD 1 . SINGAPORE 408699 Repairer: Premium Automobiles Pte Ltd - Alexandra (HQ)
Date Inspected:	04/07/2022 Inspected At:	
Estimated Period of Repair:	3.0 days	

Adjuster: ADRIAN LING**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 28 Nov 2022)
Parts:	M1-SUV	AUDI Q3 1.4 TFSI (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJK1128H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	1,738.00 FS	*- FS
2	1		*REAR BUMPER FIXING PARTS	Not Necessary	220.00 FS	*- FS
3	1		*REAR BUMPER SPOILER	Deformed	510.00 FS	*510.00 FS
4	1		*REAR BUMPER TOWNG EYE	Not Necessary	48.00 FS	*- FS
5	1		*REAR BUMPER BRACKET	Not Necessary	53.00 FS	*- FS
6	1		*BOOT LID CONTROL UNIT	Not Necessary	454.00 FS	*- FS
7	1		*TAILGATE SENSOR LINE	Not Necessary	228.00 FS	*- FS
8	1		*AERIAL FOR KESSY	Not Necessary	79.00 FS	*- FS
9	2		*REAR LIGHT REFLECTOR -LH/RH	Not Necessary	92.00 FS	*- FS
10	1		*REAR BUMPER REINFORCEMENT BEAM	Not Necessary	693.00 FS	*- FS
11	1		*REAR BUMPER HOLDING STRAP -CENTER	Not Necessary	120.00 FS	*- FS
12	2		*REAR BUMPER GUIDE SECTION -LH/RH	Not Necessary	142.00 FS	*- FS
13	2		*REAR PARKING AID SENSOR	Not Necessary	530.00 FS	*- FS
14	4		*REAR PARKING AID SENSOR SEAL RING	Not Necessary	10.00 FS	*- FS
15	1		*SET REAR BUMPER WIRING	Not Necessary	449.00 FS	*- FS
16	2		*REAR WHEEL ARCH COVER -LH/RH	Necessary	566.00 FS	*565.00 FS
17	1		*SUNDRIES	Not Necessary	350.00 FS	*- FS
					Total Parts (S\$)	6,282.00 1,075.00

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR	New	360.00	360.00
2	TO DISMANTLE AND RENEW REAR BUMPER .TO REPAIR REAR END PANELLING .RE-ORGANIZE CRASH MANAGEMENT COMPONENTS .REINSTALL ALL PARTS REMOVED	New	1,600.00	800.00
3	TO RESPRAY REAR BUMPER AND REAR END PANELLING	New	2,000.00	800.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			4,152.00	2,152.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >