

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/CTI22006537/UVY3E2

**Date:** 02/08/2022

### REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00138042101  
Claimant Vehicle No: SMC4620P Insured Vehicle No: GBG8483B  
Date of Loss: 07/07/2022 Nature of Claim: TP Claim No: SNM22D204763/C02/CSC

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMC4620P  
Make & Model: HONDA FIT, 1.3 (A) Engine No: L13B1423983  
Reg. Date: 29/06/2018 (Man. Year: 2018) Chassis No: GK31320457  
Colour: White Odometer: 109981 km  
Engine Capacity: 1317 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): Market Value/New Car Price

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 185/65 R14 Rear Tyre Size: 185/65 R14  
Front Left Side: Maxxis 7 mm Rear Left Side: Maxxis 7 mm  
Front Right Side: Maxxis 7 mm Rear Right Side: Maxxis 7 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,111.84	7,550.48	2,561.36	25.33
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,160.00	3,680.00	3,480.00	48.60
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>17,271.84</b>	<b>11,230.48</b>	<b>6,041.36</b>	<b>34.98</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>1,209.03</b>	<b>786.13</b>	<b>422.90</b>	<b>34.98</b>
<b>Nett Amount (S\$)</b>	<b>18,480.87</b>	<b>12,016.61</b>	<b>6,464.26</b>	<b>34.98</b>

### INSPECTION

Date of Assignment: 28/07/2022  
Date Inspected: 12/07/2022 Inspected At: Specialists Motor Pte Ltd (HQ)  
Blk 3018A Ubi Road 1, #01-24/25/26  
Singapore 408711  
Estimated Period of Repair: 8.0 days

**Adjuster:** MARCUS CHUA

**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 01 Aug 2022)
<b>Parts:</b>	144	HONDA FIT 1.3 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SMC4620P)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*BONNET	Dented / Buckled	573.40 FL	*573.40 FL
2	1	*BONNET LOCK	Twisted	79.40 FL	*79.40 FL
3	2	*BONNET HINGE L & RH	Bent	97.80 FL	*97.80 FL
4	1	*BONNET INSULATION SHIELD WITH CLIPS	Not Necessary	98.60 FL	*- FL
5	1	*FRONT BUMPER FASCIA	Deformed / Torn	638.20 FL	*594.20 FL
6	1	*SET FRONT BUMPER CLIPS	Necessary	35.00 FL	*35.00 FL
7	2	*FRONT BUMPER SIDE RETAINER L & RH	Bent	49.80 FL	*49.80 FL
8	1	*FRONT BUMPER REINFORCEMENT BEAM	Repair	321.40 FL	*- FL
9	2	*HEADLAMP L & RH	Holder Cracked	1,596.80 FL	*1,596.80 FL
10	1	*FRONT SUPPORT PANEL	Repair	540.70 FL	*- FL
11	1	*FRONT GRILLE BASE	Cracked	354.20 FL	*354.20 FL
12	1	*FRONT GRILLE CHROME UPPER	Cracked	224.30 FL	*224.30 FL
13	1	*FRONT GRILLE CHROME LOWER	Cracked	282.40 FL	*282.40 FL
14	1	*FRONT GRILLE LOGO	Scratched	29.40 FL	*29.40 FL
15	1	*SET FRONT GRILLE CLIP	Not Necessary	35.00 FL	*- FL
16	1	*SET RADIATOR TOP GARNISH CLIPS	Not Necessary	35.00 FL	*- FL
17	1	*REAR BOOT COVER	Badly Dented	851.40 FL	*851.40 FL
18	2	*REAR BOOT COVER DAMPER L & RH	Not Necessary	256.80 FL	*- FL
19	1	*REAR BOOT COVER WINDSCREEN	Shattered	808.30 FL	*808.30 FL
20	1	*REAR BOOT COVER WINDSCREEN MOULDING	Necessary	240.30 FL	*110.00 FL
21	1	*REAR BOOT COVER NUMBER PLATE LAMP GARNISH WITH	Cracked	266.40 FL	*266.40 FL
22	1	*REAR BOOT COVER LOCK	Dented / Jammed	92.30 FL	*92.30 FL
23	1	*REAR BOOT COVER LATCH	Not Necessary	36.40 FL	*- FL
24	1	*REAR BOOT COVER OPENING SWITCH	Not Necessary	153.40 FL	*- FL
25	1	*REAR BOOT COVER FIT EMBLEM	Necessary	38.90 FL	*38.90 FL
26	1	*REAR BOOT COVER INNER BOARD COVER	Deformed / Warped	128.40 FL	*128.40 FL
27	1	*REAR BOOT COVER WIPER ARM	Cut	88.90 FL	*88.90 FL
28	1	*REAR BOOT COVER WIPER ARM MOTOR	Bent / Jammed	145.70 FL	*145.70 FL
29	1	*REAR BOOT COVER WIPER BLADE	Not Necessary	49.20 FL	*- FL
30	2	*REAR BOOT COVER LAMP L & RH	Not Necessary	196.40 FL	*- FL
31	1	*REAR END PANEL	Badly Dented	399.40 FL	*345.20 FL
32	1	*REAR END PANEL INNER GARNISH	Twisted	65.60 FL	*65.60 FL
33	1	*REAR FLOOR PANEL	Repair	850.30 FL	*- FL
34	1	*REAR BUMPER FASCIA	Distorted	509.70 FL	*509.70 FL
35	1	*SET REAR BUMPER CLIPS	Necessary	35.00 FL	*35.00 FL
36	2	*REAR BUMPER LOWER GARNISH L & RH	Cracked	92.40 FL	*92.40 FL
37	1	*REAR BUMPER LOWER GARNISH (CENTRE)	Bent	68.40 FL	*68.40 FL
38	2	*TAIL LAMP L & RH	Cracked / Broken	722.80 FL	*722.80 FL
39	1	*SET REAR BUMPER SENSOR	Shorted	380.00 FS	*200.00 FS
40	1	*REAR BOOT COVER WINDSCREEN SEALANT	Necessary	60.00 FS	*40.00 FS
41	1	*REAR NUMBER PLATE WITH HOLDER	Scratched	50.00 FS	*40.00 FS
42	1	*REAR END PANEL SEALER	Necessary	80.00 FS	*50.00 FS
43	1	*REAR FLOOR PANEL SEALANT	Not Necessary	80.00 FS	*- FS
44	1	*BOOT COVER HOLDER SWITCH	Cracked	103.20 FL	*103.20 FL
45	1	*BOOT COVER W/STRIP	Twisted	92.30 FL	*92.30 FL

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
46	1		*REAR FLOOR PANEL TOOLS SPONGE	Deformed	146.20 FL	*146.20 FL
47	1		*TAIL LAMP HOUSING PANEL RH	Dented	95.50 FL	*95.50 FL
48	1		*REAR FLOOR PANEL TOP BOARD	Warped	258.50 FL	*258.50 FL
49	1		*BOOT COVER INNER HOLDER	Twisted	19.80 FL	*19.80 FL
50	1		*TAIL LAMP GROMMET	Necessary	6.00 FL	*6.00 FL
51	1		*REAR BUMPER SIDE SPACER	Cracked	18.00 FL	*18.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>12,477.30</b>	<b>9,355.60</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$)</b>	2,365.46	1,805.12
<b>Total Parts (\$)</b>	<b>10,111.84</b>	<b>7,550.48</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	CUT OUT, RENEW, KNOCKING & WELDING FRONT BONNET, FRONT SUPPORT PANEL, REMOVE & INSTALL FRONT DAMAGE AND REALIGN BODY	New	1,080.00	500.00
2	SPRAY PAINTING ON FRONT DAMAGE PARTS	New	1,280.00	700.00
3	CUT OUT, RENEW, KNOCKING & WELDING REAR BOOT COVER, REAR END PANEL, REAR FLOOR PANEL, REMOVE & INSTALL REAR DAMAGE PARTS, STRAIGHTEN AND RE-ALIGN CHASSIS	New	2,200.00	1,100.00
4	REMOVE & INSTALL REAR WINDSCREEN GLASS	New	120.00	120.00
5	REMOVE & REFIX REAR BUMPER SENSOR	New	80.00	50.00
6	TUFF-KOTE ON FRONT & REAR DAMAGE PARTS	New	160.00	90.00
7	SPRAY PAINTING ON REAR DAMAGE PARTS	New	2,180.00	1,100.00
8	CHECK ALL LIGHTING AFTER REPAIRS	New	60.00	20.00
<b>Gross Labour Cost (\$\$)</b>			<b>7,160.00</b>	<b>3,680.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >