

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22006538/KQY3M4**Date:** 22/03/2023**REFERENCE**Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMHCSNA00013442100

**Claimant Vehicle
No :** SNC457J**Insured Vehicle
No :** SMD3996G

Date of Loss: 26/06/2022

Nature of Claim: TP

Claim
No: SNM22D204745C02/IRENE**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **SNC457J**

Make & Model: HONDA FREED HYBRID, 1.5 7-SEATER G (A)

Engine No: LEB7238892

Reg. Date: 27/09/2021 (Man. Year: 2020)

Chassis No: GB73132638

Colour: Metallic Black

Odometer: 0 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/65R15

Rear Tyre Size: 185/65R15

Front Left Side: Dunlop 7 mm

Rear Left Side: Davanti 9 mm

Front Right Side: Dunlop 7 mm

Rear Right Side: Davanti 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	23,529.80	18,812.56	4,717.24	20.05
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	6,900.00	4,970.00	1,930.00	27.97
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	30,440.80	23,793.56	6,647.24	21.84
Approved Total (Overridden) (\$\$)		18,750.00		
(\$\$)	30,440.80	18,750.00	11,690.80	38.41
+ GST 8.00/8.00% (\$\$)	2,435.26	1,500.00	935.26	38.40
Nett Amount (\$\$)	32,876.06	20,250.00	12,626.06	38.41

INSPECTION

Date of Assignment: 08/07/2022

Date Inspected: 08/07/2022 Inspected At:

COMFORTDELGRO ENGINEERING PTE LTD
205 BRADDELL ROAD
SINGAPORE 579701

Estimated Period of Repair: 21.0 days

Adjuster: KENNETH KONG**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 22 Mar 2023)
Parts:	M1-MPV	HONDA FREED HYBRID 1.5 7-SEATER G (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNC457J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT RH FENDER	Repair	441.00 FL	*- FL
2	1		*FRT RH FENDER INNER SHIELD	Serviceable	150.00 FL	*- FL
3	8		*FRT RH FENDER INNER SHIELD CLIP	Not Necessary	31.20 FL	*- FL
4	1		*FRT LH FENDER	Buckled	441.00 FL	*441.00 FL
5	1		*FRT LH FENDER INNER SHIELD	Cracked	150.00 FL	*150.00 FL
6	8		*FRT LH FENDER INNER SHIELD CLIP	Necessary	31.20 FL	*31.20 FL
7	1		*FRT LH FENDER HYBRID BADGE	Necessary	66.00 FL	*66.00 FL
8	1		*FRT LH QUATER GLASS	Serviceable	510.00 FL	*- FL
9	1		*FRT LH FENDER LOWER PANEL(OUTER)	Bent	191.00 FL	*191.00 FL
10	1		*FRT LH FENDER LOWER PANEL(INNER)	Bent	210.00 FL	*210.00 FL
11	1		*FRT LH FENDER LOWER PANELSUPPORT BRACKET	Bent	150.00 FL	*150.00 FL
12	1		*FRT LH WHEEL HUB	Bent	201.00 FL	*201.00 FL
13	1		*FRT LH WHEEL HUB BEARING	Necessary	196.00 FL	*196.00 FL
14	1		*FRT LH KUNCKLE ARM	Bent	351.00 FL	*351.00 FL
15	1		*FRT LH LOWER ARM	Bent	291.00 FL	*291.00 FL
16	1		*FRT LH SHOCK ABSORBER	Bent	350.00 FL	*350.00 FL
17	1		*FRT LH SHOCK ABSORBER TOP MOUNTING	Serviceable	48.00 FL	*- FL
18	1		*LH STEERING TIE ROD	Serviceable	121.00 FL	*- FL
19	1		*LH STEERING TIE ROD END	Serviceable	99.00 FL	*- FL
20	1		*FRT WINDSCREEN GLASS	Cracked	1,800.00 FL	*1,800.00 FL
21	1		*FRT WINDSCREEN GLASS MOULDING	Necessary	60.00 FL	*60.00 FL
22	1		*AIRBAG CONTROL UNIT	Necessary	854.00 FL	*854.00 FL
23	1		*FRT AIR BAG CRASH SENSOR LH	Necessary	104.00 FL	*104.00 FL
24	1		*FRT AIR BAG CRASH SENSOR RH	Necessary	104.00 FL	*104.00 FL
25	1		*FRT BUMPER	Cracked	898.00 FL	*898.00 FL
26	1		*FRT BUMPER SIDE RETAINER RH	Cracked	22.00 FL	*22.00 FL
27	1		*FRT BUMPER SIDE RETAINER LH	Cracked	22.00 FL	*22.00 FL
28	10		*FRT BUMPER CLIP	Necessary	38.00 FL	*38.00 FL
29	1		*RADIATOR GRILLE	Cracked	982.00 FL	*982.00 FL
30	1		*FRT BUMPER UPPER AIRDUCT	Serviceable	36.00 FL	*- FL
31	1		*FRT BUMPER LOWER CENTER GRILLE	Cracked	165.00 FL	*165.00 FL
32	1		*FRT BUMPER RH SIDE COVER	Missing	241.00 FL	*241.00 FL
33	1		*FRT BUMPER LH SIDE COVER	Missing	241.00 FL	*241.00 FL
34	1		*FRT BUMPER LOWER GRILLE COVER RH	Serviceable	91.00 FL	*- FL
35	1		*FRT BUMPER LOWER GRILLE COVER LH	Missing	89.00 FL	*89.00 FL
36	1		*FRT BUMPER INFORCEMENT	Bent	332.00 FL	*332.00 FL
37	1		*RH HEADLAMP	Cut	1,454.00 FL	*1,454.00 FL
38	1		*RH HEADLAMP LOWER BRACKET	Cracked	36.00 FL	*36.00 FL
39	1		*LH HEADLAMP	Mtg Cracked	1,454.00 FL	*1,454.00 FL
40	1		*LH HEADLAMP LOWER BRACKET	Serviceable	36.00 FL	*- FL
41	1		*WIPER TANK	Mtg Cracked	90.00 FL	*90.00 FL
42	1		*FRT SUPPORT PANEL TOP	Repair	753.00 FL	*- FL
43	1		*FRT RH FENDER LOWER PANEL(OUTER)	Bent	191.00 FL	*191.00 FL
44	1		*FRT RH FENDER LOWER PANEL(INNER)	Repair	210.00 FL	*- FL
45	1		*FRT RH FENDER LOWER SUPPORT BRACKET	Repair	150.00 FL	*- FL
46	1		*FRT RH FENDER INNER SHIELD	Serviceable	120.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*STEERING WHEEL AIRBAG	Burst	2,400.00 FL	*2,400.00 FL
48	1		*STEERING WHEEL AIRBAG CLOCK SPRING	Necessary	283.00 FL	*283.00 FL
49	1		*FRT LH PASSENGER AIRBAG	Burst	3,201.00 FL	*3,201.00 FL
50	1		*FRT DASHBOARD	Torn	750.00 FL	*750.00 FL
51	1		*FRT RH SEAT BELT	Jammed	602.00 FL	*602.00 FL
52	1		*FRT LH SEAT BELT	Jammed	602.00 FL	*602.00 FL
53	1		*REAR RH FENDER	Bent	912.00 FL	*912.00 FL
54	1		*REAR BUMPER	Repair	950.00 FL	*- FL
55	1		*REAR RH BUMPER RETAINER	Serviceable	25.00 FL	*- FL
56	1		*AIR FILTER RESONATOR	Repeated	112.00 FL	*- FL
57	1		*FRT BUMPER UNDER RUBBER	Repeated	75.00 FL	*- FL
58	1		*FRT BUMPER TOW COVER	Repeated	15.40 FL	*- FL
59	1		*LH DRIVESHAFT	Repeated	1,105.00 FL	*- FL
60	1		*FRT LH ABSORBER BEARING	Not Necessary	36.70 FL	*- FL
61	1		*SOLAR FILM	Repeated	300.00 FL	*- FL
62	1		*AIR INTAKE RESONATOR	Dented	112.00 F	*112.00 F
63	1		*ENGINE UNDERCOVER	Cracked	75.00 F	*75.00 F
64	1		*FRT BUMPER TOW COVER	Missing	15.40 F	*15.40 F
65	1		*REAR BUMPER CLIPS	Necessary	38.00 F	*38.00 F
66	1		*LHF DRIVE SHAFT	Bent	1,105.00 F	*1,105.00 F
67	1		*STRG RING PIECE 2 OF 2	Necessary	216.00 F	*216.00 F
68	1		*FRT LH RIM 15	Cracked	401.00 FS	*401.00 FS
69	1		*FRT LH TYRE9DUNLOP ENASAVE EC300/185/65R15 (70%)	Punctured	250.00 FS	*175.00 FS
70	1		*SEALANT	Necessary	40.00 FS	*40.00 FS
71	1		*INNER SEAL	Necessary	30.00 FS	*30.00 FS
72	1		*ERP BRACKET	Necessary	26.00 FS	*26.00 FS
73	1		*PHV	Necessary	50.00 FS	*40.00 FS
74	1		*FRT NUMBER PLATE	Missing	45.00 FS	*45.00 FS
75	1		*DECAL	Necessary	50.00 FS	*50.00 FS
76	1		*SOLAR FILM	Not Insured	300.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	28,723.90	22,923.60
- List Item Discount on L Items 20.00/20.00% (\$\$)	5,194.10	4,111.04
Total Parts (\$\$)	23,529.80	18,812.56

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	OT/TP CASE (INSURER)	11.00	11.00
Sub Total (\$\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CUT WELD FRT PANEL,JACK STRAIGHTEN FRT CHASSIS,CUT FENDER LOWER PANEL,REPLACE DAMAGE PARTS AND REALIGN AFFECTED AREAS	New	1,300.00	1,000.00
2	TO PUTTY,RESPRAY ON FRT BONNET,FRT BUMPER,BOTH FENDER,CHASSIS FRAME,FRT LH DOOR AND AFFECTED AREAS	New	1,500.00	1,250.00
3	REMOVE RADIATOR AND CONDENSOR TO ASSIST REPAIR AND REPLACE }	New	150.00	100.00
4	TO VACCUM AND RECHARGE AIRCON GAS }	New	80.00	0.00
5	TO REMOVE FRT WINDSCREEN GLASS TO ASSIST REPAIR AND REPLACE	New	120.00	120.00
6	REMOVE FRT DASHBOARD TO ASSIST REPAIR AND REPLACE	New	250.00	250.00
7	TO REPLACE STEERING AIRBAG ,CLOCK SPRING,PASSENGER AIRBAG AND SRS CONTROL UNIT	New	400.00	280.00
8	TO REMOVE AND REPLACE BOTH FRT SEAL BELT	New	200.00	80.00
9	TO RESET AND RE-PROGRAM ECU/AIRBAG SYSTEM	New	400.00	280.00
10	TO CUT WELD ON REAR RH FENDER AND REPLACEMENT.REPLACE REAR BUMPER AND REALIGN AFFECTED AREAS	New	1,000.00	750.00
11	TO PUTTY,RESPRAY ON RH REAR FENDER ,RR BUMPER AND AFFECTED AREAS	New	800.00	500.00
12	TO REMOVE INTERIOR UPHOLSTERY TO ASSIST REPAIR AND REFIT	New	150.00	100.00
13	TO DISMANTLE FRT LH SUSPENSION TO ASSIST REPAIR AND REPLACE.(RIM,TYRE,KUNCKLE ARM,LOWER ARM,ABSORBER ETC.)	New	300.00	200.00
14	TO CHECK AND ADJUST WHEEL ALIGNMENT	New	100.00	60.00
15	TO TUFF KOTE ON REAR AFFECTED AREAS	New	150.00	0.00
Gross Labour Cost (\$\$)			6,900.00	4,970.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >