

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG22006542/DVY3E2**Date:** 01/12/2022REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	1001481237
Claimant Vehicle No :	SNB8218K	Insured Vehicle No :	YK3288M
Date of Loss:	08/07/2022	Nature of Claim:	TP
		Claim No:	278618

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SNB8218K	Engine No:	A25A5613726
Make & Model:	TOYOTA CAMRY, 2.5 HYBRID (A)	Chassis No:	JTNB23HK403101255
Reg. Date:	26/07/2021 (Man. Year: 2021)	Odometer:	33423 km
Colour:	White		
Engine Capacity:	2487 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/45 R18	Rear Tyre Size:	235/45 R18
Front Left Side:	Giti 5 mm	Rear Left Side:	Giti 5 mm
Front Right Side:	Giti 5 mm	Rear Right Side:	Giti 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	29,362.72	4,596.21	24,766.51	84.35
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,850.00	1,720.00	4,130.00	70.60
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	35,212.72	6,316.21	28,896.51	82.06
Approved Total (Overridden) (\$\$)		5,000.00		
(\$\$)	35,212.72	5,000.00	30,212.72	85.80
+ GST 7.00/7.00% (\$\$)	2,464.89	350.00	2,114.89	85.80
Nett Amount (\$\$)	37,677.61	5,350.00	32,327.61	85.80

INSPECTION

Date of Assignment: 08/07/2022

Date Inspected: 12/07/2022 Inspected At:

JWG International Pte Ltd (HQ)
 Blk 10, Ang Mo Kio Ind Park 2A,, #03-08 AMK
 AutoPoint
 Singapore 568047

Estimated Period of Repair: 4.0 days

Adjuster: BRYAN TANI**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 01 Dec 2022)
Parts:	143	TOYOTA CAMRY 2.5 HYBRID (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNB8218K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Bent / Dented	1,853.10 FL	*1,288.30 FL
2	1		*BOOTLID BLUE LOGO	Necessary	280.20 FL	*130.20 FL
3	1		*BOOTLID TOYOTA EMBLEM	Necessary	100.76 FL	*100.76 FL
4	1		*BOOTLID LAMP LH / RH	O/S Smashed/N/SNotNecessary	1,445.96 FL	*542.70 FL
5	1		*BOOTLID HYBRID EMBLEM	Necessary	121.40 FL	*92.00 FL
6	2		*BOOTLID NO. PLATE LAMP LH / RH	Not Necessary	378.20 FL	*- FL
7	1		*BOOTLID CENTER GARNISH	Mtg Cracked	791.49 FL	*330.95 FL
8	1		*BOOTLID CAMRY EMBLEM	Cracked	82.30 FL	*82.30 FL
9	2		*BOOTLID HINGE LH / RH	Not Necessary	436.38 FL	*- FL
10	1		*BOOTLID INNER TRIM	Not Necessary	645.00 FL	*- FL
11	1		*BOOTLID INNER TRIM HANDLE	Not Necessary	299.00 FL	*- FL
12	1		*BOOTLID WEATHER STRIP	Serviceable	342.51 FL	*- FL
13	1		*BOOTLID LOCK	Damaged	386.81 FL	*305.90 FL
14	1		*BOOTLID STRIKER LOCK	Repair	98.41 FL	*- FL
15	1		*BOOTLID ELECTRIC SWITCH	Not Necessary	582.82 FL	*- FL
16	1		*SET BOOTLID STOPPERS	Not Necessary	124.12 FL	*- FL
17	1		*TAIL LAMP LH / RH	O/S MtgCracked/N/SNotNecessary	4,051.60 FL	*705.70 FL
18	2		*TAIL LAMP LOWER BRACKET LH / RH	Not Necessary	533.56 FL	*- FL
19	2		*TAIL LAMP PANEL LH / RH	Not Necessary	1,060.20 FL	*- FL
20	1		*REAR BUMPER	Distorted	1,620.80 FL	*742.20 FL
21	2		*REAR BUMPER SIDE RETAINER LH / RH	Serviceable	267.80 FL	*- FL
22	2		*REAR BUMPER SENSOR	Damaged	742.60 FL	*464.00 FL
23	1		*SET REAR BUMPER SENSOR HOLDER	Serviceable	100.40 FL	*- FL
24	1		*REAR BUMPER SENSOR WIRE HARNESS	Not Necessary	2,272.10 FL	*- FL
25	2		*REAR BUMPER REFLECTOR LH / RH	Not Necessary	578.20 FL	*- FL
26	1		*REAR BUMPER LOWER GARNISH	Cut / Distorted	820.58 FL	*466.10 FL
27	1		*REAR BUMPER SPONGE	Torn	1,039.70 FL	*138.20 FL
28	1		*REAR BUMPER REINFORCEMENT BAR	Bent / Dented	1,039.70 FL	*520.20 FL
29	1		*REAR END PANEL	Repair	1,480.80 FL	*- FL
30	1		*REAR END PANEL TOP GARNISH	Serviceable	282.10 FL	*- FL
31	1		*SPARE TYRE PANEL	Not Necessary	1,998.36 FL	*- FL
32	1		*SPARE TYRE PANEL TOP BOARD	Not Necessary	472.00 FL	*- FL
33	1		*REAR EXHAUST PIPE	Not Necessary	1,891.20 FL	*- FL
34	1		*REAR EXHAUST MOUNTING	Not Necessary	95.70 FL	*- FL
35	1		*REAR EXHAUST HEAT SHIELD	Not Necessary	285.20 FL	*- FL
36	2		*REAR FENDER LH / RH	Not Necessary	3,852.20 FL	*- FL
37	2		*REAR FENDER INNER SHIELD LH / RH	Not Necessary	778.20 FL	*- FL
38	2		*REAR FENDER AIR DUCT LH / RH	Not Necessary	218.38 FL	*- FL
39	2		*REAR FENDER INNER TRIM LH / RH	Not Necessary	2,185.02 FL	*- FL
40	1		*REAR WINDSCREEN MOULDING	Not Necessary	342.10 FL	*- FL
41	1		*KEYLESS SENSOR	Cracked / Broken	280.00 FL	*172.10 FL
42	1		*REAR WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS

Report was unsubmitted during this print-out.

12/1/22, 1:19 PM				Adjuster Report			
No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
43	1		*REAR WINDSCREEN DAMPING SEAL	Not Necessary	30.00 FS	*- FS	
44	1		*BOOTLID CENTER GARNISH CLIPS	Necessary	50.00 FS	*15.00 FS	
45	1		*REAR BUMPER CLIPS	Necessary	50.00 FS	*20.00 FS	
46	1		*REAR END PANEL SEALANT	Not Necessary	80.00 FS	*- FS	
47	1		*REAR END PANEL TOP GARNISH CLIPS	Not Necessary	50.00 FS	*- FS	
48	1		*REAR FENDER SEALANT	Not Necessary	80.00 FS	*- FS	
49	1		*REAR FENDER INNER TRIM CLIPS	Not Necessary	50.00 FS	*- FS	
50	1		*BOOTLID ELECTRONIC OPEN / CLOSE	Not Necessary	600.00 FS	*- FS	
51	1		*BOOTLID ELECTRONIC DAMPER	Not Necessary	1,000.00 FS	*- FS	
52	1		*REAR NO. PLATE & CASING	Not Necessary	100.00 FS	*- FS	
F=Franchise part. S=SpcNett. L=ListItemDisc.							
					Sub Total (S\$)	38,426.96	6,116.61
					- List Item Discount on L Items 25.00/25.00% (S\$)	9,064.24	1,520.40
					Total Parts (S\$)	29,362.72	4,596.21
Report was unsubmitted during this print-out.							

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ALL INTERIOR UPHOLSTERLY ITEMS TO FACILIATE REPAIRS	New	300.00	0.00
2	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS	New	2,000.00	700.00
3	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS	New	2,000.00	700.00
4	TO TUFF COAT DAMAGED AREAS	New	200.00	40.00
5	TO RNR BOOTLID MECHANISM TO FACILITATE REPAIRS	New	200.00	60.00
6	TO RNR REAR BUMPER SENSOR TO FACILITATE REPAIRS	New	150.00	40.00
7	TO RNR REAR WINDSCREEN TO FACILITATE REPAIRS	New	300.00	0.00
8	TO CHECK & RE-FIX ALL ELECTRICAL WIRINGS	New	200.00	30.00
9	TO RNR REAR EXHAUST & ATTACHMENT PARTS TO FACILITATE REPAIRS	New	200.00	0.00
10	TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS. RESET ALL MEMORIES TO FACTORY DEFAULT SETTINGS	New	300.00	150.00
Gross Labour Cost (S\$)			5,850.00	1,720.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >