



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SINGAPORE PRISON SERVICE
OC FINANCE & ADMIN CLUSTER A
980, UPPER CHANGI ROAD NORTH SINGAPORE
507708

Ref: CS/SPS22006546/Gqy3m4

Date: 19/07/2022

Code: SPS

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLIDING GATE	Veh. Inspected	YQ 997M
Policy No.		Coverage (\$)	0.00
Claim No.	6000105465	Excess (\$)	0.00
Assign From	NG TIONG CHOON	Assign Date	08/07/2022

2. Vehicle Particulars & Condition

Make & Model	ISUZU FSR90SUQCC	c.c	5193
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	JALFSR907J7000042	Colour	WHITE
Odometer	-	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	265/70 R19.5	BRIDGESTONE	6 mm
L/H Front Tyre	265/70 R19.5	BRIDGESTONE	6 mm
R/H Rear Tyre	265/70 R19.5	BRIDGESTONE	6 mm
L/H Rear Tyre	265/70 R19.5	BRIDGESTONE	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	03/01/2022	Inspection Date	07/07/2022
Survey held at	15 WOODLANDS LINK SINGAPORE 738726		
Repairer	SYSTEMATIC AIRCONDITIONING PTE LTD		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------