



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
SINGAPORE PRISON SERVICE OC FINANCE & ADMIN CLUSTER A 980, UPPER CHANGI ROAD NORTHSINGAPORE 507708		Ref: CS/SPS22006546/Gqy3m4 Date: 05/08/2022 Code: SPS	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SLIDING GATE	Veh. Inspected	YQ 997M
Policy No.		Coverage (\$)	0.00
Claim No.	6000105465	Excess (\$)	0.00
Assign From	NG TIONG CHOON	Assign Date	08/07/2022
2. Vehicle Particulars & Condition			
Make & Model	ISUZU FSR90SUQCC	c.c	5193
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	JALFSR907J7000042	Colour	WHITE
Odometer	-	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	265/70 R19.5	BRIDGESTONE	6 mm
L/H Front Tyre	265/70 R19.5	BRIDGESTONE	6 mm
R/H Rear Tyre	265/70 R19.5	BRIDGESTONE	6 mm
L/H Rear Tyre	265/70 R19.5	BRIDGESTONE	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	03/01/2022	Inspection Date	07/07/2022
Survey held at	15 WOODLANDS LINK SINGAPORE 738726		
Repairer	SYSTEMATIC AIRCONDITIONING PTE LTD		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	