

COMFORT TRANSPORTATION PTE LTD

REPAIR ESTIMATE

Vehicle No. : SHC3782X

Make : HYUNDAI

Model : IONIQ(G3)

Date: 21.06.2022

Insurance: NTUC

MVA: MS. LOKE YY

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	REAR BUMPER COVER			\$459.40
10	REAR BUMPER CLIPS			\$22.00
1	REAR BUMPER CENTRE MOULDING ASSY			\$451.25
1	REAR BUMPER REINFORCEMENT			\$394.80
2	REAR BUMPER REINFORCEMENT BRACKET LH RH		138.1	\$276.20
1	REAR BUMPER FOG LAMP			\$201.50
1	REAR BUMPER LICENCE LAMP			\$85.30
1	ANTENNA ASSY SMARTKEY			\$40.50
2	REAR BUMPER SIDE BRACKET LH RH		\$55.80	\$111.60
1	REAR BUMPER LOWER CTR MOULDING			\$155.00
1	EMBLEM HYBRID			\$24.30
1	EMBLEM - IONIQ			\$31.30
1	REAR BUMPER TOWING COVER			\$98.80
1	REAR BUMPER CENTER UNDER COVER			\$225.00
			1213.25	
			970.60	
	SUB TOTAL			\$2,576.95
	LESS 20%			\$515.39
	DISCOUNTED TOTAL			\$2,061.56
	REAR NUMBER PLATE WITH TRIM COVER		-10%	\$55.00
	BOOTLID COMFORT TEL NO STICKER		-10%	\$40.00
	BOOTLID COMFORT LOGO STICKER		-10%	\$30.00
	BOOTLID COMFORT APP STICKER		-10%	\$30.00
	REAR BUMPER REVERSE SENSOR		-10%	\$180.00
				\$335.00
	Labour Charge			
	PANEL BEATING			\$750.00
	SPRAY PAINTING CHARGE			\$600.00
	CHK ALL LIGHTING			\$60.00
	TUFF KOTE			\$60.00
	REMOVE/REFIX REVERSE SENSOR			\$80.00
			2182.10	
			1/3 \$1750	
			2 days	
	TOTAL LABOUR			\$1,550.00
	ESTIMATE TOTAL			\$3,946.56

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quotation will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

- LLK Auto Consultants hence notify the Repairer that the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tanpin 97485449
 21/6/22 2:50pm
 ~ 2 days
 1/3 Repair after repair
 tanpin@llkauto.com