

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 2787P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	TO REPAIR SEE LABOUR	459.40	-
2	REAR BUMPER SIDE BRACKET LH / RH @\$55.80	NOT NECESSARY	111.60	-
1	REAR BUMPER REINFORCEMENT	NOT NECESSARY	394.80	-
1	REAR BUMPER CENTRE MOULDING	NOT NECESSARY	451.25	-
1	TOW COVER	NOT NECESSARY	98.80	-
2	NUMBER PLATE LAMP LH / RH @\$85.30	NOT NECESSARY	170.60	-
1	REAR FOG LAMP	NOT NECESSARY	210.50	-
1	REAR SMART ANTENNA	NOT NECESSARY	40.50	-
10	REAR BUMPER CLIPS @\$2.20	NOT NECESSARY	22.00	-
	LESS 20% DISCOUNT		-391.89	-
			1,567.56	-
	NETT ITEMS			
1	REAR NUMBER PLATE W/HOLDER (N)	NOT NECESSARY	55.00	-
1	REAR REVERSE SENSOR (N)	NOT NECESSARY	180.00	-
	LESS 10% DISCOUNT		-23.50	-
			211.50	-
	SPECIAL NETT ITEMS			
2	REAR FENDER ADVERTISEMENT (SN)	NOT NECESSARY	200.00	-
			200.00	-
	<u>LABOUR</u>			
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF REAR BUMPER.		600.00	350.00
	SPRAY PAINTING CHARGE.		300.00	250.00
	CHECK LIGHTING AND WIRING.	NOT NECESSARY	60.00	-
	TUFF COATING.	NOT NECESSARY	60.00	-
	REMOVE / REFIX REVERSE SENSOR.		60.00	30.00
			1,080.00	630.00
	GRAND TOTAL		3,059.06	630.00

Report Ref No. NS/INC22006551/Tqce2





Page No.:2 of 2

RECOMMENDED COST OF REPAIRS (CONFIRMED) 630.00

Report Ref No. NS/INC22006551/Tqce2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser