

OMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO SHC2787P

16.06.2022

MAKE REG 30.10.2019

CHIANG/NTUC

MODEL IONIQ G3

Qty	Parts Description/ Labour	Type	Amount
1	REAR BUMPER		\$459.40 <i>20</i>
2	REAR BUMPER SIDE BRACKET LH/RH		\$55.80 \$111.60 <i>X</i>
1	REAR BUMPER REINFORCEMENT		\$394.80 <i>X</i>
1	REAR BUMPER CENTRE MOULDING		\$451.25 <i>X</i>
1	TOW COVER		\$98.80 <i>X</i>
2	NUMBER PLATE LAMP LH/RH		\$85.30 \$170.60 <i>X</i>
1	REAR FOG LAMP		\$210.50 <i>X</i>
1	REAR SMART ANTENNA		\$40.50 <i>X</i>
10	REAR BUMPER CLIPS		\$2.20 \$22.00 <i>X</i>
	SUB TOTAL		\$1,959.45
	20.00%		\$391.89
	DISCOUNTED TOTAL		\$1,567.56
2	REAR FENDER ADVERTISEMENT		\$200.00 <i>X</i>
1	REAR NUMBER PLATE W/HOLDER		\$55.00 <i>X</i>
1	REAR REVERSE SENSOR		\$180.00 <i>X</i>
			\$411.50
	Labour Charge		
	Panel Beating		350 \$600.00
	Spray Painting Charge		250 \$300.00
	Check Lighting and Wiring		<i>un</i> \$60.00
	Tuff Coating		<i>un</i> \$60.00
	Remove/refix Reverse sensor		30 \$60.00
	TOTAL LABOUR		\$1,080.00
	ESTIMATE TOTAL		\$3,059.06
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.			

Tanf'lin 97495749
 WP 22/6/22C430
 4/5 Busy after repair
 2 days
 Tanf'lin @ 11h and 12h

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: