

TYCAB PTE LTD

## REPAIR ESTIMATE\*

VEHICLE NO SHC2993R

22.06.2022

MAKE REG 06.08.2019

CHIANG/NTUC

MODEL IONIQ G2

Qty	Parts Description/ Labour	Type	Amount
1	REAR BUMPER		\$459.40
2	REAR BUMPER SIDE BRACKET LH/RH		\$55.80 \$111.60
1	REAR BUMPER REINFORCEMENT		\$394.80
1	REAR BUMPER CENTRE MOULDING		\$451.25
1	REAR BUMPER CENTRE LOWER MOULDING		\$155.00
1	TOW COVER		\$98.80
2	NUMBER PLATE LAMP LH/RH		\$85.30 \$170.60
1	REAR FOG LAMP		\$210.50
1	REAR SMART ANTENNA		\$40.50
10	REAR BUMPER CLIPS		\$2.20 \$22.00
	<b>SUB TOTAL</b>		<b>\$2,114.45</b>
	<b>20.00%</b>		<b>\$422.89</b>
	<b>DISCOUNTED TOTAL</b>		<b>\$1,691.56</b>
1	REAR NUMBER PLATE W/HOLDER		\$55.00
1	REAR REVERSE SENSOR		\$180.00
			<b>\$211.50</b>
	<b>Labour Charge</b>		
	Panel Beating		\$600.00
	Spray Painting Charge		\$300.00
	Check Lighting and Wiring		\$60.00
	Tuff Coating		\$60.00
	Remove/refix Reverse sensor		\$60.00
	<b>TOTAL LABOUR</b>		<b>\$1,080.00</b>
	<b>ESTIMATE TOTAL</b>		<b>\$3,194.56</b>
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.			

Tang Hui 97495749

WP 22/6/22 @ 440

4/5 hrs after repair

02 days

Tang Hui @ 11:40 am