

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO SHD4254S

29.06.2022

MAKE 24.07.2019 REG DATE

CHIANG/NTUC

MODEL IONIQ G 2

Qty	Parts Description/ Labour	Type	Amount
1	REAR BUMPER		\$459.40
1	REAR BUMPER CENTRE MOULDING		\$451.25
1	REAR BUMPER REINFORCEMENT		\$394.80
1	REAR BUMPER UNDER MOULDING		\$155.00
1	REAR BUMPER BRACKET LH / RH	RHX	\$55.80
10	REAR BUMPER COVER CLIPS		\$22.00
1	REAR FOG LAMP		\$201.50
1	TAIL LAMP LH		\$935.40
1	REAR NUMBER PLATE LAMP		\$170.60
1	REAR BUMPER REFLECTOR LH		\$41.45
	SUB TOTAL	1923.85	\$2,943.00
	20.00%		\$588.60
	DISCOUNTED TOTAL	1539.08	\$2,354.40
1	REAR NUMBER PLATE W/HOLDER	UC old damage	\$55.00
1	REAR REVERSE SENSOR		\$180.00
			\$211.50
	Labour Charge		
	Panel Beating	630 350	\$550.00
	Spray Painting Charge	250	\$300.00
	Tuff Kote		\$90.00
	Remove/refix Reverse sensor	30	\$60.00
	TOTAL LABOUR	2169.08	\$1,000.00
		4154.75	
	ESTIMATE TOTAL	2 days	\$3,565.90

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Tanphir 97475749
 WP 30/6/22 @ 330 pm
 1/5 Repair after repair
 Tanphir e/Chuan
 2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: