

ASS. REC. BY: Taufikh

REF: NS/ INL 22006564/Tvc

**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: \_\_\_\_\_  
 at Workshop m/s \_\_\_\_\_  
 of \_\_\_\_\_  
 Insured: **SLX 2110J**  
 Policy No. \_\_\_\_\_  
 Claims No. **MT/1178013-002**  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

Veh No: **5H8948X** Yr Regn: **206, Dec**  
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or \_\_\_\_\_  
 Make: **Hyundai 140** c.c. **1685**  
 Colour: **Blue** A/C: Insured / Std / NI / NA  
 Sp. Reading: **598211** T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: **KMMLB414M14097066**  
 Gen. Cond: **Good** / Fair / Poor / Burnt  
 Steering: **In order** / Jammed / Leaked / Burnt or \_\_\_\_\_  
 Brake: **In order** / Jammed / Leaked / Burnt or \_\_\_\_\_  
 Modi: **G** Nil / S/Rim / STD A/Rim or \_\_\_\_\_  
 Tyre Size: F: **205/60R14**  
 R: **14**  
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or **Wet Make**  
 Front R/Bal. **6** mm Rear R/Bal. **6** mm  
 L/Bal. **6** mm L/Bal. **6** mm  
 D.O.A. **25/6/2022** D.O.I. **28/6/22**  
 Survey held at **Confort Guyon**  
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or  
**Frt o/s**  
 The U/C / Chassis frame / Body Structure affected due to collision.

N/S	O/S

(Policy Condition)  
 Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Rport: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: \_\_\_\_\_ days Res.: Yes or No  
 Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No  
 CA / REV / REP. / 24 HRS **W/P**  
 Date: \_\_\_\_\_ Person Contacted: **Wj pokor** Vehicle: IN / OUT

Date / Time	Action / Instruction
30/8/22	Taufikh confirmed LS \$2450 (Red 888, 26%)

**TK Auto Consultants** hence notify the Reporter of the following:

- To remedy damaged parts (tyres, wheels, suspension, etc.)
- To remedy damaged parts (tyres, wheels, suspension, etc.)
- To remedy damaged parts (tyres, wheels, suspension, etc.)
- To remedy damaged parts (tyres, wheels, suspension, etc.)

Date/Time, File Pass to?  : Prell. Report  
 : Final Report  
 Date/Time, File Return to? \_\_\_\_\_

Days Of Repair: **2**  
 Resurvey No. of Trip: **1**

Add Fee:  : Site Insp (\$ \_\_\_\_\_)  
 : Interview (\$ \_\_\_\_\_)  
 : Tech. Invs (\$ \_\_\_\_\_)  
 : Weekend (\$ \_\_\_\_\_)

Survey Fee:	
Transportation:	
\$ + RS. \$:	
Photos	
Others	
TOTAL	

Report Format: **TP**  
 Lump Sum / L.S. (\$ **\$2450**)

COMFORTDELGRO ENGINEERING PTE LTD

Effective Date: 1 Nov 2020

REPAIR ESTIMATE

✓ SAS-KIV → see attached.

LKK -

DATE: 28.06.2022

INSURANCE: NTUC (LIS)

MODEL: Hyundai i40

MVA: LIM T S

VEHICLE NO.: SH 8948X

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
	Front Bumper	1		\$ 1,052.20
	Front Bumper Clips	10	\$ 2.20	\$ 22.00
	Front Bumper Side Bracket RH	1		\$ 22.40
	Front Fender RH	1		\$ 663.00
	Front Fender Shield RH	1		\$ 174.90
	HeadLamp RH	1		\$ 1,388.00
	<b>SUB TOTAL</b>			\$ 3,322.50
	<b>LESS 20%</b>			\$ 664.50
	<b>DISCOUNTED TOTAL</b>			<b>\$ 2,658.00</b>
	<u>Labour Charge</u>			
	Panel Beating			\$ 300.00
	Spray Painting Charge			\$ 300.00
	Check Lightings			\$ 40.00
	Tuff Kote			\$ 40.00
	<b>TOTAL LABOUR</b>			<b>\$ 680.00</b>
	<b>ESTIMATE TOTAL</b>			<b>\$ 3,338.00</b>

de ✓  
na  
?  
A ✓  
duo ✓  
280  
250  
30  
30

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Tanpin 97495749  
 up 28/6/22 @ 430pm  
 2/3 Resury after repair  
 2 days  
 Tanpin @ Akhambon

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplemental item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

Team: ARC Repair TP(CLS0)1

**JOB CARD** Sales Order: 4327289

JC NO 305521341

Customer Name: COMFORT TRANSPORTATION PTE LTD  
Customer No: 7010045  
Address: 383 SIN MING DRIVE  
Singapore SINGAPORE 575717  
Phone: (R) 65508755 (P) (O)

REGN NO.: <b>SH 8948X</b>	MILEAGE
MAKE: <b>HYUNDAI</b>	FUEL E.....1/2.....F
MODEL <b>I-40</b>	DATE/TIME IN <b>25.06.2022 15:35</b>
YR OF MANU. <b>15.12.2016</b>	TARGET DATE
CHASSIS CODE <b>KMHLB41UMHU097066</b>	COMPLETION DATE/TIME:


Document Card No.

JOB DESCRIPTION

Accident Date: 25.06.2022  
Nature: 3P 25.06.2022/C

Job No: 00010  
Labor Code: PB

DESCRIPTION  
PANEL BEATING-SH 8948X-TP



Checked & Passed Out By: \_\_\_\_\_

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Identification Slip

Exit Pass

Vehicle No.: SH 8948X

LIMITS

Vehicle No.: SH 8948X

Service Advisor

Signature/Date

Name of Service Advisor

Date

Returned to Service Reception upon collection

To be kept by Security Guard