



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 2551M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRT FENDER LH	TO REPAIR SEE LABOUR	588.80	-
1	FRT FENDER SHIELD LH	NOT NECESSARY	164.70	-
1	FRT FENDER BLUE-DRIVE LH	NECESSARY	26.60	26.60
1	FRT WHEEL CAP LH	CUT	346.40	346.40
1	HEADLAMP LH	CUT	1,993.65	1,993.65
1	FRT BUMPER	DEFORMED	481.10	481.10
1	FRT BUMPER UPPER MOULDING	TO REPAIR SEE LABOUR	368.50	-
1	FRT BUMPER SIDE BRACKET LH	NOT NECESSARY	35.00	-
10	FRT BUMPER CLIPS @\$2.20	NECESSARY	22.00	22.00
	LESS 20% DISCOUNT		-805.35	-573.95
			3,221.40	2,295.80
<u>SPECIAL NETT ITEMS</u>				
1	FRT FENDER ADV.STICKER LH (SN)	CUT	100.00	100.00
			100.00	100.00
<u>LABOUR</u>				
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF FRT FENDER LH AND FRT BUMPER UPPER MOULDING.		800.00	350.00
	SPRAY PAINTING CHARGE.		600.00	500.00
	CHECK LIGHTINGS.		60.00	30.00
	TUFF KOTE.	NOT NECESSARY	60.00	-
	WHEEL ALIGNMENT.		120.00	80.00
			1,640.00	960.00
GRAND TOTAL			4,961.40	3,355.80

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			2,700.00
---	--	--	-----------------

Report Ref No. NS/INC22006566/Tqce2



MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor



K.K.LAU CPT(RET)

**BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE**

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.