

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT AXA INSURANCE PTE LTD Ref: CS3/ASM22006567/Vqy3m4 8 SHENTON WAY #24-01 AXA TOWER Date: 26/08/2022 SINGAPORE 068811 ATTN: KHOR SAW THENG Code: ASM 1. Policy Particulars :- (THIRD PARTY CLAIM) Insured Veh. SHC 1589B GBH 5151Z Veh. Inspected Policy No. VFX/P2419138 Coverage (\$) 0.00 Claim No. S2M0465M Excess (\$) 0.00 KHOR SAW THENG **Assign Date** 12/07/2022 Assign From **Vehicle Particulars & Condition** 2. TOYOTA HIACE Make & Model 2982 c.c 2018 HIDDEN Engine No. Year of Reg. JTFHT02P700243509 WHITE Chassis No. Colour Odometer 185998 KM Steering IN ORDER **IN ORDER** SPORTS RIM **Brakes** Modification GOOD General 3. **Conditions of Tyres** Size Make **Balance** R/H Front Tyre 195 R15C TRAVIA 5 mm TRAVIA L/H Front Tyre 195 R15C 5 mm 195 R15C TRAVIA R/H Rear Tyre 5 mm TRAVIA L/H Rear Tyre 195 R15C 5 mm 4. **Description of Damages** THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. 5. **General Information** 05/07/2022 26/07/2022 (12:00 PM) Inspect Date / Time Accident Date KIM SENG TECK MOTOR WORKS Survey held at BLK 3021A UBI ROAD 1 #01-42 SINGAPORE 408715 5a. Remarks A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000-\$4,000

Report Ref No. CS3/ASM22006567/Vqy3m4

Estimate Days of Repair

Inspected By

B

5b.

THEVAN THOMAS KARTHIKESAVAN

ESTIMATED NORMAL PERIOD FOR REPAIR:

K.K.LAU CPT(RET)

Asst. Automotive Assessor

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser

5 Working Days