

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22006571/UPA3Q2**Date:** 11/11/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100442030
Claimant Vehicle No :	SKZ8286Y	Insured Vehicle No :	SKX4487X
Date of Loss:	09/07/2022	Nature of Claim:	TP
		Claim No:	5584949813SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKZ8286Y	Engine No:	L15B4026667
Make & Model:	HONDA VEZEL, 1.5 X CVT (A)	Chassis No:	RU11106663
Reg. Date:	04/02/2016 (Man. Year: 2015)	Odometer:	296245 km
Colour:	Grey		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Sumitomo 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Sumitomo 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,534.60	5,578.40	6,956.20	55.50
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,070.00	1,550.00	520.00	25.12
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,604.60	7,128.40	7,476.20	51.19
Approved Total (Overridden) (S\$)		5,700.00		
(S\$)	14,604.60	5,700.00	8,904.60	60.97
+ GST 7.00/7.00% (S\$)	1,022.32	399.00	623.32	60.97
Nett Amount (S\$)	15,626.92	6,099.00	9,527.92	60.97
+ Loss of Use (6.0 x S\$70.00/day) (S\$)		420.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		6,521.00		
Global Sum Settlement (S\$)		6,500.00		

INSPECTION

Date of Assignment:	12/07/2022	
Date Inspected:	12/07/2022	Inspected At: Fastech Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay Singapore 417883
Estimated Period of Repair:	4.0 days	

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed / Torn	985.20 F	*762.40 FL
2	1		*FRONT BUMPER LOWER	Not Necessary	650.00 F	*- FL
3	1		*FRONT BUMPER SIDE RETAINER O/S	Cracked	66.50 F	*66.50 FL
4	1		*SET FRONT BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
5	1		*HEADLAMP O/S	Cracked	1,959.20 F	*1,929.10 FL
6	1		*FRONT FENDER O/S	Bent	788.10 F	*545.20 FL
7	1		*FRONT FENDER OUTER PROTECTOR O/S	Distorted	388.50 F	*280.40 FL
8	1		*FRONT FENDER INNER SHIELD O/S	Torn	315.10 F	*192.50 FL
9	1		*SET FRONT FENDER INNER SHIELD CLIPS O/S	Necessary	50.00 F	*50.00 FL
10	1		*FRONT DOOR O/S	Repair	1,109.20 F	*- FL
11	1		*FRONT DOOR MIRROR ASSY O/S	Not Necessary	850.00 F	*- FL
12	1		*FRONT SHOCK ABSORBER O/S	Bent	655.10 F	*398.20 FL
13	1		*FRONT KNUCKLE ARM O/S	Bent	599.20 F	*544.30 FL
14	1		*FRONT KNUCKLE ARM BEARING O/S	Necessary	350.00 F	*266.20 FL
15	1		*FRONT LOWER ARM O/S	Bent	588.20 F	*588.20 FL
16	1		*BONNET	Repair	1,280.30 F	*- FL
17	1		*FRONT SPORT RIM O/S	Warped	1,100.00 FS	*600.00 FS
18	1		*ROCKER PANEL GARNISH O/S	Torn	750.00 F	*550.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	12,534.60	6,823.00
- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00	1,244.60
Total Parts (\$\$)	12,534.60	5,578.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	50.00	20.00
2	TO SPRAY RUST PROOFING	New	80.00	30.00
3	TO CONDUCT WHEEL ALIGNMENT	New	120.00	80.00
4	TO DISMANTLE & REPLACED FRONT UNDER CARRIAGE	New	200.00	120.00
5	TO RESET & REPROGRAMME SYSTEM	New	120.00	0.00
6	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	600.00	500.00
7	TO PUTTY & SPRAY PAINTING	New	900.00	800.00
Gross Labour Cost (\$\$)			2,070.00	1,550.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >