

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III22006573/UPA3Q2**Date:** 21/12/2022REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D22MFL0000491
Claimant Vehicle No :	SKP8836M	Insured Vehicle No :	SJL8285K
Date of Loss:	09/07/2022	Nature of Claim:	TP
		Claim No:	MFL2022D0003666

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKP8836M		
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 CVT (A)	Engine No:	1ZRY102278
Reg. Date:	26/09/2014 (Man. Year: 2014)	Chassis No:	MR053REH104516977
Colour:	White	Odometer:	67168 km
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,448.02	7,111.15	3,336.87	31.94
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,780.00	3,780.00	2,000.00	34.60
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,228.02	10,891.15	5,336.87	32.89
Approved Total (Overridden) (S\$)		8,700.00		
Nett Amount (S\$)	16,228.02	8,700.00	7,528.02	46.39
+ Car Rental (15.0 x S\$100.00/day) (S\$)		1,500.00		
+ Doc/Search Fee (S\$)		38.45		
+ Other Costs (S\$)		120.00		
Nett Liability (S\$)		10,358.45		
Global Sum Settlement (S\$)		10,300.00		

INSPECTION

Date of Assignment:	12/07/2022	
Date Inspected:	12/07/2022	Inspected At: Zoom Autowerks Pte Ltd (Bedok) 130 Bedok Reservoir Road, #08-1339 Singapore 470130
Estimated Period of Repair:	12.0 days	

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 24 Aug 2022)
Parts:	143	TOYOTA COROLLA ALTIS 1.6 CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKP8836M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN MOULDING	Necessary	156.80 FL	*110.80 FL
2	1		*REAR BOOT LID	Buckled	985.70 FL	*985.70 FL
3	2		*REAR BOOT HINGES	Repair	171.40 FL	*- FL
4	1		*REAR BOOT INNER TRIM	Not Necessary	188.50 FL	*- FL
5	1		*SET REAR BOOT INNER TRIM CLIP	Not Necessary	50.00 FL	*- FL
6	2		*REAR BOOT LAMPS	Cracked	577.40 FL	*577.40 FL
7	1		*REAR BOOT LOCK	Twisted	100.80 FL	*100.80 FL
8	1		*REAR BOOT LOCK CATCH	Not Necessary	60.30 FL	*- FL
9	1		*REAR BOOT LOGO	Necessary	89.70 FL	*89.70 FL
10	1		*REAR BOOT RUBBER	Twisted	145.70 FL	*145.70 FL
11	1		*REAR BOOT COROLLA EMBLEM	Necessary	80.30 FL	*80.30 FL
12	1		*REAR BOOT ALTIS EMBLEM	Necessary	75.70 FL	*75.70 FL
13	1		*REAR BOOT OUTER CHROME MOULDING	Cracked	288.50 FL	*288.50 FL
14	2		*REAR TAILLAMPS	Cracked	760.20 FL	*760.20 FL
15	2		*REAR TAILLAMP PANELS	Repair	775.40 FL	*- FL
16	1		*REAR END PANEL	Badly Dented	777.40 FL	*777.40 FL
17	1		*REAR END PANEL INNER GARNISH	Twisted	200.30 FL	*200.30 FL
18	1		*REAR KEYLESS SENSOR	Cracked	185.20 FL	*185.20 FL
19	1		*REAR BUMPER	Distorted	688.70 FL	*581.10 FL
20	2		*REAR BUMPER TOP BRACKETS	Cracked	181.80 FL	*181.80 FL
21	2		*REAR BUMPER SIDE BRACKETS	Bent	97.00 FL	*97.00 FL
22	2		*REAR BUMPER REFLECTORS	Not Necessary	120.20 FL	*- FL
23	1		*REAR BUMPER REINFORCEMENT	Bent	344.70 FL	*344.70 FL
24	2		*REAR BUMPER REINFORCEMENT STAYS	Bent	161.00 FL	*161.00 FL
25	2		*REAR BUMPER SIDE RETAINERS	Bent	130.00 FL	*130.00 FL
26	2		*REAR BUMPER PDC SENSORS	Cracked	390.00 FL	*390.00 FL
27	2		*REAR NUMBER PLATE LAMPS	Not Necessary	96.00 FL	*- FL
28	1		*REAR SPARE TYRE BOARD	Torn	363.50 FL	*363.50 FL
29	1		*REAR SPARE TYRE PANEL	Crumpled / Buckled	1,100.70 FL	*1,100.70 FL
30	1		*REAR EXHAUST SILENCER	Repair	881.70 FL	*- FL
31	2		*REAR EXHAUST MOUNTINGS	Not Necessary	97.20 FL	*- FL
32	1		*REAR FENDERS	N/S Repair / O/S Buckled	2,241.40 FL	*1,120.70 FL
33	1		*REAR FENDER AIR GATE	Not Necessary	87.50 FL	*- FL
34	1		*REAR FENDER INNER SHIELDS	N/S Torn	249.20 FL	*124.60 FL
35	1		*REAR FENDER INNER TRIMS	N/S Torn	670.80 FL	*335.40 FL
36	1		*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
37	1		*SET REAR BUMPER CLIP	Necessary	50.00 FS	*50.00 FS
38	1		*REAR NUMBER PLATE WITH HOLDER	Bent	50.00 FS	*40.00 FS
39	2		*SET REAR FENDER INNER TRIM CLIPS	Not Necessary	90.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	13,840.70	9,438.20
- List Item Discount on L Items 25.00/25.00% (\$)	3,392.68	2,327.05
Total Parts (\$)	10,448.02	7,111.15

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ,REPLACE DAMAGED LAMPS AND CHECK UP REAR WIRING	New	80.00	30.00
2	TO REMOVE AND REFIT INNER GARNISHES	New	150.00	80.00
3	TO REMOVE AND REFIT REAR REVERSE SENSOR	New	150.00	50.00
4	TO TRANSFER BOOT LID MECHANISM AND WIRING ASSEMBLY	New	120.00	60.00
5	TO REMOVE AND REFIT FUEL TANK ASSEMBLY WITH ALL ATTACHMENTS	New	150.00	60.00
6	TO REMOVE AND REFIT REAR WINDSCREEN GLASS	New	180.00	120.00
7	TO REMOVE ,REFIT AND REPLACE EXHAUST SILENCER AND MOUNTINGS	New	150.00	60.00
8	TO APPLY UNDERCOATING	New	200.00	120.00
9	PANEL BEATING	New	2,400.00	2,000.00
10	TO RE-SPRAY PAINTING ON THE AFFECTED AREAS	New	2,200.00	1,200.00
Gross Labour Cost (S\$)			5,780.00	3,780.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >