

Vehicle Damage Assessment Report for [SKP8836M]

Estimate Created: 12/07/2022 06:06 by LKK_admin-a
(LKK_Auto_Consultants_Pte_Ltd)

Owned: 30/07/2022 03:33 by LKK_cs-a (LKK_Auto_Consultants_Pte_Ltd)

General Information

Insurance Company	III	Claim Number
Claim Type	TP	
Workshop	LKK_Auto_Consultants_Pte_Ltd	Reference Number

Vehicle Information

Brand	Toyota	Model	Corolla
Engine Type			
License Plate Number	SKP8836M	VIN (or Chassis #)	

Vehicle Condition

Damaged Diagram	Odometer	0.00 Km
	Tyres Condition	
	Front Left	mm
	Front Right	mm
	Rear Left	mm
	Rear Right	mm

Comments

- Final review base on information provided by LKK : Concluded the cost of repair at lump sum \$8700.00 with 12 days for repair

Insurlogic 1 (30/07/2022 03:30)

Parts

Description	Number/Type	Qty	Cost	Markup/Disc. %	Sum
REAR WINDSCREEN MOULDING		1	110.80	-25.00 %	83.10
REAR BOOTLID		1	985.70	-25.00 %	739.28
REAR BOOT LAMPS		1	577.40	-25.00 %	433.05
REAR BOOT LOCK		1	100.80	-25.00 %	75.60
REAR BOOT LOGO		1	89.70	-25.00 %	67.28
REAR BOOT RUBBER		1	145.70	-25.00 %	109.28
REAR BOOT COROLLA EMBLEM		1	80.30	-25.00 %	60.23
REAR BOOT ALTIS EMBLEM		1	75.70	-25.00 %	56.78
REAR BOOT OUTER CHROME MOULDING		1	288.50	-25.00 %	216.38
TAIL LAMPS R/L		1	760.20	-25.00 %	570.15
END PANEL		1	777.40	-25.00 %	583.05
END PANEL INNER GARNISH		1	200.30	-25.00 %	150.23
REAR KEYLESS SENSOR		1	185.20	-25.00 %	138.90
REAR BUMPER		1	581.10	-25.00 %	435.83
REAR BUMPER TOP BRACKETS L/R		1	181.80	-25.00 %	136.35
REAR BUMPER SIDE BRACKETS L/R		1	97.00	-25.00 %	72.75
REAR BUMPER REINFORCEMENT		1	344.70	-25.00 %	258.53
REAR BUMPER REINFORCEMENT STAYS L/R		1	161.00	-25.00 %	120.75
REAR BUMPER SIDE RETAINERS L/R		1	130.00	-25.00 %	97.50
REAR BUMPER PDC SENSORS		1	390.00	-25.00 %	292.50
REAR SPARE TYRE BOARD		1	363.50	-25.00 %	272.63
REAR SPARE TYRE PANEL		1	1100.70	-25.00 %	825.53
REAR FENDER LH		1	1120.70	-25.00 %	840.53
REAR FENDER INNER SHIELD		1	124.60	-25.00 %	93.45
REAR FENDER INNER TRIM LH		1	335.40	-25.00 %	251.55

Parts Subtotal 6,981.21

Materials

Description	Number/Type	Qty	Cost	Markup/Disc.%	Sum
REAR WINDSCREEN SEALANT		1.0	40.00	0.00 %	40.00
CLIPS		1.0	50.00	0.00 %	50.00
REAR NUMBER PLATE WITH HOLDER		1.0	40.00	0.00 %	40.00

Materials Subtotal 130.00

Labor

Replace/RnR

Description	Type	Cost	Markup/Disc %	Price
CHECK WIRING	RnR	30.00	0.00 %	30.00
REMOVE AND REFIX INERIOR GAARNISH	RnR	80.00	0.00 %	80.00
REMOVE AND REFIX REVERSE SENSORS	RnR	50.00	0.00 %	50.00
TRANSFER BOOTLID MECHNISM	RnR	60.00	0.00 %	60.00
REMOVE AND REFIX FUEL TANK	RnR	60.00	0.00 %	60.00
REMOVE AND REFIX REAR WINDSCREEN	RnR	120.00	0.00 %	120.00
REMOVE AND REFIX REAR EXHAUST SILENCER	RnR	60.00	0.00 %	60.00
APPLY UNDERCOATING	RnR	120.00	0.00 %	120.00
REPLACE REAR BOOTLID	RnR	100.00	0.00 %	100.00
REPLACE REAR BUMPER	RnR	100.00	0.00 %	100.00
REPLACE REAR END PANEL	RnR	400.00	0.00 %	400.00
REPLACE REAR FLOOR	RnR	400.00	0.00 %	400.00
REPLACE REAR FENDER RH	RnR	400.00	0.00 %	400.00

Repair

Description	Severity	Cost	Markup/Disc %	Price
REAR FENDER LH	Unknown	250.00	0.00 %	250.00
REAR CHASSIS MEMBER	Unknown	250.00	0.00 %	250.00
REPAIR AND ADJUST REAR DOOR LH	Unknown	100.00	0.00 %	100.00

Paint

Description	Paint Type	Cost	Markup/Disc %	Price
REAR PORTION AND AFFECTED AREA	Full spray	1200.00	0.00 %	1,200.00

Labor Rate S\$ 50 / Hour

General Labor Subtotal 2,580.00

Paint Labor Subtotal 1,200.00

Labor Subtotal 3,780.00

Summary

Repair Cost 10,891.21

Discount(20 %)	(2,191.15)
	8,700.06
Excess	(0.00)
GST(0.00 %)	0.00
Grand Subtotal	8,700.06