LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG22006575/AGCY3E2

19/09/2022 Date:

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: 1002008407

Claimant Vehicle SJP2984U Insured Vehicle No: SFB9393A No:

Date of Loss: 08/07/2022 Nature of Claim: TP Claim No: 278708

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJP2984U**

Make & Model: TOYOTA COROLLA ALTIS, 1.6 (A) Engine No: 3ZZ4869555

Reg. Date: 18/03/2009 (Man. Year: 2009) Chassis No: MR053ZEE106141643

Colour: Odometer: Gold 182677 km

Engine Capacity: 1598 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Engine Modification: Pre-accident Condition: Yes No

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15 Front Left Side: Rear Left Side: Michelin 6 mm Michelin 6 mm Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		4,414.67	1,157.82	3,256.85	73.77
Miscellaneous Items		0.00	0.00	0.00	
Labour		2,200.00	1,270.00	930.00	42.27
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	6,614.67	2,427.82	4,186.85	63.30
	Approved Total (Overridden) (S\$)		1,950.00		
	(S\$)	6,614.67	1,950.00	4,664.67	70.52
	+ GST 7.00/7.00% (S\$)	463.03	136.50	326.53	70.52
	Nett Amount (S\$)	7,077.70	2,086.50	4,991.20	70.52

INSPECTION

Date of Assignment: 12/07/2022

Date Inspected: 19/07/2022 Inspected At: Blk 3023A Ubi Road 1, #01-61 & #01-58

Modern Automotive Pte Ltd (HQ)

Singapore 408717

Estimated Period of Repair: 4.0 days

Adjuster: XING GUO QIANG Manager: **CELINE FONG**

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 06 Sep 2022)

Parts: 143 TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SJP2984U)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	576.10 FL	*576.10 FL
2	1		*SET REAR BUMPER CLIPS	Necessary	30.00 FL	*30.00 FL
3	1		*REAR BUMPER SIDE HOLDER - LH & RH	O/S Damaged	70.40 FL	*35.20 FL
4	1		*REAR BUMPER SPONGE	Cracked	138.20 FL	*138.20 FL
5	1		*REAR BUMPER IMPACT BRACKET - LH & RH	O/S Dented	171.20 FL	*85.60 FL
6	2		*REAR BUMPER REFLECTOR - LH & RH	Not Necessary	88.60 FL	*- FL
7	1		*REAR END PANEL	Repair	708.40 FL	*- FL
8	1		*REAR END PANEL TOP GARNISH	Not Necessary	192.50 FL	*- FL
9	1		*REAR END PANEL LOCK SENSOR	Not Necessary	158.00 FL	*- FL
10	1		*BOOTLID	Repair	794.10 FL	*- FL
11	1		*BOOTLID LOCK	Not Necessary	1,898.00 FL	*- FL
12	1		*BOOTLID WEATHERSTRIP	Not Necessary	195.40 FL	*- FL
13	1		*TOYOTA LOGO	Necessary	45.90 FL	*45.90 FL
14	1		*1.6 EMBLEM	Necessary	42.10 FL	*42.10 FL
15	1		*COROLLA EMBLEM	Necessary	49.90 FL	*49.90 FL
16	1		*ALTIS EMBLEM	Necessary	48.50 FL	*48.50 FL
17	1		*REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS
18	1		*REAR END PANEL SEALANT	Not Necessary	60.00 FS	*- FS
19	1		*BOOTLID REFLECTOR LH	Cracked	225.60 FL	*225.60 FL
F=Fra	anchise p	art. S=SpcN	ett. L=ListItemDisc.	_		
				Sub Total (S\$)	5,772.90	1,477.10
			- List Item Discount on L	. Items 25.00/25.00% (S\$)	1,358.23	319.28
				Total Parts (S\$)	4,414.67	1,157.82

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

Particulars	Lab.Type	Repairer's	Amount
our Items			
TO KNOCKING & PULL OUT REAR PORTION & RENEW ABOVE PARTS	New	800.00	500.00
TO PUTTY & SPRAY UP PAINT WORKS	New	800.00	600.00
TO CHECK WIRING	New	50.00	30.00
TO REMOVE REVERSE SENSOR	New	100.00	50.00
TO REMOVE UPHOLSTERY	New	150.00	40.00
TO SPRAY TUFF COAT	New	150.00	50.00
TO TRANSFER BOOTLID FITTINGS	New	150.00	0.00
Gross L	abour Cost (S\$)	2,200.00	1,270.00
	TO KNOCKING & PULL OUT REAR PORTION & RENEW ABOVE PARTS TO PUTTY & SPRAY UP PAINT WORKS TO CHECK WIRING TO REMOVE REVERSE SENSOR TO REMOVE UPHOLSTERY TO SPRAY TUFF COAT TO TRANSFER BOOTLID FITTINGS	TO KNOCKING & PULL OUT REAR PORTION & RENEW ABOVE PARTS TO PUTTY & SPRAY UP PAINT WORKS TO CHECK WIRING TO REMOVE REVERSE SENSOR New TO REMOVE UPHOLSTERY New TO SPRAY TUFF COAT New	DOUR Items TO KNOCKING & PULL OUT REAR PORTION & RENEW ABOVE PARTS New 800.00 TO PUTTY & SPRAY UP PAINT WORKS New 800.00 TO CHECK WIRING New 50.00 TO REMOVE REVERSE SENSOR New 100.00 TO REMOVE UPHOLSTERY New 150.00 TO SPRAY TUFF COAT New 150.00 TO TRANSFER BOOTLID FITTINGS New 150.00

< END OF ESTIMATES >

Report was unsubmitted during this print-out.