



Case Details

Case Reference Number :

TAX/07/22/2017

Type of Repair : Accident Repair

Vehicle Registration Number :

SHD6234L

Company Type : Strides Taxi Pte Ltd

Estimation ID : EST-18762-ID

Assigned By : Taxi Claims Manager
Team

Insurance Company Name : China Taiping Insurance (Singapore) Pte Ltd

Accident Date and Time : 06/07/2022 02:30 PM

Vehicle Age(In Months) : -

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 0

Estimation Details

Spare Part's Cost Detail

BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	SMRT Recommendation				Repair/ Replace	Surveyor Quantity	Surveyor Approval		Remark	
						List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)			Surveyor Final Price(\$)	Repair/Replace		
Standard	Main			BUMPER REAR	1	458.60	458.60	25.00	343.95	Replace	1	343.9	Replace	✓	see
Standard	Main			BUMPER CLIPS	10	2.10	21.00	25.00	15.75	Replace	10	15.75	Replace	✓	see
Standard	Main			BUMPER REINFORCEMENT REAR	1	205.70	205.70	25.00	154.27	Replace	0	0	Check	✓	?
Standard	Main			ARM SUB-ASSY. RR BUMPER RH	1	139.60	139.60	25.00	104.70	Replace	0	0	Check	✓	?
Standard	Main			ARM SUB-ASSY. RR BUMPER LH	1	139.60	139.60	25.00	104.70	Replace	0	0	Check	✓	?
Standard	Main			ANTENNA,ELECTRICAL LOWER REAR	1	157.40	157.40	10.00	141.66	Replace	0	0	Not Give	✓	X an
Standard	Main			SENSOR REVERSE	1	180.00	180.00	0.00	180.00	Replace	0	0	Check	✓	?
Standard	Main			BUMPER SIDE RETAINER RR/LH	1	94.80	94.80	25.00	71.10	Replace	0	0	Not Give	✓	X
Standard	Main			BUMPER SIDE RETAINER RR/RH	1	94.80	94.80	25.00	71.10	Replace	0	0	Not Give	✓	X
Standard	Main			BUMPER SEAL, RR LH	1	88.90	88.90	25.00	66.68	Replace	0	0	Not Give	✓	X
Standard	Main			BUMPER LIP COVER RR/LH	1	72.20	72.20	25.00	54.15	Replace	0	0	Not Give	✓	X
Standard	Main			BUMPER LIP REAR	1	228.90	228.90	25.00	171.68	Replace	0	0	Not Give	✓	X
Standard	Main			END PANEL	1	602.10	602.10	25.00	451.58	Replace	0	0	Not Give	✓	X
Total Spare Part Cost									1,931.32	Surveyor Total		359.70			
Lump Sum Discount (%)									20.00	Lump Sum Dis (%)		20			
Final Spare Part Cost									1,183.79	Final Sur Total		287.76			

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR REAR PORTION	676.00	200	
Total			676.00	200.00	

Spray Cost Detail



S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY REAR BUMPER	378.00	200	
2	Main	TO RESPRAY REAR PANEL	180.00	0	X
3	Main	TO RESPRAY BUMPER BEAM	180.00	0	X
Total			738.00	200.00	<i>Sum</i>

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO WASH AND VACUUM	60.00	0	X
2	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0	X
3	Main	TO CHECK WIRING AND SYSTEM FUNCTION	120.00	0	X
4	Main	TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER(NET)	296.88	296.88	
5	Main	TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	40	
6	Main	TO REPLACE SUNDRY PARTS	100.00	0	X
Total:			796.88	336.88	<i>NN</i>

Summary

	Estimator Assessment(\$)	Surveyor Assessment(\$)
Total Spare Part Detail	1,183.79	287.76
Total Labour Cost	676.00	200.00
Total Spray Painting	738.00	200.00
Other	796.88	336.88
Overall Total	3,394.67	1,024.64

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Lump Sum Repair Option		<input checked="" type="checkbox"/>
Lump Sum Total	3,400.00	1,000.00
Surveyor Approved Amount		1,000.00
No of Repair Days*	5	3
Remarks		LUMP SUM REPAIR / AFTER PAINT PHOTO / FOR CHECK ITEM AND REPLACE ITEM PLEASE CALL SURVEYOR quodiang (LKK) & Email
Surveyor Name		GuoQiang
Signature		
Survey Date	08/07/2022	<input type="button" value="Save"/> <input type="button" value="Clear"/>

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before after spray painting
- To do photo and video during resurvey
- To get approval from insurance confirmation
- To estimate on "Without Prejudice" basis
- To get approval from insurance
- To get approval from insurance surveyed **and** with the approval from insurance Company

Acknowledged by repairer
 Signature:
 Date: