

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/GRB22005470/GCY3E2-1

Date: 15/08/2022

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0000447_01

Claimant Vehicle No : SLB3503T **Insured Vehicle No :** SMJ4061R

Date of Loss: 04/06/2022 Nature of Claim: TP Claim No: MFL2022D0002944

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLB3503T**
Make & Model: TOYOTA AXIO, 1.5 (A) Engine No: 2NR8499790
Reg. Date: 04/04/2016 (Man. Year: 2015) Chassis No: NRE1610009630
Colour: White Odometer: 294595 km
Engine Capacity: 1496 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/60 R15 Rear Tyre Size: 185/60 R15
Front Left Side: Arivo 6 mm Rear Left Side: Arivo 6 mm
Front Right Side: Arivo 6 mm Rear Right Side: Arivo 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,903.22	3,455.00	2,448.22	41.47
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,540.00	2,340.00	1,200.00	33.90
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,443.22	5,795.00	3,648.22	38.63
Approved Total (Overridden) (S\$)		4,600.00		
Nett Amount (S\$)	9,443.22	4,600.00	4,843.22	51.29

INSPECTION

Date of Assignment: 08/07/2022

Date Inspected: 08/06/2022 Inspected At:

Estimated Period of Repair: 7.0 days

Neo Automotive Pte Ltd (HQ)
53 UBI AVE 1, #05-44 PAYA UBI INDUSTRIAL
PARK
Singapore 408934

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 15 Aug 2022)
Parts:	143	TOYOTA AXIO 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLB3503T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOT LID	Repair	909.50 FL	*- FL
2	1		*BOOT EMBLEM (LOGO)	Necessary	50.90 FL	*50.90 FL
3	1		*BOOT EMBLEM (COROLLA)	Necessary	40.90 FL	*40.90 FL
4	1		*BOOT EMBLEM (AXIO)	Necessary	45.60 FL	*45.60 FL
5	1		*BOOT INNER TRIM	Serviceable	173.90 FL	*- FL
6	11		*BOOT INNER TRIM CLIP	Serviceable	35.20 FL	*- FL
7	1		*BOOT LOCK	Serviceable	99.80 FL	*- FL
8	1		*BOOT WEATHERSTRIP	Torn / Necessary	194.70 FL	*194.70 FL
9	1		*TAILLAMP RH	Broken	568.30 FL	*452.00 FL
10	1		*TAILLAMP PANEL RH	Dented	116.50 FL	*116.50 FL
11	1		*RR BUMPER	Dented / Cracked	502.30 FL	*502.30 FL
12	6		*RR BUMPER CLIP	Necessary	19.20 FL	*19.20 FL
13	1		*RR BUMPER RETAINER R/L	O/S Broken / N/S Not Necessary	200.80 FL	*100.40 FL
14	1		*RR BUMPER REFLECTOR RH	Broken	46.30 FL	*46.30 FL
15	1		*RR BUMPER SIDE SEAL RH	Serviceable	61.00 FL	*- FL
16	1		*RR END PANEL	Dented	696.30 FL	*696.30 FL
17	1		*RR END PANEL GARNISH	Cracked / Deformed	230.60 FL	*230.60 FL
18	1		*RR COMPARTMENT TRIM	Cut / Torn	403.70 FL	*403.70 FL
19	1		*RR FLOOR PANEL	Repair	698.70 FL	*- FL
20	1		*RR FLOOR PANEL SIDE EXT RH	Dented / Distorted	140.40 FL	*140.40 FL
21	1		*RR WINDSCREEN MOULDING	Necessary	102.00 FL	*102.00 FL
22	1		*RR FENDER PANEL RH	Dented / Buckled	1,036.40 FL	*974.30 FL
23	1		*RR FENDER INNER PANEL RH	Repair	256.80 FL	*- FL
24	1		*RR WHEEL HOUSE RH	Repair	390.60 FL	*- FL
25	1		*RR FENDER INNER TRIM RH	Torn / Deformed	329.70 FL	*329.70 FL
26	6		*RR FENDER INNER TRIM CLIP RH	Necessary	19.20 FL	*19.20 FL
27	1		*RR FENDER AIR VENT RH	Dented / Cracked	35.00 FL	*35.00 FL
28	1		*RR FENDER LH (NPA)	Repair	0.00 FL	*- FL
29	1		*RR FENDER INNER PANEL RH (NPA)	Repair	0.00 FL	*- FL
30	1		*RR WHEEL HOUSE RH (NPA)	Repair	0.00 FL	*- FL
31	1		*RR FLOOR PANEL (NPA)	Repair	0.00 FL	*- FL
32	1		*RR CHASSIS MEMBER RH (NPA)	Repair	0.00 FL	*- FL
33	1		*EXHAUST SILENCER (NPA)	Repair	0.00 FL	*- FL
34	1		*RR WINDSCREEN SEALANT	Necessary	50.00 FS	*40.00 FS
35	1		*RR FENDER PANEL SEALANT RH	Serviceable	50.00 FS	*- FS
36	1		*RR REVERSE SENSOR	Serviceable	200.00 FS	*- FS
37	1		*RR END PANEL SEALANT	Necessary	50.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	7,754.30	4,580.00
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,851.08	1,125.00
Total Parts (\$\$)	5,903.22	3,455.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REINSTALL ELECTRICAL WIRING SYSTEM FOR NECESSARY REPAIRS. TO CHECK REAR ELECTRICAL WIRING SYSTEM	New	60.00	30.00
2	TO REMOVE AND REINSTALL REAR WINDSCREEN FOR NECESSARY REPAIRS	New	120.00	120.00
3	TO STRAIGHTEN, REPAIR AND REALIGN REAR EXHAUST SILENCER	New	60.00	60.00
4	TO TRANSFER BOOT COMPONENT PARTS TO NEW BOOT	New	100.00	0.00
5	TO REMOVE AND REINSTALL REAR INTERIOR TRIMS, GARNISHES, SEATS, ETC. FOR NECESSARY REPAIRS	New	120.00	60.00
6	TO REMOVE, REPLACE AND REINSTALL REAR REVERSE SENSORS & CONTROL UNIT	New	50.00	40.00
7	TO SPRAY ANTI-RUST COATING ON NEW AND AFFECTED PANELS	New	30.00	30.00
8	TO STRAIGHTEN, REPAIR, REALIGN ON AFFECTED AREA AND REPLACE DAMAGED PARTS	New	1,500.00	1,000.00
9	TO SPRAY PAINTING, BLENDING ON AFFECTED AND ADJACENT AREA	New	1,500.00	1,000.00
Gross Labour Cost (\$\$)			3,540.00	2,340.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >