PROMINENT APPRAISER SERVICES PTE LTD Qualified Loss Adjusters And Motor Appraisers

Correspondence Mail Address: My Mail Box 886259 Singapore 919191 Mobile: 9295 2204 Fax: 6722 8508 Email: pasvcs@hotmail.com

Business Reg. 201404434D

VEHICLE INSPECTION REPORT

Report No.: PAS/TP/0080622 Date of Report : 01/07/2022

To: M/s. Prestige Leasing Pte Ltd Date of Assignment : 08/06/2022

C/o. 53, Ubi Ave 1, #05-44 Report requested by : M/s. Prestige Leasing Pte Ltd

Paya Ubi Industrial Park
Singapore 408934
Date of Accident : 04/06/2022
: 08/06/2022

Claim No. : Third Party Claim
Policy No. : -

PARTICULARS OF DAMAGED VEHICLE

Vehicle Registration No. : SLB3503T Engine Capacity (cc) : 1496

Make & Model: Toyota Corolla Axio 1.5XMileage (km): 294594kmDate of Registration: 04/04/2016Chassis / Frame No.: NRE1610009630

Colour : Pearl White Engine No. : 2NR8499790

TYRE CONDITION

Front LH : 5 mm Front RH : 5 mm

Make : Premio Make : Premio

Rear LH : 5 mm Rear RH : 5 mm Make : Premio Make : Premio

Road wheels Type: Alloy

(The above represents the approximate remaining life of tyre treads)

PRE-ACCIDENT CONDITION OF DAMAGED VEHICLE (Static tests only)

General Bodywork : Good
Paintwork : Good
Handbrake : Serviceable
Footbrake : Serviceable
Steering : Serviceable

Apparent Engine Modification : Nil

PLACE OF REPAIRER OFFICE/WORKSHOP

Location : M/s. Neo Automotive Pte Ltd

53, Ubi Ave 1, #05-44, Paya Ubi Industrial Park, Singapore 408934

ASSESSMENT

Revised Amount: \$9,443.23 Revised Amount: \$7,668.38

Less Excess : \$

Recommended Reserve : \$ 6,130.00 (Lump Sum)

Estimated Normal Period of Repairs : 10 Working Days

<u>Disclaimer:</u> The information contained in this report is intended for exclusive use of the addresses (including any attachments) solely in relation to the loss occurrence in which the assessed vehicle involved. It is confidential and may protected by legal privileged. No liability or responsibility whatsoever shall be held by PROMINENT APPRAISER SERVICES PTE LTD for any reliance on this report by any third party. If you are not the intended recipient, please contact us immediately to arrange for its return and you should not disseminate, distribute, copy any information contained herein or use of this communication is strictly prohibited.

PAS

Correspondence Mail Address: My Mail Box 886259 Singapore 919191 Mobile: 9295 2204 Fax: 6722 8508 Email: pasvcs@hotmail.com

Business Reg. 201404434D

Vehicle No: SLB3503T

Report No.: PAS/TP/0080622

GENERAL REMARKS

WITHOUT PREJUDICE

THE ASSIGNMENT

The survey was conducted at M/s. Neo Automotive Pte Ltd, 53, Ubi Ave 1, #05-44, Paya Ubi Industrial Park, Singapore 408934.

(Subsequent inspections have been conducted)

POINT OF IMPACT

At the RHR portion.

DAMAGES

The boot lid, rear bumper, rear end panel, rear floor panels, rear chassis members, rear fenders, RHR fender inner panel, RHR wheel house, RH taillamp, exhaust silencer, etc.

Other parts were also found damaged. (See schedule for details)

ADJUSTMENT / RECOMMENDATION

We have inspected thoroughly each and every item on the repairer's estimate against the actual damaged found on the vehicle. We list the breakdown of our findings and our recommendation as per schedule attached.

Our adjusted amount for the cost of repairs is SGD \$7,668.38.

CONCLUSION

The repairer has agreed to undertake the repairs at a lump sum of SGD \$6,130.00.

This inspection was conducted entirely on a 'Without Prejudice' basis. We have not given an authorization and/or instruction to the repairer to proceed with the repairs.

We hereby reverting the matter to you for your discretion on repairs.

Assuring you of our best services always.

Yours Truly,

Prominent Appraiser Services Pte Ltd

Andrew How

Automobile Appraiser

MSAAA

Licensed Appraiser



PROMINENT APPRAISER SERVICES PTE LTD
Qualified Loss Adjusters And Motor Appraisers
Correspondence Mail Address: My Mail Box 886259 Singapore 919191.
Mobile: 9295 2204 Fax: 6722 8508 Email: pasvcs@hotmail.com

Business Reg. 201404434D

Vehicle No: SLB3503T

Report No.: PAS/TP/0080622

APPRAISEMENT SCHEDULE

S/No.	Qty	Parts Descriptions	Condition			414/4/4/20	pairer's imate (S\$)		Our nent (S\$)
1	1 pc	Boot lid	Dented/Distorted			\$	909.50	\$	909.50
2		Boot emblem (Logo)	Necessary			\$	50.90	\$	50.90
3		Boot emblem (Corolla)	Necessary			\$	40.90	\$	40.90
4	1 pc	Boot emblem (Axio)	Necessary			\$	45.60	\$	45.60
5	*	Boot inner trim	Refit			\$	173.90	\$	-
6		Boot inner trim clip	Necessary	\$	3.20	\$	35.20	\$	35.20
7		Boot lock	Serviceable			\$	99.80	\$	
8		Boot weatherstrip	Torn/Necessary			\$	194.70	\$	194.70
9	1 pc	Taillamp RH	Broken			\$	568.30	\$	568.30
10	1 pc	Taillamp panel RH	Dented			\$	116.50	\$	116.50
11	1 pc	Rr bumper	Dented/Cracked			\$	502.30	\$	502.30
12		Rr bumper clip	Necessary	\$	3.20	\$	19.20	\$	19.20
13	-	Rr bumper retainer R/L	Broken/Cracked	\$	100.40	\$	200.80	\$	200.80
14	-	Rr bumper reflector RH	Broken			\$	46.30	\$	46.30
15	1 pc	Rr bumper side seal RH	Torn			\$	61.00	\$	61.00
16	1 pc	Rr end panel	Dented			\$	696.30	\$	696.30
17	1 pc	Rr end panel garnish	Cracked/Deformed			\$	230.60	\$	230.60
18	1 pc	Rr compartment trim	Cut/Torn			\$	403.70	\$	403.70
19	1 pc	Rr floor panel	Dented/Repair			\$	698.70	\$	-
20	1 pc	Rr floor panel side ext RH	Dented/Distorted			\$	140.40	\$	140.40
21	-	Rr windscreen moulding	Necessary			\$	102.00	\$	102.00
22		Rr fender panel RH	Dented/Buckled			\$	1,036.40	\$	1,036.40
23	-	Rr fender inner panel RH	Dented/Repair			\$	256.80	\$	-
24	-	Rr wheel house RH	Dented/Repair			\$	390.60	\$	_
25		Rr fender inner trim RH	Torn/Deformed			\$	329.70	\$	329.70
26	-	Rr fender inner trim clip RH	Necessary	\$	3.20	\$	19.20	\$	19.20
27	_	Rr fender air vent RH	Dented/Cracked	-		\$	35.00	\$	35.00
28		Rr fender LH	Dented/Repair			54.5			. 5, 7 & 8)
29		Rr fender inner panel RH	Dented/Repair						5, 7 & 8)
30		Rr wheel house RH	Dented/Repair						. 5, 7 & 8)
31	1 pc	Rr floor panel	Dented/Repair						5, 7 & 8)
32	1 pc	Rr chassis member RH	Dented/Repair						. 5, 7 & 8)
33		Exhaust silencer	Bent/Repair				(oour no. 3)
			1				7.404.20		
				Laga	Discount: 25%	\$	7,404.30	\$ 25% \$	5,784.50
			**				1,851.08		1,446.13
			List	t Parts Si	ıb-Total :	\$	5,553.23	\$	4,338.38
1	1 pc	Rr windscreen sealant	Necessary		S/N	\$	50.00	\$	40.00
2	1 pc	Rr fender panel sealant RH	Necessary		S/N	\$	50.00	\$	40.00
3	1 pc	Rr reverse sensor	Dented/Damaged		S/N	\$	200.00	\$	200.00
4	1 pc	Rr end panel sealant	Necessary		S/N	\$	50.00	\$	40.00
			Specia	ıl Nett Sı	ıb-Total :	\$	350.00	\$	320.00
				Par	ts Total :	\$	5,903.23	\$	4,658.38



Business Reg. 201404434D

ele No : SLB3503T	Report No. : PAS/TP/0080622				
Labour Descriptions	Repairer's Estimate (S\$)		Our Assessment (S\$)		
To remove and reinstall electrical wiring system for necessary repairs. To check rear electrical wiring system.	\$	60.00	\$	50.00	
To remove and reinstall rear windscreen for necessary repairs.	\$	120.00	\$	120.00	
To straighten, repair and realign rear exhaust silencer.	\$	60.00	\$	60.00	
To transfer boot component parts to new boot.	\$	100.00	\$	80.00	
To remove and reinstall rear interior trims, garnishes, seats, etc. for necessary repairs.	\$	120.00	\$	100.00	
To remove, replace and reinstall rear reverse sensors & control unit.	\$	50.00	\$	50.00	
To straighten, repair, realign on affected area and replace damaged parts.	\$	1,500.00	\$	1,320.00	
To spray painting, blending on affected and adjacent area.	\$	1,500.00	\$	1,200.00	
To spray anti-rust coating on new and affected panels.	\$	30.00	\$	30.00	
Labour Total:	\$	3,540.00	\$	3,010.00	
Total (Parts & Labour) :	\$	9,443.23	-\$	7,668.38	
	To remove and reinstall electrical wiring system for necessary repairs. To check rear electrical wiring system. To remove and reinstall rear windscreen for necessary repairs. To straighten, repair and realign rear exhaust silencer. To transfer boot component parts to new boot. To remove and reinstall rear interior trims, garnishes, seats, etc. for necessary repairs. To remove, replace and reinstall rear reverse sensors & control unit. To straighten, repair, realign on affected area and replace damaged parts. To spray painting, blending on affected and adjacent area. To spray anti-rust coating on new and affected panels. Labour Total:	To remove and reinstall electrical wiring system for necessary repairs. To check rear electrical wiring system. To remove and reinstall rear windscreen for necessary repairs. To straighten, repair and realign rear exhaust silencer. To transfer boot component parts to new boot. To remove and reinstall rear interior trims, garnishes, seats, etc. for necessary repairs. To remove, replace and reinstall rear reverse sensors & control unit. To straighten, repair, realign on affected area and replace damaged parts. To spray painting, blending on affected and adjacent area. Shabour Total:	To remove and reinstall electrical wiring system for necessary repairs. To check rear electrical wiring system. To remove and reinstall rear windscreen for necessary repairs. To straighten, repair and realign rear exhaust silencer. \$ 60.00 To straighten, repair and realign rear exhaust silencer. \$ 120.00 To remove and reinstall rear interior trims, garnishes, seats, etc. for necessary repairs. \$ 120.00 To remove, replace and reinstall rear reverse sensors & control unit. \$ 50.00 To straighten, repair, realign on affected area and replace damaged parts. \$ 1,500.00 To spray painting, blending on affected and adjacent area. \$ 1,500.00 To spray anti-rust coating on new and affected panels. \$ 30.00 Labour Total: \$ 3,540.00	Labour Descriptions Repairer's Estimate (S\$) Assessing To remove and reinstall electrical wiring system for necessary repairs. To check rear electrical wiring system. To remove and reinstall rear windscreen for necessary repairs. To straighten, repair and realign rear exhaust silencer. To transfer boot component parts to new boot. To remove and reinstall rear interior trims, garnishes, seats, etc. for necessary repairs. To remove, replace and reinstall rear reverse sensors & control unit. To straighten, repair, realign on affected area and replace damaged parts. To spray painting, blending on affected and adjacent area. Solution 1,500.00 Labour Total: \$ 30.00 \$ 1.500.00 \$ 2.500.00 \$ 3.500.	

For Lump Sum Repairs

The final adjusted Lump Sum contract amount is \$

Under normal circumstances, the repairs should be completed within a reasonable period 10 Working Days. (Exclude waiting days of PRI, Sunday, Pubic Holiday and awaiting of shipment for spare parts)

60 Photographs were taken at the time of inspection.

N.B: By accepting to carry out the repairs on a contract Lump Sum basis, the repairer shall has the prerogative and discretion to replace the damaged parts with new, used, OEM or reconditioned parts and/or to repair the vehicle on a roadworthy condition to the entire satisfaction of owner.