

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22006587/UQY3M4**Date:** 29/07/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00096582200

Claimant Vehicle No : SNF8886K **Insured Vehicle No :** SLF7782G

Date of Loss: 09/07/2022 Nature of Claim: TP Claim No: SNM22D204818/C02/LEEPG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SNF8886K**

Make & Model: MINI COOPER S, 1.6 HB HID SR ABS TC 2WD (A) Engine No: A990I825

Reg. Date: 27/12/2010 (Man. Year: 2010) Chassis No: WMWSV32070TY82269

Colour: Black/White Odometer: 144070 km

Engine Capacity: 1598 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/45 R17 Rear Tyre Size: 215/45 R17

Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,267.91	2,685.70	3,582.21	57.15
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,530.00	1,350.00	2,180.00	61.76
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,797.91	4,035.70	5,762.21	58.81
Approved Total (Overridden) (S\$)		3,200.00		
Nett Amount (S\$)	9,797.91	3,200.00	6,597.91	67.34

INSPECTION

Date of Assignment: 12/07/2022

Date Inspected: 13/07/2022 Inspected At: Zoom Autowerks Pte Ltd (HQ)
15 Kaki Bukit Road 4, #01-53
Singapore 417808

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 29 Jul 2022)

Parts: M1-COUPE MINI COOPER S 1.6 HB HID SR ABS TC 2WD (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SNF8886K)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Repair	1,150.00 FL	*- FL
2	1		*FRONT BONNET LOGO	Not Necessary	90.00 FL	*- FL
3	1		*FRONT FENDER -RH	Dented	535.00 FL	*535.00 FL
4	1		*FRONT FENDER INNER SHIELD	Torn	165.00 FL	*165.00 FL
5	1		*FRONT FENDER WHEEL ARCH GARNISH	Distorted	220.00 FL	*220.00 FL
6	1		*FRONT WHEEL HUB	Bent	245.00 FL	*245.00 FL
7	1		*FRONT WHEEL BEARING	Necessary	225.00 FL	*225.00 FL
8	1		*FRONT SHOCK ABSORBER	Bent	385.00 FL	*385.00 FL
9	1		*FRONT KNUCKLE ARM	Bent	498.00 FL	*498.00 FL
10	1		*FRONT LOWER ARM	Not Necessary	431.00 FL	*- FL
11	1		*FRONT DOOR	Repair	930.90 FL	*- FL
12	1		*FRONT DOOR RUBBER	Not Necessary	145.00 FL	*- FL
13	1		*FRONT TYRE	Serviceable	500.00 FS	*- FS
14	1		*FRONT WHEEL RIM	Warped/Bent	1,200.00 FS	*600.00 FS
15	1		*SET FRONT FENDER INNER SHIELD CLIP	Necessary	50.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,769.90	2,913.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	501.99	227.30
Total Parts (\$\$)	6,267.91	2,685.70

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING AND RESET HEADLAMPS FOCUSING	New	80.00	20.00
2	TO REMOVE AND REFIT FRONT UNDERCARRIAGE	New	250.00	120.00
3	TO CONDUCT WHEEL ALIGNMENT	New	150.00	80.00
4	TO APPLY UNDERCOATING	New	150.00	30.00
5	PANEL BEATING	New	1,500.00	500.00
6	TO RE-SPRAY PAINTING ON THE AFFECTED AREAS	New	1,400.00	600.00
Gross Labour Cost (\$)			3,530.00	1,350.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >