

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/EG122006590/EQY3Q2**Date:** 12/09/2022REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : XD7917D**Insured Vehicle No :** YL5831B

Date of Loss: 07/07/2022

Nature of Claim:

TP

Claim No: CDMCG22001350

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **XD7917D**

Make & Model: HINO FS1ETLA-KAS, 12.9 D (M)

Engine No: E13CWL10198

Reg. Date: 29/10/2013 (Man. Year: 2013)

Chassis No: FS1ETL10051

Colour: White

Odometer: 135817 km

Engine Capacity: 12913 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 295/80 R22.5

Rear Tyre Size:

295/80 R22.5

Front Left Side: Dunlop 4 mm

Rear Left Side:

Dunlop 4 mm

Front Right Side: Dunlop 4 mm

Rear Right Side:

Dunlop 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,463.90	3,860.00	6,603.90	63.11
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,890.00	1,490.00	1,400.00	48.44
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,353.90	5,350.00	8,003.90	59.94
Approved Total (Overridden) (S\$)		4,300.00		
(S\$)	13,353.90	4,300.00	9,053.90	67.80
+ GST 7.00/7.00% (S\$)	934.77	301.00	633.77	67.80
Nett Amount (S\$)	14,288.67	4,601.00	9,687.67	67.80

INSPECTION

Date of Assignment: 12/07/2022

Date Inspected: 14/07/2022 Inspected At:

Ryder Auto Pte Ltd (HQ)

2 Kaki Bukit Ave 2, #02-19 AutoHub @ Kaki Bukit

Singapore 417921

Estimated Period of Repair: 5.0 days

Adjuster: CHEN TSUE YEE**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 12 Sep 2022)	
Parts:	N/A	HINO FS1ETLA-KAS 12.9 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for XD7917D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*REAR O/S & N/S TAIL LAMP BRACKET	Bent (1 PCS ONLY)	160.40 FL	*120.00 FL
2	2		*REAR O/S & N/S TAIL LAMP	Broken (1 PCS ONLY)	920.40 FL	*280.00 FL
3	2		*REAR REG NO.PLATE LAMP	Not Necessary	240.20 FL	*- FL
4	2		*REAR O/S & N/S TAIL LAMP REFLECTOR (WHITE)	Broken (1 PCS ONLY)	300.00 FS	*150.00 FS
5	1		*REAR REG NO PLATE	Bent	45.00 FS	*40.00 FS
6	1		*REAR REG NO PLATE BRACKET	Bent	100.00 FS	*50.00 FS
7	1		*REAR TAIL GATE (CHENGAL)	Broken	2,800.00 FS	*1,400.00 FS
8	5		*REAR TAIL GATE HINGES	Bent	300.00 FS	*200.00 FS
9	1		*REAR LTA GUARD	Dented	2,200.00 FS	*800.00 FS
10	2		*REAR LTA GUARD BRACKET	Not Necessary	300.00 FS	*- FS
11	1		*REAR LTA GUARD REFLECTIVE STICKER	Necessary	100.00 FS	*50.00 FS
12	1		*REAR GUARD STEP	Broken	600.00 FS	*350.00 FS
13	2		*REAR TAIL GATE 60 KMPH EMBLEM	Necessary	30.00 FS	*20.00 FS
14	1		*REAR BECAREFUL OF SWINGING STICKER	Necessary	50.00 FS	*40.00 FS
15	1		*REAR REVERSE CAMERA	Not Necessary	500.00 FS	*- FS
16	1		*REAR END PANEL	Not Necessary	1,500.00 FS	*- FS
17	1		*REAR END PANEL REFLECTIVE STICKER	Necessary	100.00 FS	*50.00 FS
18	1		*BLINKING LIGHT (RH)	Broken	350.00 FS	*350.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	10,596.00	3,900.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	132.10	40.00
Total Parts (\$\$)	10,463.90	3,860.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPAIR REAR PORTION ,STRAIGHTEN ,WELDING REAR DAMAGE PARTS & REALIGN REAR CARRIDGE	New	1,600.00	900.00
2	TO PAINT REAR PORTION	New	800.00	500.00
3	TO REMOVE AND REPLACE REAR REVERSE CAMERA	New	50.00	30.00
4	TO CHECK FOR FAULT CODE AND RESTTING	New	280.00	30.00
5	TO CHECK WIRING	New	100.00	0.00
6	TO RESEAL ANTI RUST	New	60.00	30.00
Gross Labour Cost (\$)			2,890.00	1,490.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >