

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT	
STRIDES AUTOMOTIVE SERVICES PTE LTD Ref: CS3/SMR2	22006592/Eqy3e2
60 WOODLANDS INDUSTRIAL PARK Date: 14/07/2022 E4SINGAPORE 757705	2
Code: SMR	
1. Policy Particulars :- (THIRD PARTY CLAIM)	
Insured Veh. SHB 1137C Veh. Inspected FBQ 7711	Y
Policy No. Coverage (\$) 0.00	
Claim No. TAX/06/22/2063 Excess (\$) 0.00	
Assign From Ashlene Lee Assign Date 12/07/2022	2
2. Vehicle Particulars & Condition	
Make & Model HONDA FS150F c.c 149	
Engine No. HIDDEN Year of Reg. 2019	
Chassis No.PMKKC27A0KB212603ColourORANGE	
Odometer 67048 KM Steering IN ORDER	R
Brakes IN ORDER Modification SPORTS F	RIM
General GOOD	
3. Conditions of Tyres	
Size Make Balance	
R/H Front Tyre 70/80-19 DUNLOP 4 mm	
L/H Front Tyre mm	
R/H Rear Tyre 80/90-19 DUNLOP 4 mm	
L/H Rear Tyre mm	
4. Description of Damages	
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION, O/S AND N/S BODY.	
5. General Information	
Accident Date 23/06/2022 Inspect Date / Time 12/07/2022	2 (02:34 PM)
Survey held at RIGHT CLICK AUTOWORKS PTE LTD	
7 SOON LEE STREET, #01-27, ISPACE, SINGAPORE 627608	
5a. Remarks	
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000-\$4,000	
5b. Estimate Days of Repair	
ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days	

Report Ref No. CS3/SMR22006592/Eqy3e2

Inspected By

CHEN TSUE YEE

K.K.LAU CPT(RET)

Automotive Assessor

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser