

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI22006595/KQY3Q2**Date:** 30/08/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00068292204		
Claimant Vehicle No :	GBF7561X	Insured Vehicle No :	GBD1200M		
Date of Loss:	08/07/2022	Nature of Claim:	TP	Claim No:	SNM22D204790/C02/TANCHC

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>GBF7561X</b>	Engine No:	1KD2665588
Make & Model:	TOYOTA HIACE, 3.0 D DX (A)	Chassis No:	KDH2010210454
Reg. Date:	02/03/2017 (Man. Year: 2016)	Odometer:	194935 km
Colour:	Metallic Silver		
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	195 R15X8	Rear Tyre Size:	195 R15X8
Front Left Side:	Michelin 4 mm	Rear Left Side:	Michelin 4 mm
Front Right Side:	Michelin 4 mm	Rear Right Side:	Michelin 4 mm

*The above values represent the remaining tyre tread depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	6,779.39	4,821.51	1,957.88	28.88
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,340.00	2,030.00	310.00	13.25
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>9,119.39</b>	<b>6,851.51</b>	<b>2,267.88</b>	<b>24.87</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>5,450.00</b>		
<b>(\$\$)</b>	9,119.39	5,450.00	3,669.39	40.24
<b>+ GST 7.00/7.00% (\$\$)</b>	638.36	381.50	256.86	40.24
<b>Nett Amount (\$\$)</b>	<b>9,757.75</b>	<b>5,831.50</b>	<b>3,926.25</b>	<b>40.24</b>

**INSPECTION**

Date of Assignment:	13/07/2022	
Date Inspected:	13/07/2022	Inspected At: E M Solution Pte Ltd (HQ) 160 Sin Ming Drive,, #03-18, Sin Ming Autocity Singapore 575722
Estimated Period of Repair:	7.0 days	

**Adjuster:** KENNETH KONG**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 30 Aug 2022)
Parts:	213	TOYOTA HIACE 3.0 D DX (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBF7561X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT DOOR LH	Bent	1,999.70 FL	*1,710.00 FL
2	1		*FRT DOOR WING MIRROR LH	Dented / Cut	1,272.70 FL	*845.10 FL
3	1		*FRT DOOR OUTER HANDLE	Serviceable	199.30 FL	*- FL
4	1		*FRT DOOR LOCK LH	Repair	613.30 FL	*- FL
5	1		*FRT DOOR WEATHERSTRIP	Serviceable	244.20 FL	*- FL
6	1		*SLIDING DOOR LH	Bent	2,080.20 FL	*1,822.00 FL
7	1		*CENTRE PILLAR LH	Bent	377.85 FL	*377.85 FL
8	1		*PETROL TANK PANEL	Repair	78.20 FL	*- FL
9	1		*REAR BODY PANEL LH	Bent	1,640.40 FL	*1,640.40 FL
10	1		*FRT DOOR COS STICKER	Necessary	50.00 FS	*25.00 FS
11	1		*REAR ROAD RIM LH	Serviceable	350.00 FS	*- FS
						F=Franchise part. S=SpcNett. L=ListItemDisc.
					Sub Total (\$\$)	8,905.85 6,420.35
					- List Item Discount on L Items 25.00/25.00% (\$\$)	2,126.46 1,598.84
					Total Parts (\$\$)	6,779.39 4,821.51

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE & REARRANGE ELECTRICAL WIRINGS ,CHECK LIGHTINGS	New	80.00	20.00
2	TO REMOVE ,TRANSFER FRONT DOOR COMPONENTS	New	80.00	60.00
3	TO REMOVE,TRANSFER SLIDING DOOR COMPONENT	New	80.00	60.00
4	TO REMOVE,REPAIR & REPLACE DAMAGED BODYPARTS AND WHERE CONSISTENT TO THE ACCIDENT	New	1,000.00	1,000.00
5	PUTTY AND RESPRAY PAINTING ON AFFECTED PORTIONS	New	1,000.00	800.00
6	RUST PROOFING ON AFFECTED PORTIONS	New	100.00	90.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,340.00</b>	<b>2,030.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >