



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLT 4447X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	FRONT HEADLAMP - O/S	NOT NECESSARY	653.50	-
1	FRONT BUMPER	CUT / TORN	858.60	633.00
1	FRONT BUMPER LOGO	NOT NECESSARY	75.00	-
1	FRONT BUMPER SIDE RETAINER	NECESSARY	32.80	32.80
1	FRONT FENDER - O/S	DENTED / BENT	522.50	419.00
1	FRONT FENDER INNER GARNISH O/S	TORN	41.00	41.00
1	FRONT FENDER INNER SHIELD O/S	TORN	106.90	106.90
1	FRONT FENDER LAMP O/S	CRACKED	68.00	68.00
1	FRONT WHEEL HUB O/S	DAMAGED	160.00	160.00
1	FRONT WHEEL BEARING O/S	DAMAGED	115.00	115.00
1	FRONT SHOCK ABSORBER O/S	NOT NECESSARY	282.00	-
1	FRONT KNUCKLE ARM O/S	WARPED	325.00	325.00
1	FRONT KNUCKLE ARM BEARING O/S	REPEATED	182.00	-
1	FRONT LOWER ARM O/S	NOT NECESSARY	295.00	-
1	STABILIZER BAR LINK O/S	NOT NECESSARY	95.00	-
1	FRONT TIE ROD O/S	NOT NECESSARY	115.00	-
1	FRONT DRIVE SHAFT O/S	NOT NECESSARY	1,025.00	-
1	FRONT DOOR - O/S	DENTED / BENT	955.00	955.00
1	SET FRONT DOOR STICKER O/S	NECESSARY	68.50	68.50
2	FRONT DOOR HINGES O/S	NOT NECESSARY	111.20	-
1	FRONT DOOR LOCK O/S	NOT NECESSARY	207.00	-
1	FRONT DOOR WEATHERSTRIP O/S	NOT NECESSARY	190.00	-
1	FRONT DOOR SIDE MIRROR O/S	NOT NECESSARY	490.00	-
	LESS 10% DISCOUNT		-697.40	-292.42
			6,276.60	2,631.78
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	SET FRONT BUMPER CLIP (SN)	NECESSARY	60.00	40.00
1	SET FRONT FENDER INNER SHIELD CLIP (SN)	NECESSARY	45.00	40.00
1	FRONT TYRE (SN)	SERVICEABLE	400.00	-
1	FRONT WHEEL RIM - RH (SN)	WARPED	850.00	400.00

Report Ref No. CS/SMR22006596/Uqy3m4



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT DOOR BLACK TAPE (SN)	REPEATED	120.00	-
			1,475.00	480.00
	<u>LABOUR</u>			
	TO CHECK WIRING AND RESET HEADLAMPS FOCUSING.		80.00	20.00
	TO REMOVE AND REFIT FRONT UNDERCARRIAGE.		300.00	120.00
	TO CONDUCT WHEEL ALIGNMENT.		180.00	60.00
	TO REMOVE, REFIT DOOR FITTINGS AND REPLACE DAMAGED PARTS, TRANSFER ALL FITTINGS TO NEW DOOR.		200.00	60.00
	TO APPLY UNDERCOATING.		180.00	60.00
	PANEL BEATING.		1,600.00	520.00
	TO RE-SPRAY PAINTING ON THE AFFECTED AREAS.		1,500.00	800.00
		4,040.00	1,640.00	
GRAND TOTAL			11,791.60	4,751.78
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,800.00

Report Ref No. CS/SMR22006596/Uqy3m4

CHUA KANG SENG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.