

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/EGI22006603/UCY3E2

**Date:** 10/08/2022

### REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd. Policy No: DMFG21009443  
Claimant Vehicle No: GBF1783L Insured Vehicle No: YN6066B  
Date of Loss: 08/07/2022 Nature of Claim: TP Claim No: CDMFG22001353

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBF1783L**  
Make & Model: TOYOTA HIACE, 3.0 TURBO 4DR AT (A) Engine No: 1KD2629060  
Reg. Date: 26/07/2016 (Man. Year: 2016) Chassis No: JTFHT02PX00200301  
Colour: Black/White Odometer: 99732 km  
Engine Capacity: 2982 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 195 R15 Rear Tyre Size: 195 R15  
Front Left Side: Austone 6 mm Rear Left Side: Austone 6 mm  
Front Right Side: Austone 6 mm Rear Right Side: Austone 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	16,320.50	8,055.12	8,265.38	50.64
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,780.00	3,110.00	670.00	17.72
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>20,100.50</b>	<b>11,165.12</b>	<b>8,935.38</b>	<b>44.45</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>8,900.00</b>		
<b>(S\$)</b>	20,100.50	8,900.00	11,200.50	55.72
<b>+ GST 7.00/7.00% (S\$)</b>	1,407.04	623.00	784.04	55.72
<b>Nett Amount (S\$)</b>	<b>21,507.54</b>	<b>9,523.00</b>	<b>11,984.54</b>	<b>55.72</b>

### INSPECTION

Date of Assignment: 12/07/2022  
Date Inspected: 13/07/2022 Inspected At: Liu's Brother Auto Engineering Workshop (HQ)  
KAKI BUKIT  
Singapore 417883  
Estimated Period of Repair: 8.0 days

**Adjuster:** MARCUS CHUA

**Manager:** CELINE FONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

## Reference

<b>Part Source:</b>	(Last Synchronised: 10 Aug 2022)	
<b>Parts:</b>	N/A	TOYOTA HIACE 3.0 TURBO 4DR AT (A) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for GBF1783L)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Badly Dented	2,051.60 F	*2,051.60 FL
2	1		*REAR TAILGATE LOCK	Dented / Jammed	394.90 F	*394.90 FL
3	1		*REAR TAILGATE WEATHERSTRIP	Twisted	426.70 F	*426.70 FL
4	1		*REAR TAILGATE OUTER GARNISH	Cracked	397.00 F	*397.00 FL
5	1		*REAR TAILGATE OUTER GARNISH ACCESSORIES	Warped	400.00 FS	*380.00 FS
6	1		*REAR TAILGATE INNER ALUMINIUM BOARD	Bent	450.00 FS	*400.00 FS
7	1		*SET REAR TAILGATE INNER ALUMINIUM BOARD CLIPS	Necessary	65.00 FS	*45.00 FS
8	1		*REAR TAILGATE TOYOTA MOTIF	Necessary	70.50 F	*70.50 FL
9	1		*REAR TAILGATE 70KM/H STICKER	Necessary	15.00 FS	*10.00 FS
10	1		*REAR TAILGATE 8 PAX STICKER	Necessary	15.00 FS	*10.00 FS
11	1		*REAR NUMBER PLATE METAL	Bent	35.00 FS	*20.00 FS
12	1		*REAR TAILGATE WINDSCREEN GLASS	Shattered	1,311.30 F	*1,211.10 FL
13	1		*REAR TAILGATE WINDSCREEN GLASS MOULDING	No such part	219.00 F	*- FL
14	1		*REAR TAILGATE WINDSCREEN GLASS SEALANT	Necessary	50.00 FS	*40.00 FS
15	1		*REAR TAIL LAMP	N/S Broken	772.80 F	*386.40 FL
16	1		*SET REAR TAIL LAMP OUTER ACCESSORIES	Not Necessary	168.00 FS	*- FS
17	1		*REAR BUMPER ACCESSORIES	Distorted	1,250.00 FS	*1,000.00 FS
18	1		*SET BUMPER CLIPS	Necessary	65.00 FS	*50.00 FS
19	1		*REAR CORNER PANEL LH	Repair	165.80 F	*- FL
20	1		*REAR BRACKET LH	Cracked	31.50 F	*31.50 FL
21	1		*REAR FENDER (BODY PANEL) LH	Repair	1,718.50 F	*- FL
22	1		*REAR END PANEL OUTER	Badly Dented	566.10 F	*566.10 FL
23	1		*REAR END PANEL INNER	Badly Dented	936.20 F	*845.10 FL
24	1		*REAR END PANEL SEALANT	Necessary	50.00 FS	*50.00 FS
25	1		*REAR TOP WOODEN PLYWOOD BOARD	Not Necessary	450.00 FS	*- FS
26	1		*FRONT BONNET	Repair	1,050.00 FS	*- FS
27	1		*FRONT BUMPER	Deformed / Torn	796.80 F	*796.80 FL
28	1		*SET FRONT BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS
29	1		*FRONT BUMPER GRILLE	Torn	155.80 F	*155.80 FL
30	1		*FRONT GRILLE SPORT	Cracked	680.00 FS	*500.00 FS
31	1		*SET FRONT GRILLE CLIP	Not Necessary	30.00 FS	*- FS
32	1		*FRONT AIRCON CONDENSER	Serviceable	1,448.00 F	*- FL
33	1		*FRONT NUMBER PLATE METAL	Not fitted	35.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>16,320.50</b>	<b>9,888.50</b>
<b>- List Item Discount on L Items 0.00/25.00% (\$)</b>	0.00	1,833.38
<b>Total Parts (\$)</b>	<b>16,320.50</b>	<b>8,055.12</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO CHECK ALL WIRING & ELECTRICAL COMPONENT FOR PROPER FUNCTION	New	80.00	30.00
2	TO REMOVE & REFIX AIR CON, RE-FILL AIR CON GAS & TEST FOR LEAKAGES	New	300.00	100.00
3	REMOVE AND REFIX REAR TAILGATE COMPONENTS & WIPER MECHANISM	New	80.00	80.00
4	REMOVE & REINSTALL TAILGATE GLASS TO FACILITATE REPAIRS	New	120.00	120.00
5	LABOR FOR PANEL BEATING, CUT, WELD, STRAIGHTEN & REPLACING PARTS ETCS	New	1,500.00	1,300.00
6	TO PUTTY & SPRAY PAINTING & INCLUDING TOUCH UP PAINT ON ACCIDENT AFFECTED AREAS	New	1,600.00	1,400.00
7	TO APPLY RUST PROOFING, RESEAL TUFF-COATING TREATMENT ON ACCIDENT AREA	New	100.00	80.00
			<b>Gross Labour Cost (S\$)</b>	<b>3,780.00</b>
				<b>3,110.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >